

# Vision Autowork Pte.Ltd.

( ROC / GST Reg. No. 201500371E)

8 Kaki Bukit Ave 4, #08-09 Premier@Kaki Bukit

Singapore 415875

Tel : 6341 6789 Fax: 6341 6778

E-mail:visionautowork@gmail.com

DATE : 22.10.20

TO : AXA MOTOR CLAIMS DEPTS  
VEHICLE NO : SJR8162A  
MODEL : TOYOTA COROLLA ALTIS  
DATE OF ACCIDENT : 21.10.20  
TIME OF ACCIDENT : 18:30HRS

WE APPEND HEREUNDER THE ESTIMATED COST OF REPAIRS TO BE CARRIED OUT TO THE ABOVE VEHICLE.

## CLAIM DETAIL : PARTS

| S/N | DESCRIPTION                                     | QTY | UNIT LIST PRICE | TOTAL LIST PRICE |
|-----|-------------------------------------------------|-----|-----------------|------------------|
| 1   | FRONT BUMPER <i>Dented</i>                      | 1   | \$ 490.00       | \$ 490.00        |
| 2   | FRONT BUMPER LOWER GRILLE <i>Not in</i>         | 1   | \$ 140.00       | \$ 140.00        |
| 3   | FRONT BUMPER LOGO <i>Not in</i>                 | 1   | \$ 85.00        | \$ 85.00         |
| 4   | FRONT BUMPER FOG LAMP <i>3 each</i>             | 2   | \$ 300.00       | \$ 600.00        |
| 5   | FRONT BUMPER FOG LAMP COVER <i>Not in</i>       | 2   | \$ 85.00        | \$ 170.00        |
| 6   | FRONT BUMPER TOP RUBBER <i>Not in</i>           | 1   | \$ 75.00        | \$ 75.00         |
| 7   | FRONT BUMPER BOTTOM COVER GARNISH <i>Not in</i> | 1   | \$ 100.00       | \$ 100.00        |
| 8   | FRONT BUMPER SIDE RETAINER <i>Not in</i>        | 2   | \$ 75.00        | \$ 150.00        |
| 9   | FRONT BUMPER REINFORCEMENT <i>Best</i>          | 1   | \$ 380.00       | \$ 380.00        |
| 10  | FRONT RADIATOR GRILLE <i>Cracked</i>            | 1   | \$ 360.00       | \$ 360.00        |
| 11  | HEADLAMP <i>Cracked</i>                         | 2   | \$ 780.00       | \$ 1,560.00      |
| 12  | HEAD LAMP LOWER BRACKET <i>Not in</i>           | 2   | \$ 95.00        | \$ 190.00        |
| 13  | FRONT FENDER <i>LH Buckled</i>                  | 2   | \$ 650.00       | \$ 1,300.00      |
| 14  | FRONT FENDER EMBLEM 'VVTI' <i>Not in</i>        | 2   | \$ 65.00        | \$ 130.00        |
| 15  | FRONT FENDER INNER COWLING <i>Not in</i>        | 2   | \$ 170.00       | \$ 340.00        |
| 16  | FRONT WHEEL HOUSE SUPPORT PANEL <i>Plays</i>    | 2   | \$ 580.00       | \$ 1,160.00      |
| 17  | FRONT WIPER SIDE GARNISH <i>Not in</i>          | 2   | \$ 42.00        | \$ 84.00         |
| 18  | BONNET <i>Dented</i>                            | 1   | \$ 880.00       | \$ 880.00        |
| 19  | BONNET HINGE <i>Not in</i>                      | 2   | \$ 80.00        | \$ 160.00        |
| 20  | BONNET INSULATOR <i>Not in</i>                  | 1   | \$ 290.00       | \$ 290.00        |
| 21  | BONNET STOPPER <i>Not in</i>                    | 2   | \$ 20.00        | \$ 40.00         |
| 22  | BONNET LOCK <i>Damaged</i>                      | 1   | \$ 110.00       | \$ 110.00        |
| 23  | BONNET LOCK BRACE PANEL <i>Best</i>             | 1   | \$ 118.00       | \$ 118.00        |
| 24  | BONNET WEATHERSTRIP <i>Not in</i>               | 1   | \$ 80.00        | \$ 80.00         |
| 25  | FRONT SUPPORT PANEL <i>Buckled</i>              | 1   | \$ 750.00       | \$ 750.00        |
| 26  | HORN <i>Not in</i>                              | 1   | \$ 130.00       | \$ 130.00        |
| 27  | AIR CONDENSOR <i>Dented</i>                     | 1   | \$ 1,510.00     | \$ 1,510.00      |
| 28  | AIR CON PIPE <i>Not in</i>                      | 1   | \$ 325.00       | \$ 325.00        |

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJR8162A  
 MODEL : TOYOTA COROLLA ALTIS  
 DATE OF ACCIDENT : 21.10.20  
 TIME OF ACCIDENT : 18:30HRS

|    |                                                       |   |             |             |     |
|----|-------------------------------------------------------|---|-------------|-------------|-----|
| 29 | AIR CONDENSOR SUPPORT PANEL (TOP) <i>Cracked</i>      | 1 | \$ 111.00   | \$ 111.00   | ✓   |
| 30 | AIR CONDENSOR SUPPORT PANEL (BOTTOM) <i>new</i>       | 1 | \$ 111.00   | \$ 111.00   | +   |
| 31 | RADIATOR <i>Dented</i>                                | 1 | \$ 2,030.00 | \$ 2,030.00 | +   |
| 32 | RADIATOR TOP BRACKET <i>new</i>                       | 2 | \$ 29.00    | \$ 58.00    | +   |
| 33 | RADIATOR MOUNTING <i>new</i>                          | 4 | \$ 25.00    | \$ 100.00   | +   |
| 34 | RADIATOR FAN COWLING <i>Cracked</i>                   | 1 | \$ 280.00   | \$ 280.00   | ✓   |
| 35 | RADIATOR FAN MOTOR <i>new</i>                         | 1 | \$ 260.00   | \$ 260.00   | +   |
| 36 | RADIATOR HOSE <i>new</i>                              | 2 | \$ 58.00    | \$ 116.00   | +   |
| 37 | RADIATOR TOP HOSE JOINT (T) <i>new</i>                | 1 | \$ 69.00    | \$ 69.00    | +   |
| 38 | RADIATOR LOWER HOSE <i>2 new</i>                      | 1 | \$ 68.00    | \$ 68.00    | +   |
| 39 | RADIATOR OIL PIPE <i>2 new</i>                        | 2 | \$ 150.00   | \$ 300.00   | +   |
| 40 | RADIATOR OIL PIPE JOINT HOSE                          | 2 | \$ 120.00   | \$ 240.00   | +   |
| 41 | AIR DUCT <i>new</i>                                   | 1 | \$ 115.00   | \$ 115.00   | +   |
| 42 | FRONT AIR DUCT (FLEXIBLE PIPE) <i>2 new</i>           | 1 | \$ 120.00   | \$ 120.00   | +   |
| 43 | AIR DUCT (JOINT AIR CLEANER) <i>new</i>               | 1 | \$ 320.00   | \$ 320.00   | +   |
| 44 | AIR CLEANER (HOUSING&COVER) <i>new</i>                | 1 | \$ 960.00   | \$ 960.00   | +   |
| 45 | FUSE BOX <i>new</i>                                   | 1 | \$ 498.00   | \$ 498.00   | +   |
| 46 | BATTERY BRACKET <i>Best</i>                           | 1 | \$ 60.00    | \$ 60.00    | ✓   |
| 47 | BATTERY TRAY <i>new</i>                               | 1 | \$ 90.00    | \$ 90.00    | +   |
| 48 | FRONT AIR TANK (RESORATOR) <i>new</i>                 | 1 | \$ 198.00   | \$ 198.00   | +   |
| 49 | TEMPERATURE SENSOR <i>new</i>                         | 1 | \$ 119.00   | \$ 119.00   | +   |
| 50 | REAR BUMPER <i>Distorted</i>                          | 1 | \$ 520.00   | \$ 520.00   | ✓   |
| 51 | REAR BUMPER REFLECTOR <i>Missing</i>                  | 2 | \$ 60.00    | \$ 120.00   | ✓   |
| 52 | REAR BUMPER RETAINER (FRONT) <i>new</i>               | 2 | \$ 90.00    | \$ 180.00   | +   |
| 53 | REAR BUMPER SIDE RETAINER (BACK) <i>new</i>           | 2 | \$ 50.00    | \$ 100.00   | ✓   |
| 54 | REAR BUMPER BRACKET <i>LH Missing</i>                 | 2 | \$ 80.00    | \$ 160.00   | 80  |
| 55 | REAR BUMPER SPONGE <i>Missing</i>                     | 1 | \$ 160.00   | \$ 160.00   | ✓   |
| 56 | REAR BUMPER PROTECTOR BAR <i>Missing</i>              | 1 | \$ 400.00   | \$ 400.00   | ✓   |
| 57 | REAR FENDER LH <i>Buckled</i>                         | 1 | \$ 980.00   | \$ 980.00   | ✓   |
| 58 | REAR FENDER INNER PANEL LH <i>Repair</i>              | 1 | \$ 585.00   | \$ 585.00   | +   |
| 59 | REAR FENDER INNER COWLING <i>new</i>                  | 2 | \$ 65.00    | \$ 130.00   | +   |
| 60 | REAR FENDER INNER TRIM <i>LH Cracked</i>              | 2 | \$ 390.00   | \$ 780.00   | 390 |
| 61 | REAR FENDER AIR VENT LH <i>new</i>                    | 1 | \$ 148.00   | \$ 148.00   | +   |
| 62 | REAR WHEEL HOUSE PANEL LH <i>Repair</i>               | 1 | \$ 894.00   | \$ 894.00   | +   |
| 63 | REAR WHEEL HOUSE UPPER SUPPORT PANEL LH <i>Repair</i> | 1 | \$ 543.00   | \$ 543.00   | +   |
| 64 | REAR FUEL TANK <i>new</i>                             | 1 | \$ 1,063.00 | \$ 1,063.00 | +   |
| 65 | REAR FUEL TANK INLET PIPE <i>new</i>                  | 1 | \$ 395.00   | \$ 395.00   | +   |
| 66 | REAR FUEL TANK INLET PIPE CAP <i>new</i>              | 1 | \$ 105.00   | \$ 105.00   | +   |

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJR8162A  
 MODEL : TOYOTA COROLLA ALTIS  
 DATE OF ACCIDENT : 21.10.20  
 TIME OF ACCIDENT : 18:30HRS

|     |                                       |   |             |             |
|-----|---------------------------------------|---|-------------|-------------|
| 67  | REAR FUEL TANK INLET PIPE COVER PANEL | 1 | \$ 117.00   | \$ 117.00   |
| 68  | REAR WINDSCREEN MOULDING              | 1 | \$ 110.00   | \$ 110.00   |
| 69  | REAR DOOR LH                          | 1 | \$ 1,250.00 | \$ 1,250.00 |
| 70  | REAR DOOR PROTECTOR LH                | 1 | \$ 104.00   | \$ 104.00   |
| 71  | REAR DOOR BLACK STICKER LH            | 1 | \$ 78.00    | \$ 78.00    |
| 72  | REAR DOOR OUTER STRIP LH              | 1 | \$ 150.00   | \$ 150.00   |
| 73  | REAR DOOR WEATHERSTRIP LH             | 1 | \$ 180.00   | \$ 180.00   |
| 74  | REAR DOOR INNER LOCK LH               | 1 | \$ 480.00   | \$ 480.00   |
| 75  | REAR DOOR CATCHER LH                  | 1 | \$ 60.00    | \$ 60.00    |
| 76  | REAR DOOR INNER TRIM LH               | 1 | \$ 89.00    | \$ 89.00    |
| 77  | TAILLAMP                              | 2 | \$ 430.00   | \$ 860.00   |
| 78  | TAILLAMP PANEL                        | 2 | \$ 198.00   | \$ 396.00   |
| 79  | TAILLAMP LOWER BARCKET                | 2 | \$ 58.00    | \$ 116.00   |
| 80  | BOOTLID                               | 1 | \$ 680.00   | \$ 680.00   |
| 81  | BOOTLID LAMP                          | 2 | \$ 226.00   | \$ 452.00   |
| 82  | BOOTLID LAMP COVER GARNISH (INNER)    | 2 | \$ 40.00    | \$ 80.00    |
| 83  | BOOTLID MOULDING CHROME               | 1 | \$ 250.00   | \$ 250.00   |
| 84  | BOOTLID LOGO                          | 1 | \$ 85.00    | \$ 85.00    |
| 85  | BOOTLID STOPPER                       | 4 | \$ 18.00    | \$ 72.00    |
| 86  | BOOT LID HINGE                        | 2 | \$ 90.00    | \$ 180.00   |
| 87  | BOOTLID INSULATOR                     | 1 | \$ 210.00   | \$ 210.00   |
| 88  | BOOTLID TOP LOCK                      | 1 | \$ 125.00   | \$ 125.00   |
| 89  | BOOTLID LOWER LOCK                    | 1 | \$ 20.00    | \$ 20.00    |
| 90  | BOOTLID WEATHERSTRIP                  | 1 | \$ 210.00   | \$ 210.00   |
| 91  | REAR END PANEL                        | 1 | \$ 610.00   | \$ 610.00   |
| 92  | REAR END PANEL TOP GARNISH            | 1 | \$ 230.00   | \$ 230.00   |
| 93  | REAR FLOOR PANEL                      | 1 | \$ 790.00   | \$ 790.00   |
| 94  | REAR FLOOR BOTTOM CROSS MEMBER        | 1 | \$ 895.00   | \$ 895.00   |
| 95  | REAR FLOOR PANEL TOP BOARD            | 1 | \$ 319.00   | \$ 319.00   |
| 96  | REAR FLOOR SIDE PANEL LH              | 1 | \$ 240.00   | \$ 240.00   |
| 97  | REAR SPRE TYRE BOLT                   | 1 | \$ 50.00    | \$ 50.00    |
| 98  | REAR CHASSIS MEMBER LH                | 1 | \$ 998.00   | \$ 998.00   |
| 99  | CENTER EXHAUST C/W CONVERTER          | 1 | \$ 2,410.00 | \$ 2,410.00 |
| 100 | CENTER EXHAUST INSULATOR              | 1 | \$ 198.10   | \$ 198.10   |
| 101 | CENTER EXHAUST GASKET                 | 1 | \$ 60.00    | \$ 60.00    |
| 102 | REAR EXHAUST PIPE                     | 1 | \$ 881.70   | \$ 881.70   |
| 103 | REAR EXHAUST INSULATOR                | 1 | \$ 175.00   | \$ 175.00   |
| 104 | REAR EXHAUST GASKET                   | 1 | \$ 60.00    | \$ 60.00    |

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJR8162A  
 MODEL : TOYOTA COROLLA ALTIS  
 DATE OF ACCIDENT : 21.10.20  
 TIME OF ACCIDENT : 18:30HRS

|     |                                      |   |          |           |
|-----|--------------------------------------|---|----------|-----------|
| 105 | REAR EXHAUST MOUNTING <i>Not New</i> | 4 | \$ 45.00 | \$ 180.00 |
|-----|--------------------------------------|---|----------|-----------|

17421  
 13065-75

TOTAL PRICE \$ 39,643.80  
 LESS 25% \$ 9,910.95  
 SUB TOTAL PRICE \$ 29,732.85

| S/N | DESCRIPTION                                      | QTY | UNIT S/NETT | TOTAL S/NETT |
|-----|--------------------------------------------------|-----|-------------|--------------|
| 1   | FRONT NUMBER PLATE <i>Bent</i>                   | 1   | \$ 80.00    | \$ 80.00     |
| 2   | FRONT BUMPER CLIP (SET) <i>New</i>               | 1   | \$ 80.00    | \$ 80.00     |
| 3   | FRONT FENDER COWLING CLIPS (SET) <i>New</i>      | 1   | \$ 60.00    | \$ 60.00     |
| 4   | BONNET INSULATOR CLIP (SET) <i>New</i>           | 1   | \$ 80.00    | \$ 80.00     |
| 5   | FRONT SUPPORT PANEL SEALANT <i>New</i>           | 1   | \$ 150.00   | \$ 150.00    |
| 6   | BATTERY <i>Alt</i>                               | 1   | \$ 250.00   | \$ 250.00    |
| 7   | RADIATOR COOLANT <i>New</i>                      | 1   | \$ 80.00    | \$ 80.00     |
| 8   | REAR NUMBER PLATE <i>Bent</i>                    | 1   | \$ 80.00    | \$ 80.00     |
| 9   | REAR BUMPER CLIP (SET) <i>New</i>                | 1   | \$ 80.00    | \$ 80.00     |
| 10  | BOOT LID INSULATOR CLIP (SET) <i>New</i>         | 1   | \$ 80.00    | \$ 80.00     |
| 11  | TAILLAMP CLIPS (SET) <i>New</i>                  | 1   | \$ 40.00    | \$ 40.00     |
| 12  | TAILLAMP PANEL SEALANT <i>New</i>                | 2   | \$ 60.00    | \$ 120.00    |
| 13  | REAR FENDER LH SEALANT <i>New</i>                | 1   | \$ 150.00   | \$ 150.00    |
| 14  | REAR FENDER INNER PANEL SEALANT LH <i>New</i>    | 1   | \$ 120.00   | \$ 120.00    |
| 15  | REAR FENDER COWLING CLIP (SET) <i>New</i>        | 1   | \$ 80.00    | \$ 80.00     |
| 16  | REAR FENDER INNER TRIM CLIP (SET) <i>New</i>     | 1   | \$ 80.00    | \$ 80.00     |
| 17  | REAR WHEEL HOUSE PANEL SEALANT LH <i>New</i>     | 1   | \$ 120.00   | \$ 120.00    |
| 18  | REAR WINDSCREEN SEALANT <i>New</i>               | 1   | \$ 80.00    | \$ 80.00     |
| 19  | REAR WINDSCREEN INNER SEAL <i>New</i>            | 1   | \$ 60.00    | \$ 60.00     |
| 20  | REAR DOOR INNER TRIM CLIP LH (SET) <i>New</i>    | 1   | \$ 80.00    | \$ 80.00     |
| 21  | REAR END PANEL TOP GARNISH CLIP (SET) <i>New</i> | 1   | \$ 40.00    | \$ 40.00     |
| 22  | REAR END PANEL INSULATION SEAL <i>New</i>        | 1   | \$ 150.00   | \$ 150.00    |
| 23  | REAR FLOOR PANEL INSULATION SEAL <i>New</i>      | 1   | \$ 350.00   | \$ 350.00    |
| 24  | REAR FLOOR SIDE PANEL SEALANT LH <i>New</i>      | 1   | \$ 120.00   | \$ 120.00    |
| 25  | REAR WHEEL TYRE <i>Not New</i>                   | 1   | \$ 380.00   | \$ 380.00    |
| 26  | BREAKDOWN TRIANGLE SIGN <i>Not New</i>           | 1   | \$ 180.00   | \$ 180.00    |
| 27  | REVERSE SENSOR <i>Damaged</i>                    | 1   | \$ 220.00   | \$ 220.00    |
| 28  | REVERSE CAMERA <i>Not New</i>                    | 1   | \$ 580.00   | \$ 580.00    |

TOTAL \$ 3,970.00

870

TO : AXA MOTOR CLAIMS DEPTS  
 VEHICLE NO : SJR8162A  
 MODEL : TOYOTA COROLLA ALTIS  
 DATE OF ACCIDENT : 21.10.20  
 TIME OF ACCIDENT : 18:30HRS

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (FRONT)**

| S/N | JOB DESCRIPTION                                         | PRICE       | ADJUSTED COST |
|-----|---------------------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVING AND REPLACING PARTS             | \$ 1,800.00 | 1000          |
| 2   | SPRAY PAINTING TO AFFECTED AREA                         | \$ 1,800.00 | 1000          |
| 3   | WIRING CHECK                                            | \$ 180.00   | 30            |
| 4   | REMOVE AND REFIX AIRCON CONDENSOR AND REFILL AIRCON GAS | \$ 120.00   | 60            |
| 5   | REMOVE AND REFIX RADIATOR AND CONDUCT PRESSURE TEST     | \$ 80.00    | 60            |
| 6   | REFOCUS HEADLAMP BEAM                                   | \$ 60.00    | x             |

2150

**CLAIM DETAILS: LABOUR AND SPRAY PAINTING (REAR)**

| S/N | JOB DESCRIPTION                                                                | PRICE       | ADJUSTED COST |
|-----|--------------------------------------------------------------------------------|-------------|---------------|
| 1   | PANEL BEATING, REMOVAL AND REPLACING PARTS                                     | \$ 2,800.00 | 1600          |
| 2   | TO SPRAY PAINT AFFECTED AREA                                                   | \$ 2,000.00 | 1400          |
| 3   | TUFF COAT                                                                      | \$ 250.00   | 100           |
| 4   | REMOVE AND REFIX CUSHION SEAT/ UPHOLSTRY AND ROOF LINNING TO FACILITATE REPAIR | \$ 350.00   | 180           |
| 5   | REMOVE AND REFIX REVERSE SENSOR AND DISTANCE SETTING                           | \$ 80.00    | 50            |
| 6   | TRANSFER REAR DOOR MECHANISM                                                   | \$ 80.00    | x             |
| 7   | REAR CHASSIS ALIGNMENT                                                         | \$ 250.00   | x             |
| 8   | TRANSFER BOOTLID MECHANISM                                                     | \$ 60.00    | ✓             |
| 9   | CONDUCT WATER LEAKAGE TEST                                                     | \$ 180.00   | x             |
| 10  | REMOVE & REINSTALL REAR WINDSCREEN                                             | \$ 120.00   | ✓             |
| 11  | REMOVE AND REFIX FUEL TANK TO FACILITATE FENDER REPLACEMENT                    | \$ 80.00    | ✓             |
| 12  | REMOVE AND REFIX REAR EXHAUST PIPE                                             | \$ 180.00   | x             |

3590

**TOTAL**

**\$10,470.00**

TO : AXA MOTOR CLAIMS DEPTS  
VEHICLE NO : SJR8162A  
MODEL : TOYOTA COROLLA ALTIS  
DATE OF ACCIDENT : 21.10.20  
TIME OF ACCIDENT : 18:30HRS

---

TOTAL PARTS COST : \$ 33,702.85  
TOTAL LABOUR COST : \$ 10,470.00  
TOTAL REPAIR COST : \$ 44,172.85

NB: THIS IS ONLY AN ESTIMATE AND SHOULD ADDITIONAL WORK BE FOUND NECESSARY TO BE CARRIED OUT IN THE COURSE OF REPAIRS, EXTRA MATERIALS AND LABOUR COST WILL BE CHARGED ACCORDINGLY WHICH HOWEVER, YOU WILL BE INFORMED PRIOR TO ACTION TAKEN.  
PARTS PRICES ARE SUBJECT TO CHANGES.

YOURS FAITHFULLY,

**ABBY**

SERVICE ADVISOR  
ABBY  
HP : 9856 4815

Adrian Lj

L/S 23/10/20

16 Days.

Nett Value : \$14,810.

S.S.

Total: 19675.75

L/S: 14.810.

(Nett Value)

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: