

BIFROST AUTO PTE LTD

REPAIR ESTIMATE

DATE: 21-Oct-20

INSURANCE: III

MODEL: HYUNDAI I40

VEHICLE NO.: SHD 6570 R

DESCRIPTION	QTY	LIST PRICE	AMOUNT	
REAR BUMPER <i>st</i> 553.00	1	\$1,106.00	\$1,106.00	✓
REAR BUMPER CLIP <i>Hec</i>	1	\$19.00	\$19.00	✓
TAIL LAMP (LH) <i>broken</i>	1	\$697.80	\$697.80	✓
TAIL LAMP QUARTER PANEL (LH) <i>HH</i>	1	\$453.00	\$453.00	X
REAR PANEL LOWER <i>HH</i>	1	\$367.20	\$367.20	X
REAR PANEL GARNISH <i>HH</i>	1	\$57.70	\$57.70	X
SPARE WHEEL LOCK NUT <i>HH</i>	1	\$41.80	\$41.80	X
SPARE TYRE PANEL <i>HH</i>	1	\$852.80	\$852.80	X
SPARE TYRE PANEL CUSHION <i>HH</i>	1	\$223.10	\$223.10	X
REAR FENDER <i>Decker</i>	1	\$2,171.40	\$2,171.40	✓
REAR FENDER UNDER SHIELD(LH) <i>HH</i>	1	\$338.60	\$338.60	X
FUEL LID COVER LH <i>destroyed</i>	1	\$82.10	\$82.10	✓
FUEL LID GARNISH COVER <i>broken</i>	1	\$361.20	\$361.20	✓
REAR TRAY LUGGS SIDE (LH) <i>HH</i>	1	\$232.60	\$232.60	X
REAR FENDER AIR-DUCT (LH) <i>HH</i>	1	\$51.60	\$51.60	X
REAR FENDER TRIM BOARD (LH) <i>HH</i>	1	\$688.75	\$688.75	X
REAR WINDSCREEN MOULDING <i>Hec</i>	1	\$51.80	\$51.80	✓
REAR TYRE RIM (LH) <i>st</i> 325.30	1	\$650.60	\$650.60	✓
REAR TYRE WHEEL CAP <i>broken</i> 107.10	1	\$214.20	\$214.20	✓
REAR WHEEL BEARING ING & HUB <i>2 Den</i> 362.00	1	\$724.00	\$724.00	✓
REAR TRAILING ARM (LH) <i>2 destroyed</i> 192.00	1	\$384.00	\$384.00	✓
REAR ASSIST (LH) <i>2 destroyed</i> 145.70	1	\$219.40	\$219.40	✓
REAR SHOCK ABSORBER (LH) <i>2 destroyed</i> 276.30	1	\$683.70	\$683.70	✓
REAR SHOCK ABSORBER MOUNTING (LH) <i>HH</i>	1	\$162.60	\$162.60	X
ABS SENSOR <i>HH</i>	1	\$217.90	\$217.90	X
REAR CROSS MEMBER <i>HH 2 destroyed</i>	1	\$2,021.50	\$2,021.50	✓
STABILIZER BAR <i>HH</i>	1	\$199.60	\$199.60	X
STABILIZER LINK <i>HH</i>	1	\$85.90	\$85.90	X
REAR UPPER ARM (LH) <i>2 destroyed</i>	1	\$335.75	\$335.75	✓
REAR LOWER ARM (LH) <i>2 destroyed</i>	1	\$353.80	\$353.80	✓
REAR KNUCKLE ARM (LH) <i>2 destroyed</i>	1	\$545.60	\$545.60	✓
SUB TOTAL			\$14,595.00	
LESS 20%			\$2,919.00	
DISCOUNTED TOTAL			\$11,676.00	
REAR BUMPER ADVERTISEMENT LOGO <i>Hec</i> SN	1	\$50.00	\$50.00	✓
REAR FENDER ADVERTISEMENT LOGO (LH) <i>Hec</i> SN	1	\$100.00	\$100.00	✓
REAR WINDSCREEN SEALANT <i>Hec</i> SN	1	\$46.00	\$46.00	✓
REAR TYRE (LH) <i>HH</i> SN	1	\$216.00	\$216.00	X
SUB TOTAL			\$412.00	

Labour Charge				
Panel Beating	1	\$1,400.00	\$1,400.00	600/-
Spray Painting Charge	1	\$1,200.00	\$1,200.00	500/-
Wiring Charge	1	\$160.00	\$160.00	30/-
Tuff Kote	1	\$160.00	\$160.00	40/-
Towing Charge	1	\$80.00	\$80.00	40/-
Remove/Refix Cushion & Upholstery Rear	1	\$150.00	\$150.00	80/-
Remove/Refix Rear Windscreen Glass	1	\$120.00	\$120.00	80/-
Remove/Refix Undercarriage (RR)	1	\$400.00	\$400.00	150/-
Re-set Rear ABS System	1	\$400.00	\$400.00	40/-
Four Wheel Alignment	1	\$120.00	\$120.00	60/-
Diagnostic & Resetting To Erase Fault Code	1	\$550.00	\$550.00	150/-
TOTAL LABOUR			\$4,740.00	
ESTIMATE TOTAL			\$ 16,828.00	
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

22/10/20 e 1700hr
 Not Author
 2/3mm 6 days.
 Ryan
 LKK Auto



Provide BV before finalization.
 Check part prices.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: