

Date : 26-Oct-20

Registration no. : SGT2357U / Honda Civic IMA A

DOA : 22-Oct-20

Estmate No. : 19A007_SGT2357U_CIVIC IMA

S/N	Qty	Item	Amount
<u>LIST ITEMS</u>			
1	1	Rear bumper ✓ DD	825.20 638 ✓
2	2	Rear bumper side retainer @ \$68.50 ✓ BR	137.00 ✓
3	1	Bootlid ✓ DD	925.50 690 ✓
4	1	Bootlid logo ✓ NEC	98.00 78 ✓
5	1	Bootlid emblem CIVIC ✓ NEC	74.20 65 ✓
6	1	Bootlid emblem HYBRID ✓ NEC	103.00 68 ✓
7	2	Bootlid reflector @ \$372.80 × NN	745.60
8	1	Bootlid inner lock ✓ Jammed	297.60 194 ✓
9	1	Bootlid inner trim × NN	212.00
10	1set	Bootlid inner trim clips × NN	45.00
11		Bootlid weatherstrip ✓ TN	197.60 ✓
12	2	Taillamp @ \$458.00 × NN	916.00
13	2	Taillamp lower bracket @ \$69.60 × NN	139.20
14	1	Rear end panel ✓ DD	826.40 316 ✓
15	1	Rear end panel top garnish ✓ CRU	188.90 72 ✓
16	1	Spare tyre panel × Repair	1152.20
17	1	Spare tyre panel top board × NN	328.30
18	1	Exhaust pipe assy × NN	996.30
19	3	Exhaust mounting @ \$68.00 × NN	204.00
			8412.00
			2455.60
			-20%
Less 20%			1964.48
			1682.40
			6729.60

Date : 26-Oct-20

Registration no. : SGT2357U / Honda Civic IMA A

DOA : 22-Oct-20 Estimate No. : 19A007_SGT2357U_CIVIC IMA

S/N	Qty	Item	Amount
SPECIAL NETT ITEMS			
1	1	Sundries ✓ NEC	60.00 30
2	1set	Rear bumper clips ✓ NEC	80.00 30
3	2set	Bootlid reflector clips @ \$25.00 ✗ NN	50.00
4	2	Bootlid reflector seal @ \$25.00 ✗ NN	50.00
5	1	Bootlid sealant ✓ NEC	80.00 30
6	2set	Taillamp clips @ \$30.00 ✗ NN	60.00
7	2	Taillamp seal @ \$30.00 ✗ NN	60.00
8	1set	Rear end panel top garnish clips ✓ NEC	35.00 10
9	1	Rear end panel sealant ✓ NEC	80.00 30
10	1	Spare tyre panel sealant ✗ NN	80.00
11	1	Reverse sensor with module ✓ Shorted	300.00 200
Parts Total			935.00
			330
			7664.60
LABOUR & MISC CHARGES			
1	1	Panel beating and strengthen parts on accident area.	1800.00 800
2	1	Check wiring system after disconnect and connect.	80.00 30
3	1	R&R interior upholstery.	200.00 30
4	1	R&R bootlid component.	100.00 30
5	1	R&R exhaust pipe.	200.00 ✗
6	1	R&R reverse sensor and check	80.00 30
7	1	To apply undercoating for rust roofing.	200.00 30
8	1	Spray painting on accident area.	1200.00 800
Labour Total			3860.00
			1750
Total Parts and Labour Cost of Repair			11524.60

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Steve (LKK)
26/10/20
Without Prejudice
Lumpsum
Resurvey After Spray
5 repair days

P - 1964.48
N - 330
L - 1750
= 4044.48
L/S - 3235.58
= 3250