

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III20011484/T1BS3Q2

Date: 07/04/2021

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant		
Vehicle No : SLB5810T	Insured Vehicle No :	SHA6513Y
Date of Loss: 16/10/2020	Nature of Claim: TP	Claim No: MCT20100268

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLB5810T	Engine No:	L15Z12722508
Make & Model:	HONDA CITY, 1.5 SV CVT (A)	Chassis No:	MRHGM6660GP000552
Reg. Date:	14/04/2016 (Man. Year: 2016)	Odometer:	65604 km
Colour:	Maroon		
Engine Capacity:	1497 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55 R16	Rear Tyre Size:	185/55 R16
Front Left Side:	Yokohama 6 mm	Rear Left Side:	Yokohama 6 mm
Front Right Side:	Yokohama 6 mm	Rear Right Side:	Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	4,473.68	2,580.32	1,893.36	42.32
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,760.00	1,490.00	1,270.00	46.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	7,233.68	4,070.32	3,163.36	43.73
Approved Total (Overridden) (\$\$)		3,250.00		
(\$\$)	7,233.68	3,250.00	3,983.68	55.07
+ GST 7.00/7.00% (\$\$)	506.36	227.50	278.86	55.07
Nett Amount (\$\$)	7,740.04	3,477.50	4,262.54	55.07
+ Loss of Use (5.0 x S\$80.00/day) (\$\$)		400.00		
+ Doc/Search Fee (\$\$)		29.00		
Nett Liability (\$\$)		3,906.50		
Global Sum Settlement (\$\$)		3,700.00		

INSPECTION

Date of Assignment:	23/10/2020	
Date Inspected:	26/10/2020 Inspected At:	Em-1 Auto Pte Ltd (HQ)
		Blk 8 Sin Ming Industrial Estate Sector C, #01-68
		Singapore 575643
Estimated Period of Repair:	5.0 days	

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 23 Mar 2021)
Parts:	143	HONDA CITY 1.5 SV CVT (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLB5810T)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	492.70 FL	*492.70 FL
2	1		*FRONT BUMPER SIDE RETAINER	N/S Not Necessary/O/SNecessary	72.00 FL	*36.00 FL
3	1		*SET FRONT BUMPER CLIP	Necessary	50.00 FL	*30.00 FL
4	1		*HEADLAMP ASSY RH	Cracked	452.10 FL	*452.10 FL
5	1		*FRONT FENDER RH	Bent	392.20 FL	*392.20 FL
6	1		*FRONT FENDER INNER SHIELD	Deformed	92.60 FL	*92.60 FL
7	1		*SET FRONT FENDER INNER SHIELD CLIPS	Necessary	30.00 FL	*30.00 FL
8	1		*FRONT SHOCK ABSORBER RH	Bent	232.60 FL	*232.60 FL
9	1		*FRONT SHOCK ABSORBER TOP MOUNTING RH	Not Necessary	96.20 FL	*- FL
10	1		*FRONT LOWER ARM RH	Not Necessary	263.50 FL	*- FL
11	1		*FRONT KNUCKLE ARM RH	Bent	391.50 FL	*391.50 FL
12	1		*FRONT WHEEL BEARING RH	Bent	209.20 FL	*209.20 FL
13	1		*FRONT ANTI ROLL BAR LINK RH	Not Necessary	92.00 FL	*- FL
14	1		*FRONT DOOR RH	Repair	762.50 FL	*- FL
15	1		*FRONT DOOR WING MIRROR RH	Cracked	491.50 FL	*491.50 FL
16	2		*FRONT DOOR BLACK STICKER RH	Not Necessary	92.00 FL	*- FL
17	1		*FRONT DOOR WEATHERSTRIP RH	Not Necessary	129.50 FL	*- FL
18	1		*FRONT SPORT RIM RH	Cut	450.00 FS	*300.00 FS
19	1		*FRONT TYRE RH	Not Necessary	300.00 FS	*- FS
20	1		*SET DOOR SUN VISOR	Not Necessary	250.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$) **5,342.10** **3,150.40**
- List Item Discount on L Items 20.00/20.00% (\$\$) 868.42 570.08

Total Parts (\$\$) **4,473.68** **2,580.32**

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING	New	1,200.00	600.00
3	ANTI RUST	New	90.00	30.00
4	CHECK WIRING	New	40.00	30.00
5	REMOVE AND INSTALL FRONT DOORS PARTS	New	90.00	0.00
6	REMOVE AND INSTALL FRONT AND UNDERCARRIAGE	New	250.00	150.00
7	TO PERFORM COMPUTERIZE WHEEL ALIGNMENT	New	90.00	80.00
Gross Labour Cost (\$\$)			2,760.00	1,490.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >