

CITYCABS PTE LTD

REPAIR ESTIMATE*

VEHICLE NO SHC7006C

23.10.20

MAKE :

CHIANG/ CHINA

MODEL HYU- I40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
1	REAR BUMPER COVER / 00			\$1,106.00
2	REAR BUMPER BRACKET SIDE LH/RH X NN		\$35.60	\$71.20
10	REAR BUMPER CLIPS / APC X NN		\$2.20	\$22.00
1	REAR BUMPER REINFORCEMENT X NN			\$428.40
1	REAR BUMPER UNDER COVER X NN			\$228.00
				\$1,855.60
				\$371.12
				\$1,484.48
1	REVERSE SENSOR X NN			\$135.70
1	BUMPER RUBBER MAT X not fitted			\$50.00
				\$185.70
	Labour Charge		280	\$400.00
	Panel Beating		200	\$400.00
	Spray Painting Charge		30	\$60.00
	Remove/refix reverse sensor		X	\$90.00
	Tuff Kote			
				\$950.00
				\$2,620.18
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				

Steve (LKK)

W AL

23/10/20, 4.30pm

2 dyr

L/S

My AL smy

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

COMFORTDELGRO ENGINEERING

A member of COMFORTDELGRO

ComfortDelGro Engineering Pte Ltd

205 Braddell Road Singapore 579701

Mainline + 65 6383 6280 Facsimile + 65 6280 9755

Workshops

59 Loyang Drive Singapore 508969

383 Sin Ming Drive Singapore 575717

45 Pandan Road Singapore 60286

320 Pandan Road Singapore 602649

24 Senoko Loop Singapore 758156

7 Sungei Kadut Way Singapore 728791

501 Yishun Industrial Park A Singapore 7687

Date/Time: 23.10.2020 16:06

Page : 1

Team: ARC Repair TP(CFSO)1

JOB CARD Sales Order:

JC NO.: 305429545

USTOMER

IR/MS CITYCAB PTE LTD

USTOMER NO 7010070

DDRESS 383 SIN MING DRIVE

Singapore SINGAPORE 575717

EL. (R) 65551188

(O)

(P)

ISCOUNT CARD NO.

REGN NO. SHC7006C

MILEAGE

MAKE: HYUNDAI

FUEL

E.....1/2.....F

MODEL I-40

DATE/TIME IN 23.10.2020 14:15

YR OF MANU. 29.12.2015

TARGET DATE

CHASSIS CODE KMHLB41UMGU080804

COMPLETION DATE/TIME:

JOB DESCRIPTION


Accident Date: 22.10.2020

NATURE: 3P 22.10.2020

S/NO

LABOR CODE

DESCRIPTION



CHECKED & PASSED OUT BY:

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

nowledgement Slip

ie:
Jo.:
cle No.: SHC7006C CHIANG

Exit Pass

Vehicle No.: SHC7006C

ie of Service Advisor

Signature/Date

Name of Service Advisor

Date

e returned to Service Reception upon collection

To be kept by Security Guard