

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way, #09-16
Singapore 079120

Our File No: CC3/AIG20011487/ACD3E2

Date: 14/04/2021

REFERENCE

Insured/Claimant: LO XINSHENG(LUO XINSHENG) Policy No: 1900021467-01
Date of Loss: 17/10/2020 Nature of Claim: OD Claim No: 3933433214SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMJ2025J**
Make & Model: AUDI A3, 999cc SEDAN TFSI (A) Engine No: CHZC26271
Reg. Date: 25/02/2019 (Man. Year: 2018) Chassis No: WAUZZZ8V6K1016408
Colour: Grey Odometer: 34851 km
Engine Capacity: 999 cc
Market Value/New Car Price: S\$93,000.00
Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/40 R18 Rear Tyre Size: 225/40 R18
Front Left Side: ALTIMAX 6 mm Rear Left Side: ALTIMAX 6 mm
Front Right Side: ALTIMAX 6 mm Rear Right Side: ALTIMAX 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	17,954.00	7,554.32	10,399.68	57.92
Miscellaneous Items	0.00	0.00	0.00	
Labour	15,112.00	9,832.00	5,280.00	34.94
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	33,066.00	17,386.32	15,679.68	47.42
+ GST 7.00/7.00% (S\$)	2,314.62	1,217.04	1,097.58	47.42
Nett Amount (S\$)	35,380.62	18,603.36	16,777.26	47.42

INSPECTION

Date of Assignment: 22/10/2020
Date Inspected: 22/10/2020 Inspected At: Premium Automobiles Pte Ltd (UBI)
55 Ubi Road 1
Singapore 408699
Estimated Period of Repair: 12.0 days

Adjuster: ADRIAN LING

Manager: CELINE FONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Distorted	1,944.00 FS	*1,555.20 FS
2	1		*REAR BUMPER FIXING PARTS	Not Necessary	191.00 FS	*- FS
3	2		*WHEEL HOUSING LINER ADAPTER - LH / RH	Not Necessary	74.00 FS	*- FS
4	2		*REAR BUMPER GUIDE SECTION - LH / RH	Damaged	32.00 FS	*25.12 FS
5	2		*REAR BUMPER LOCKING MECHANISM	Damaged	59.00 FS	*46.72 FS
6	1		*REAR BUMPER SPOILER	Deformed	234.00 FS	*187.20 FS
7	2		*REAR LIGHT REFLECTOR - LH / RH	Not Necessary	82.00 FS	*- FS
8	2		*LED LICENCE PLATE LIGHT	Not Necessary	197.00 FS	*- FS
9	2		*LED TAIL LIGHT - LH / RH	Not Necessary	1,734.00 FS	*- FS
10	2		*TAIL LIGHT TRIM - LH / RH	Not Necessary	60.00 FS	*- FS
11	2		*LED TAIL LIGHT - LH / RH	Not Necessary	1,734.00 FS	*- FS
12	2		*TAIL LIGHT TRIM - LH / RH	Not Necessary	60.00 FS	*- FS
13	1		*REAR REINFORCEMENT BEAM	Bent	565.00 FS	*451.60 FS
14	1		*REAR BUMPER BRACKET - LH	Damaged	27.00 FS	*21.12 FS
15	1		*REAR BUMPER BRACKET - RH	Damaged	28.00 FS	*22.24 FS
16	2		*REAR BUMPER GUIDE SECTION - LH / RH	Not Necessary	132.00 FS	*- FS
17	1		*REAR PARKING AID SENSOR - INNER / OUTER (4PCS)	Damaged (1Pc Only)	968.00 FS	*386.00 FS
18	4		*REAR PARKING AID SEL RING	Necessary	14.00 FS	*10.88 FS
19	1		*SET REAR BUMPER WIRING	Not Necessary	510.00 FS	*- FS
20	1		*REAR LID	Dented	2,564.00 FS	*2,051.20 FS
21	1		*REAR LID ATTACHMENT PARTS	Not Necessary	291.00 FS	*- FS
22	2		*RAER LID HINGE - LH / RH	Not Necessary	506.00 FS	*- FS
23	1		*REAR LID FLAP GASKET	Damaged	203.00 FS	*162.00 FS
24	1		*REAR LID LOCK STRIKER	Not Necessary	49.00 FS	*- FS
25	1		*REAR LID LOCK	Not Necessary	184.00 FS	*- FS
26	1		*LID LOCK PUSH BUTTON	Not Necessary	172.00 FS	*- FS
27	1		*LID LOCK COVER	Not Necessary	16.00 FS	*- FS
28	1		*AUDI EMBLEM	Necessary	122.00 FS	*97.60 FS
29	1		*REAR CROSS PANEL	Distorted	356.00 FS	*284.40 FS
30	1		*CROSS PANEL REINFORCEMENT	Distorted	725.00 FS	*579.60 FS
31	1		*REAR CROSS PANEL TRIM	Deformed	153.00 FS	*122.40 FS
32	1		*LUGGAGE COMPARTMENT FLOOR COVERING	Deformed	536.00 FS	*428.40 FS
33	1		*REAR LID TRIM PANEL	Not Necessary	303.00 FS	*- FS
34	1		*REAR SILENCER HEAT SHIELD	Not Necessary	158.00 FS	*- FS
35	1		*REAR SILENCER	Not Necessary	712.00 FS	*- FS
36	1		*REAR SILENCER DUAL CLIP	Not Necessary	57.00 FS	*- FS
37	1		*FRONT SILENCER	Not Necessary	475.00 FS	*- FS
38	1		*FRONT SILENCER DUAL CLIP - INNER	Not Necessary	57.00 FS	*- FS
39	1		*FRONT SILENCER DUAL CLIP - OUTER	Not Necessary	57.00 FS	*- FS
40	2		*EXHAUST SYSTEM RETAINER	Not Necessary	79.00 FS	*- FS
41	1		*STONE CHIP	Necessary	180.00 FS	*180.00 FS
42	1		*CAVITY WAX	Necessary	140.00 FS	*140.00 FS
43	1		*ACRYLIC SEALANT	Necessary	180.00 FS	*180.00 FS
44	1		*REAR NO PLATE	Not Necessary	60.00 FS	*- FS
45	1		*SUNDRIES	Necessary	300.00 FS	*84.80 FS
46	1		*STOWAGE COMPARTMENT	Damaged	58.00 FS	*46.00 FS
47	1		*REAR LID LOCK COVER	Cut	8.00 FS	*6.32 FS
48	1		*KEYLESS CONTROL UNIT	Damaged	69.00 FS	*55.12 FS
49	1		*REAR LID HINGE - RH	Bent	253.00 FS	*202.40 FS
50	1		*CONNECTING PLATE - LH/RH	Bent	286.00 FS	*228.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$) 17,954.00 7,554.32

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	New	280.00	280.00
2	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT	New	480.00	480.00
3	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND BOTH REAR FENDERS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED	New	5,600.00	3,250.00
4	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING, BOTH REAR FENDERS AND SPARE WHEEL HOUSING	New	5,200.00	2,750.00
5	TO REMOVE AND RENEW REAR AND CENTRE EXHAUST SILENCER	New	480.00	0.00
6	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
7	TO REMOVE AND TRANSFER REAR LIDS CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS	New	280.00	280.00
8	TO CARRY OUT FIRST MEASUREMENT ON CAR O-LINER	New	800.00	800.00
9	TO PUT UP VEHICLE ON CAR O-LINER TO FACILITATE REPAIRING OF SPARE WHEEL HOUSING	New	1,800.00	1,800.00
Gross Labour Cost (\$\$)			15,112.00	9,832.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >