

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0785/2020/NS
DATE : 19-Oct-20
WIP : 53653

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

YOUR INSURED VEH NO : SMJ 2025 J

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR LO XINSHENG(LUO XINSHENG)
ADDRESS : 10 RAMBAI ROAD
SINGAPORE 424330
TELEPHONE : HP +65 97822176
TYPE OF CLAIM : ~~THIRD PARTY CLAIM~~ *OD claim,*
POLICY NO : 1900021467-01
VEHICLE NO : **SMJ 2025 J**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 25/2/2019
ENGINE NO : CHZ C26271
CHASSIS NO : WAUZZZ8V6K1016408
MILEAGE : 34753KM
DATE IN : 19-Oct-20
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 17-Oct-20
PLACE OF ACCIDENT : PIE TOWARDS TUAS BEFORE EXIT 15A

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 2025 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	✓ S/N \$ 280.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	✓ S/N \$ 280.00	✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 480.00	✓
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND BOTH REAR FENDERS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1500 without end. Panel 2750 with end panel 3250 and spare tyre Panel (Repair)
5	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING, BOTH REAR FENDERS AND SPARE WHEEL HOUSING.	\$ 5,200.00	2750 LH only. ✓
6	TO REMOVE AND RENEW REAR AND CENTRE EXHAUST SILENCER.	S/N \$ 480.00	✗
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: \$ 12,512.00	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2025 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>Dislocated</i>	\$	1,944.00 ✓	1555.20
2 REAR BUMPER FIXING PARTS <i>not in</i>	\$	191.00 +	
3 WHEEL HOUSING LINER ADAPTER - LH / RH <i>new</i> 2	\$	74.00 +	
4 REAR BUMPER GUIDE SECTION - LH / RH <i>Dented</i> 2	\$	32.00 * ✓	25.12
5 REAR BUMPER LOCKING MECHANISM <i>Dented</i>	\$	59.00 ✓	46.72
6 REAR BUMPER SPOILER <i>del</i>	\$	234.00 ✓	187.20
7 REAR LIGHT REFLECTOR - LH / RH <i>new</i> 2	\$	82.00 +	
8 LED LICENSE PLATE LIGHT <i>new</i> 2	\$	197.00 *	
9 LED TAIL LIGHT - LH / RH 2	\$	1,734.00 +	
10 TAIL LIGHT TRIM - LH RH 2	\$	60.00 +	
11 LED TAIL LIGHT - LH / RH 2	\$	1,734.00 +	
12 TAIL LIGHT TRIM - LH / RH 2	\$	60.00 +	
13 REAR REINFORCEMENT BEAM <i>Best</i>	\$	565.00 ✓	451.60
14 REAR BUMPER BRACKET - LH <i>Dented</i>	\$	27.00 ✓	21.12
15 REAR BUMPER BRACKET - RH <i>Dented</i>	\$	28.00 ✓	22.24
16 REAR BUMPER GUIDE SECTION - LH / RH <i>new</i> 2	\$	132.00 *	
17 REAR PARKING AID SENSOR - INNER / OUTER <i>1 piece</i> 4	\$	968.00 242	386.
18 REAR PARKING AID SEL RING <i>new</i> 4	\$	14.00 ✓	10.88
19 REAR BUMPER WIRING SET <i>new</i>	\$	510.00 *	
20 REAR LID <i>Dented</i>	\$	2,564.00 ✓	2051.20
SUB TOTAL SPARE PARTS	:	\$ 11,209.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2025 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 REAR LID ATTACHMENT PARTS <i>new</i>		\$ 291.00	+
22 REAR LID HINGE - LH / RH <i>new</i>	2	\$ 506.00	+
23 REAR LID FLAP GASKET <i>Damaged.</i>		\$ 203.00	3/ 162.00
24 REAR LID LOCK STRIKER <i>new</i>		\$ 49.00	+
25 REAR LID LOCK <i>new</i>		\$ 184.00	+
26 LID LOCK PUSH BUTTON <i>new</i>		\$ 172.00	+
27 LID LOCK COVER <i>new</i>		\$ 16.00	+
28 AUDI EMBLEM <i>new</i>		\$ 122.00	✓ 97.60
29 REAR CROSS PANEL <i>Distorted</i>		\$ 356.00	2/ 284.40
30 CROSS PANEL REINFORCEMENT <i>Distorted.</i>		\$ 725.00	2/ 579.60
31 REAR CROSS PANEL TRIM <i>Delud</i>		\$ 153.00	✓ 122.40
32 LUGGAGE COMPARTMENT FLOOR COVERING <i>Delud</i>		\$ 536.00	✓ 428.40.
33 REAR LID TRIM PANEL <i>new</i>		\$ 303.00	+
34 REAR SILENCER HEAT SHIELD <i>new</i>		\$ 158.00	+
35 REAR SILENCER	3 <i>new</i>	\$ 712.00	+
36 REAR SILENCER DUAL CLIP		\$ 57.00	+
37 FRONT SILENCER <i>new</i>		\$ 475.00	+
38 FRONT SILENCER DUAL CLIP - INNER	2 <i>new</i>	\$ 57.00	+
39 FRONT SILENCER DUAL CLIP - OUTER		\$ 57.00	+
40 EXHAUST SYSTEM RETAINER	2	\$ 79.00	+
SUB TOTAL SPARE PARTS	:	\$ 5,211.00	

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2025 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
41 STONE CHIP <i>Nec</i>	S/N	\$ 180.00	<i>2</i> 180.00
42 CAVITY WAX <i>Nec</i>	S/N	\$ 140.00	<i>2</i> 140.00
43 ACRYLIC SEALANT <i>Nec</i>	S/N	\$ 180.00	<i>2</i> 180.00
44 REAR NO PLATE <i>Nec</i>	S/N	\$ 60.00	<i>+</i>
45 SUNDRIES <i>Nec</i>		\$ 300.00	<i>✓</i> 84.80
TOTAL SPARE PARTS	:	\$ 17,280.00	
TOTAL LABOUR CHARGES	:	\$ 12,512.00	
GRAND TOTAL	:	\$ 29,792.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adrian 
SURVEYED DATE : 22/10/20
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : not Authorized, 06 Days Without end panel
109 Days with end panel
and repair spare tyre panel.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE
AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR
CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR,
WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO
MS. NORA KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

Shirley

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0785/2020/NS

26-Oct-20

George Wong

1 of 1

SMJ 2025 J

AUDI A3 SEDAN 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
Parts			
1	STOWAGE COMPARTMENT <i>Damaged</i>	\$ 58.00	✓ 46.00
2	REAR LID LOCK COVER <i>lit</i>	\$ 8.00	✓ 6.32
3	KEYLESS CONTROL UNIT <i>Damaged</i>	\$ 69.00	✓ 55.12
4	REAR LID HINGE-RH <i>Best</i>	\$ 253.00	✓ 202.40
5	CONNECTING PLATE-LH/RH <i>Best</i>	\$ 286.00	✓ 228.00
TOTAL		\$674.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling

27/10/20

Resigned H.S.



5 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 2

ST Reg No. 19-9902271-W

Shirley

AIG Asia Pacific Insurance Pte Ltd

78 Shenton Way

#07-16 AIG Building

Singapore 079120

Attn: Mr. Adrian Ling - Motor Claims Dept

Tel: 6841 0055 - Fax: 6256 4315

Estimate No.

Date

Service Advisor

Pages

Regn No

Model No

PA/OD/0785/2020/NS

28-Oct-20

George Wong

1 of 1

SMJ 2025 J

AUDI A3 SEDAN 1.0 TFSI 8V

Quantity	Description		Unit Price	Amount
LABOUR				
1	To carry out first measurement on car o-liner.	S/N	\$ 800.00	✓
2	To put up vehicle on car o-liner to facilitate repairing of spare wheel housing.	S/N	\$ 1,800.00	✓
TOTAL			\$ 2,600.00	

For Premium Automobiles Pte Ltd

Authorised Signature

Adrian Ling
28/10/20
AS