



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

Supplementary Estimate 1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
 78 Shenton Way
 #07-16 AIG Building
 Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 - Fax: 6256 4315

Estimate No. PA/OD/0785/2020/NS
Date 26-Oct-20
Service Advisor George Wong
Pages 1 of 1
Regn No SMJ 2025 J
Model No AUDI A3 SEDAN 1.0 TFSI 8V

Quantity	Description	Unit Price	Amount
Parts			
1	STOWAGE COMPARTMENT <i>Damaged</i>	\$ 58.00	✓
2	REAR LID LOCK COVER <i>lit</i>	\$ 8.00	✓
3	KEYLESS CONTROL UNIT <i>Damaged</i>	\$ 69.00	✓
4	REAR LID HINGE-RH <i>Best</i>	\$ 253.00	✓
5	CONNECTING PLATE-LH/RH <i>Best</i>	\$ 286.00	✓
TOTAL		\$674.00	

For Premium Automobiles Pte Ltd

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

Authorised Signature

Adrian Ling
 27/10/20
Resurveyed H.S.

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 2025 J

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	✓ S/N \$ 280.00	✓
2	TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS.	✓ S/N \$ 280.00	✓
3	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS. ELECTRICAL AND AUDIO EQUIPMENT.	S/N \$ 480.00	✓
4	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND BOTH REAR FENDERS. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 5,600.00	1500 without end panel 2750 with end panel and spare tyre Panel (Repair)
5	TO RESPRAY REAR BUMPER, REAR LID, HINGES, REAR END PANELLING, BOTH REAR FENDERS AND SPARE WHEEL HOUSING.	\$ 5,200.00	2750
6	TO REMOVE AND RENEW REAR AND CENTRE EXHAUST SILENCER.	S/N \$ 480.00	✓
7	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	✓
TOTAL LABOUR CHARGES		: <u>\$ 12,512.00</u>	

Carni wip: 53653

Kiam/Choy

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAJ@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 2025 J

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 REAR BUMPER <i>Distorted</i>	1	\$ 1,944.00	✓
2 REAR BUMPER FIXING PARTS <i>not in</i>	1	\$ 191.00	+
3 WHEEL HOUSING LINER ADAPTER - LH / RH <i>2</i>	2	\$ 74.00	+
4 REAR BUMPER GUIDE SECTION <i>(LH) (RH) Dmgd</i>	2	\$ 32.00	✓
5 REAR BUMPER LOCKING MECHANISM <i>Dmgd</i>	2	\$ 59.00	✓
6 REAR BUMPER SPOILER <i>del</i>	1	\$ 234.00	✓
7 REAR LIGHT REFLECTOR - LH / RH <i>new</i>	2	\$ 82.00	+
8 LED LICENSE PLATE LIGHT <i>new</i>	2	\$ 197.00	+
9 LED TAIL LIGHT - LH / RH <i>2</i>	2	\$ 1,734.00	+
10 TAIL LIGHT TRIM - LH RH <i>new</i>	2	\$ 60.00	+
11 LED TAIL LIGHT - LH / RH <i>new</i>	2	\$ 1,734.00	+
12 TAIL LIGHT TRIM - LH / RH <i>new</i>	2	\$ 60.00	+
13 REAR REINFORCEMENT BEAM <i>Best</i>	1	\$ 565.00	✓
14 REAR BUMPER BRACKET - LH <i>Dmgd</i>	1	\$ 27.00	✓
15 REAR BUMPER BRACKET - RH <i>?</i>	1	\$ 28.00	?
16 REAR BUMPER GUIDE SECTION - LH / RH <i>?</i>	2	\$ 132.00	?
17 REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	4	\$ 968.00	2+2
18 REAR PARKING AID SEL RING <i>new</i>	4	\$ 14.00	✓
19 REAR BUMPER WIRING SET <i>?</i>	1	\$ 510.00	?
20 REAR LID <i>Dented</i>	1	\$ 2,564.00	✓
SUB TOTAL SPARE PARTS	:	\$ 11,209.00	

PREMIUM AUTOMOBILES

55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG



MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 20251

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
21 REAR LID ATTACHMENT PARTS <i>new</i>		\$ 291.00	+
22 REAR LID HINGE LT RH <i>Rit Bent</i>	2	\$ 506.00	<i>253</i>
23 REAR LID FLAP GASKET <i>changed</i>		\$ 203.00	<i>✓</i>
24 REAR LID LOCK STRIKER <i>new</i>		\$ 49.00	+
25 REAR LID LOCK <i>new</i>		\$ 184.00	+
26 LID LOCK PUSH BUTTON <i>new</i>		\$ 172.00	+
27 LID LOCK COVER <i>new</i>		\$ 16.00	+
28 AUDI EMBLEM <i>new</i>		\$ 122.00	<i>✓</i>
29 REAR CROSS PANEL <i>Disturbed</i>		\$ 356.00	<i>✓</i>
30 CROSS PANEL REINFORCEMENT <i>Disturbed</i>		\$ 725.00	<i>✓</i>
31 REAR CROSS PANEL TRIM <i>new</i>		\$ 153.00	<i>✓</i>
32 LUGGAGE COMPARTMENT FLOOR COVERING <i>new</i>		\$ 536.00	<i>✓</i>
33 REAR LID TRIM PANEL <i>new</i>		\$ 303.00	+
34 REAR SILENCER HEAT SHIELD <i>new</i>		\$ 158.00	+
35 REAR SILENCER <i>new</i>		\$ 712.00	+
36 REAR SILENCER DUAL CLIP <i>new</i>		\$ 57.00	+
37 FRONT SILENCER <i>new</i>		\$ 475.00	+
38 FRONT SILENCER DUAL CLIP - INNER <i>new</i>		\$ 57.00	✓
39 FRONT SILENCER DUAL CLIP - OUTER <i>new</i>		\$ 57.00	✓
40 EXHAUST SYSTEM RETAINER <i>new</i>	2	\$ 79.00	+
SUB TOTAL SPARE PARTS		\$ 5,211.00	