

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6836 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 1 17:13

Company Reg. No. 199902271W

GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120		Invoice No: 85016171	Account: A0006 (T 0)	AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120	
		Date : 09/04/2021			
		Order : SMJ2025J			
		Term : 30			

Regn No: SMJ2025J (V 41015)	Regn Date: 25/02/2019	Mileage: 43357	WIP No.: 53653
Model: A3 SEDAN 1.0 TFSI 8VMANG	Chassis: WAUZZZ8V6K1016408	Engine: CHZ C26271	Dept: U
You have been assisted by :- UB-Tony Foong (33)			

		Details	Qty	Unit Price	Amount
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE	280.00	1.00	280.00
S	BODYWORK	M: TO REMOVE AND TRANSFER REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHT.	280.00	1.00	280.00
S	BODYWORK	M: TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS,BATTERY MANAGER,FUSE AND RELAY TRAYS.ELECTRICAL AND AUDIO EQUIPMENT.	480.00	1.00	480.00
S	BODYWORK	M: TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID.TO CUT OUT AND WELD REAR END PANELLING. TO REPAIR SPARE WHEEL HOUSING AND BOTH REAR FENDER.REORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	3250.00	1.00	3,250.00
S	BODYWORK	M: TO RESPRAY REAR BUMPER,REAR LID, END PANELLING,LHS REAR FENDER AND SPARE WHEEL HOUSING.	2750.00	1.00	2,750.00
S	BODYWORK	M: TO CARRY OUT DIAGNOSTIC CHECK	192.00	1.00	192.00
S	BODYWORK	M: TO SUPPLY STONE CHIP,CAVITY WAX AND ACRYLIC SEALANT.	500.00	1.00	500.00
S	BODYWORK	M: TO CARRY OUT FIRST MEASUREMENT ON CAR O LINER	800.00	1.00	800.00
S	BODYWORK	M: TO PUT UP VEHICLE ON CAR O LINER TO FACILITATE REPAIRING OF SPARE WHEEL HOUSING.	1800.00	1.00	1,800.00
X	A8V5807067G GRU	COVER(LAST) Less 020%	1.00	1944.00	1,555.20

Premium Automobiles Pte Ltd



Audi Centre Singapore
281 Alexandra Road
Singapore 159938
Main Telephone 6386 2223
Main Telefax 6471 3733

Alexandra Service Centre
281 Alexandra Road
Singapore 159938
Main Telephone 6388 2223
Main Telefax 6475 1023

Ubi Service Centre
55 Ubi Road 1
Singapore 408699
Main Telephone 6388 2323
Main Telefax 6841 1183

Customer Service
Service Appointment 6366 2323
24-hour Breakdown Service 9828 1233
Email customer.care@premiumauto.com.sg

INS TAX INVOICE

Page 2 17:13

Company Reg. No. 199902271W
GST Reg. No. 199902271W

AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120 079120	Invoice No: 85016171 Date : 09/04/2021 Order : SMJ2025J Term : 30	Account: A0006 (T 0) AIG ASIA PACIFIC INSURANCE PTE LTD MOTOR CLAIM DEPT AIG BUILDING 78 SHENTON WAY #07-16 SINGAPORE 079120
---	--	--

Regn No: SMJ2025J (V 41015) Regn Date: 25/02/2019 Mileage: 43357 WIP No.: 53653
Model: A3 SEDAN 1.0 TFSI 8VMANG Chassis: WAUZZZ8V6K1016408 Engine: CHZ C26271 Dept: U
You have been assisted by :- UB-Tony Foong (33)

		Details	Qty	Unit Price	Amount
X	A8V5807571A	GUIDE AP			
X	A8V5807572A	GUIDE AP	Less 020%	1.00	15.70
X	A8V5807975A	CATCH AP	Less 020%	1.00	15.70
X	A8V5807521L 9B9	(A) (SK) SPOILER 22/10	Less 020%	2.00	29.20
X	A8V5807309	(SK) BEAM-A/P GT	Less 020%	1.00	234.00
X	A8V5807329A	BRACKET AP	Less 020%	1.00	564.50
X	A8V5807330A	BRACKET AP	Less 020%	1.00	26.40
X	A8V5827302C	HINGE (LAST) AP	Less 020%	1.00	27.80
X	A8V5827705E	WTHRSTRIP AP	Less 020%	1.00	253.00
X	A4H0827520	COVER AP	Less 020%	1.00	202.50
X	A8V7853742 22Z	(A) (SK) AUDI SIGN 22/	Less 020%	1.00	7.50
X	A8V5813307	008472/ (V) (SK) REAR A	Less 020%	1.00	122.00
X	A8V5813331TC	REINFORCEM (LAST) AP	Less 020%	1.00	355.50
X	A8V5863471B 4PK	(A) (SK) TRIM PANEL 2	Less 020%	1.00	724.50
X	A8V5863463G CA9	(A) (SK) LINING 22/10/	Less 020%	1.00	153.00
X	A8D0853419F	PACKING-A/P GT	Less 020%	1.00	535.50
X	A5Q0919275B GRU	Sensor	Less 020%	1.00	18.00
X	A5Q0919133 704	WASHER	Less 020%	2.00	241.25
X	A8V5827025F	LID BORROW	Less 020%	4.00	3.40
X	A8T0827310A	CLIP	Less 020%	1.00	2564.00
X	A8V5012109F	008472/ (V) (GER) BIN A	Less 020%	2.00	1.40
X	AN 91233601	008472/ (V) (SK) NUT AP	Less 020%	1.00	57.50
X	A8K9805673C	GROMMET AP	Less 020%	4.00	2.90
X	AN 10596201	NUT	Less 020%	4.00	1.70
X	A5Q0962131	008472/ (V) (SK) AERIAL	Less 020%	2.00	2.30
X	A8V5813543	PLATE AP	Less 020%	1.00	68.90
X	A8V5813544	PLATE AP	Less 020%	1.00	142.50
X	AN 10226501	PLUG AP	Less 020%	1.00	142.50
X	A8V5827231 9B9	COVER AP	Less 020%	4.00	2.10
X	A8V5827232 9B9	COVER AP	Less 020%	1.00	7.90
X	A8V5827310	CLIP AP	Less 020%	1.00	7.90
X	A8V5971821	008485/ (GER) CONDUIT-	Less 020%	2.00	1.50
X	A8P4827951A	PLUG	Less 020%	1.00	33.60
				1.00	1.80

Parts 7,054.32
Labour 0.00
Sublet 10,332.00
Menus 0.00
Lubricant 0.00

Sub-Total 17,386.32

7% GST 1,217.04

Grand Total 18,603.36



Received by

For & on behalf of
Premium Automobiles Pte Ltd