



CYCLE &amp; CARRIAGE

**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

Co Reg No : 199405410K

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info	
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name	LCV08067/CHIA JIA JUN
	Reg No/Reg Date	SMH1421R / 14/01/201
	Date In/Mileage	/ 27731
	Chassis No	KNAF3416MK5024571
	Engine No	G4FGJH713534
	Make/Model	KIA/CERATO 1.6 A EX G333
	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No	
LAX00000	Credit	23/10/2020/ 10:35	BLE	261 / Edwin Caina	23120	
Description of Goods / Services			Qty	Unit Price	Disc%	Amount
E PNT88000	RENEW RR BUMPER , RR END PNL , BOOTLID & RR FLR PNL REPAIR LHR FENDER , RHR FENDER & RR CHASSIS <i>@ 4.5 x 400</i>					1800 <del>3200.00</del>
E PNT98000	RESPRAY RR BUMPER , RR END PNL , RR FLR PNL , BOOTLID , LHR FENDER RHR FENDER & RR CHASSIS <i>@ 350 x 5</i>					1750 <del>2450.00</del>
E PNT88000	REMOVE & REFIT BOOTLID COMPONENT					120.00
E PNT88000	REMOVE & REFIT RR FLR BOARD , TRIM , CARPET , SEAT TO FACILITATE REPAIR <i>? p lhr</i>					? 120.00
A 13900099	REMOVE & REFIT FUEL TANK ASSY TO GIVE WAY FOR REPAIR					X 200.00
A 15900099	REMOVE & REFIT RR EXHAUST MUFFLER ASSY					? 200.00
A 54900099	CHECK WIRING ELECTRICAL SYSTEM					30.00
A 10028901	TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					120.00
M SUNDRY	APPLY ANTI CORROSION ON AFFECTED AREAS					80.00
M SUNDRY	SUPPLY RR NUMBER PLATE WITH CASING					? 50.00
E PNT88000	REMOVE & REFIT REVERSE SENSOR					60.00
M SUNDRY	SUPPLY REVERSE SENSOR					220.00
M SUNDRY	SUPPLY C&C BADGE nec					40.00
M SUNDRY	Sundries nec					20.00
M COVER-RR BUMPER	<i>turn</i>				1.00	651.00 20.00 520.80

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Insurer Reference  
Road No



CARRIAGE

## CYCLE &amp; CARRIAGE KIA PTE LTD

## PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



199405410K

## ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	Cust No/Name LCV08067/CHIA JIA JUN Reg No/Reg Date SMH1421R / 14/01/201 Date In/Mileage / 27731 Chassis No KNAF3416MK5024571 Engine No G4FGJH713534 Make/Model KIA/CERATO 1.6 A EX G333 Colour/Trim CR5 RUNWAY RED / WK SATURN BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
LAX00000	Credit	23/10/2020/ 10:35	BLE	261 / Edwin Caina	23120
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
M COVER-RR BUMPER LWR <i>hm</i>		1.00	241.00	20.00	192.80
M COVER-RR BUMPER UNDER, LH <i>X</i> NN		1.00	33.00	20.00	26.40
M COVER-RR BUMPER FOG LAMP, LH <i>X</i> NN		1.00	19.00	20.00	15.20
M COVER-RR BUMPER FOG LAMP, RH <i>?</i>		1.00	19.00	20.00	15.20
M LAMP ASSY-SIDE T/SIGNAL, LH <i>X</i> NN		1.00	181.00	20.00	144.80
M LAMP ASSY-SIDE T/SIGNAL, RH <i>?</i>		1.00	181.00	20.00	144.80
M EXTN WIRING ASSY-BWS <i>?</i>		1.00	207.00	20.00	165.60
M BEAM-RR BUMPER <i>cr</i>		1.00	318.00	20.00	254.40
M STAY-RR BUMPER LH <i>X</i> NN		1.00	65.00	20.00	52.00
M STAY-RR BUMPER RH <i>?</i>		1.00	65.00	20.00	52.00
M BRACKET-RR BEAM UPR MTG, LH <i>X</i> NN		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM UPR MTG, RH <i>?</i>		1.00	9.00	20.00	7.20
M BRACKET-RR BEAM LWR, CTR <i>?</i>		1.00	6.00	20.00	4.80
M BRACKET-RR BEAM LWR MTG <i>?</i>		1.00	6.00	20.00	9.60
M ANTENNA ASSY-SMARTKEY <i>X</i> NN		1.00	46.00	20.00	36.80
M BRACKET ASSY-RR BPR SIDE UPR, L <i>X</i> NN		1.00	25.00	20.00	20.00
M BRACKET-ASSY RR BPR SIDE UPR, R <i>?</i>		1.00	31.00	20.00	24.80
M COVER-RR BUMPER UNDER, RH <i>?</i>		1.00	33.00	20.00	26.40
M PANEL ASSY-TRUNK LID <i>bt</i>		1.00	1297.00	20.00	1037.60
M HINGE ASSY-TRUNK LID, LH <i>?</i>		1.00	97.00	20.00	77.60
M HINGE ASSY-TRUNK LID, RH <i>?</i>		1.00	97.00	20.00	77.60
M LOGO ASSY-KIA SUB <i>hce</i>		1.00	32.00	20.00	25.60
M EMBLEM-CERATO <i>hce</i>		1.00	28.00	20.00	22.40
M W/STRIP-TRUNK LID OPNG <i>?</i>		1.00	100.00	20.00	80.00
M LATCH ASSY-TRUNK LID <i>cut</i>		1.00	112.00	20.00	89.60
M STRIKER ASSY-TRUNK LID <i>?</i>		1.00	40.00	20.00	32.00
M TRIM ASSY-TRUNK LID <i>?</i>		1.00	202.00	20.00	161.60
M LAMP ASSY-CENTER GARNISH <i>?</i>		1.00	690.00	20.00	552.00
M LAMP ASSY-REAR COMB INSIDE, LH <i>?</i>		1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB INSIDE, RH <i>?</i>		1.00	608.00	20.00	486.40
M LAMP ASSY-REAR COMB OUTSIDE, LH <i>?</i>		1.00	675.00	20.00	540.00
M LAMP ASSY-REAR COMB OUTSIDE, RH <i>cr</i>		1.00	675.00	20.00	540.00
M PANEL ASSY-BACK <i>bt</i>		1.00	324.00	20.00	259.20

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.





**CYCLE & CARRIAGE KIA PTE LTD**  
**PANDAN GARDENS CUSTOMER SERVICE CENTRE**

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



**ESTIMATE**

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPARTMENT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 64191000	<table> <tr><td>Cust No/Name</td><td>LCV08067/CHIA JIA JUN</td></tr> <tr><td>Reg No/Reg Date</td><td>SMH1421R / 14/01/201</td></tr> <tr><td>Date In/Mileage</td><td>/ 27731</td></tr> <tr><td>Chassis No</td><td>KNAF3416MK5024571</td></tr> <tr><td>Engine No</td><td>G4FGJH713534</td></tr> <tr><td>Make/Model</td><td>KIA/CERATO 1.6 A EX G333</td></tr> <tr><td>Colour/Trim</td><td>CR5 RUNWAY RED / WK SATURN BLACK</td></tr> </table>	Cust No/Name	LCV08067/CHIA JIA JUN	Reg No/Reg Date	SMH1421R / 14/01/201	Date In/Mileage	/ 27731	Chassis No	KNAF3416MK5024571	Engine No	G4FGJH713534	Make/Model	KIA/CERATO 1.6 A EX G333	Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK
Cust No/Name	LCV08067/CHIA JIA JUN														
Reg No/Reg Date	SMH1421R / 14/01/201														
Date In/Mileage	/ 27731														
Chassis No	KNAF3416MK5024571														
Engine No	G4FGJH713534														
Make/Model	KIA/CERATO 1.6 A EX G333														
Colour/Trim	CR5 RUNWAY RED / WK SATURN BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
LAX00000	Credit	23/10/2020/ 10:35	BLE	261 / Edwin Caina	23120			
Description of Goods / Services				Qty	Unit Price	Disc%	Amount	
M	TRIM ASSY-RR TRANSVERSE			SVC	1.00	41.00	20.00	32.80
M	TRIM ASSY-RR TRANSVERSE				1.00	41.00	20.00	32.80
M	PANEL ASSY-REAR FLOOR,RR <i>repair</i>			SVC	1.00	219.00	20.00	175.20
M	GUARD-REAR WHEEL,LH ?				1.00	75.00	20.00	60.00
M	GUARD-REAR WHEEL,RH ?				1.00	75.00	20.00	60.00
M	MUFFLER ASSY-REAR ?				1.00	757.00	20.00	605.60
M	PROTECTOR-HEAT REAR <i>bt</i>				1.00	136.00	20.00	108.80

# Estimate

SURVEYOR NAME: RASUL - 116 90010068

SURVEYOR SIGNATURE: *[Signature]*

DATE: 23/10/2020 @ 1540

REMARKS: 9 days

EXCESS: THA / PERCEP  
Resurvey before paint

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

Confirm & accepted by

	Nett	14,174.00
7% GST on	14174.00	992.18

**Total Payable 15,166.18**

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.