

ASS. REC. BY:

REF:

CS/CTI20011521/Ksd3


Kenneth

ASSIGNMENT

From: _____ Date: _____
 Estimated Cost: _____
 To Inspect Vehicle No: 00 / TP / WS / TP RES / OD RES / EVA / INV / MV
 at Workshop n/s Yes No
 of _____
 Insured: _____
 Policy No. _____
 Claims No. _____
 Sum Insured: _____ Excess: _____
 (Client's Record)
 Make of Veh: _____

Veh No: SKU 43355 Yr Regn: 071 15
 Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /
 Truck / Trailer or Wagon
 Make: Honda Odyssey c.c. 2356
 Colour: M.P. White A/C: Insured / Std / Nil / NA
 Sp. Reading: 120246 T/Radio: Insured / Std / Nil / NA
 Eng/No: _____
 C/No: JHMRC1890FC 202518
 Gen. Cond: Good / Fair / Poor / Burnt
 Steering: In order / Jammed / Leaked / Burnt or _____
 Brake: In order / Jammed / Leaked / Burnt or _____
 Mod: Nil / SR/Im / STD A/R/Im or _____

(Policy Condition)
 Remark: The veh had commenced its repair at the time of inspection.
 Bal. or Market Value: _____
 IDAC Accident Rport: _____ Consistent?: Yes or No
 GIA / PR Seen: _____ Consistent?: Yes or No
 Est. Repairs: 06 days Res.: Yes or No
 Lum Sum: 20 % 3 Val.: Yes or No
 CA / REV / REP. / 24 HRS
 Date: _____ Person Contacted: _____
 Vehicle: IN / OUT



Tyre Size: F: _____ R: 215/55R17
 BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
 TOYO / YOKO or _____
 Front R/Bal. 8 mm Rear R/Bal. 8 mm
 L/Bal. 8 mm L/Bal. 8 mm
 D.O.A. 21/10/20 D.O.I. 23/10/2020
 Survey held at _____
 Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or
N/S body
 The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
/	
	KENNETH CONFIRMED L/S \$ 5,100.00/6 DAYS WITH MS. PENG.
	(\$ 14,612.40/RED - 74%)

Date/Time, File Pass to? 19/11/2020
 1) TYPIST : Prell. Report : Final Report
 Date/Time, File Return to?

Days Of Repair: 6
 Resurvey No. of Trip: 2

Report Format : **Lump Sum** I.B.I: (\$ L/S \$ 5,100.00)

- Add Fee: : Site Insp (\$)
 : Interview (\$)
 : Tech Invs (\$)
 : Weekend (\$)

Survey Fee: _____
 Transportation: _____
 S - RS. SI _____
 Fuel/Exp _____
 Others _____
 TOTAL _____



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

Estimate No: ES2000096
 Date: 22 Oct 2020

ATTN: Motor Claim Department

Not Authored

Policy No:
 Veh Reg No: SKU4335S
 Make/Model: HONDA ODYSSEY 2.4 EXV-S CVT SR NAVI RES

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 21/10/2020
 TP Veh Reg No: SKU4335S


*11 Sep 8
 Recovery After Pain*

Chassis No: JHMRC1890FC202518
 Engine No: K24W71011220
 Reg. Date: 27/07/2015

6 days

Estimate Repair Cost to Vehicle No :SKU4335S

Description	U/Price	Quantity	List Price SS	Amount SS
Net Price	600.00	1 PC	600.00	600.00
1 REAR WHEEL RIM - LH			600.00	
Spare Parts				
2 FRONT DOOR - LH	1,135.90	1 PC	1,135.90	
3 FRONT DOOR CENTRE PILLAR - LH	642.10	1 PC	642.10	
4 FRONT DOOR CHANNEL - LH	92.40	1 PC	92.40	
5 FRONT DOOR GLASS OUTER MOULDING - LH	147.70	1 PC	147.70	
6 FRONT DOOR HINGE - LH (TOP)	188.60	1 PC	188.60	
7 FRONT DOOR HINGE - LH (LOWER)	188.60	1 PC	188.60	
8 FRONT DOOR LOCK - LH	272.80	1 PC	272.80	
9 FRONT DOOR LOCKER PANEL STEP COVER - LH	198.50	1 PC	198.50	
10 FRONT DOOR OUTER HANDLE - LH	385.00	1 PC	385.00	
11 FRONT DOOR PILLAR - LH	628.60	1 PC	628.60	
12 FRONT DOOR REGULATOR GEAR - LH	278.60	1 PC	278.60	
13 FRONT DOOR REGULATOR GEAR MOTOR - LH	334.90	1 PC	334.90	
14 FRONT DOOR STICKER - LH	56.50	1 PC	56.50	
15 FRONT DOOR TRIM BOARD - LH	698.00	1 PC	698.00	
16 FRONT DOOR WEATHERSTRIP - LH	179.50	1 PC	179.50	
17 FRONT DOOR OUTER HANDLE - LH (back)	195.50	1 PC	195.50	
18 FRONT DOOR PROTECTOR - LH	485.10	1 PC	485.10	
19 REAR BUMPER	882.20	1 PC	882.20	
20 REAR BUMPER CLIPS	40.00	1 SET	40.00	
21 REAR BUMPER SIDE RETAINER - LH	65.20	1 PC	65.20	
22 REAR BUMPER SIDE RETAINER - RH	65.20	1 PC	65.20	
23 REAR SLIDING DOOR - LH	1,112.30	1 PC	1,112.30	
24 REAR SLIDING DOOR AUTOMATIC MOTOR - LH	755.20	1 PC	755.20	
25 REAR SLIDING DOOR GLASS OUTER MOULDING - LH	145.50	1 PC	145.50	
26 REAR SLIDING DOOR HINGE - LH (TOP)	186.40	1 PC	186.40	
27 REAR SLIDING DOOR INNER TRIM BOARD - LH (LOWER)	798.00	1 PC	798.00	
28 REAR SLIDING DOOR LOCKER PANEL STEP COVER - LH	225.50	1 PC	225.50	
29 REAR SLIDING DOOR HINGE - LH (CENTRE)	230.90	1 PC	230.90	
30 REAR SLIDING DOOR OUTER HANDLE - LH	385.00	1 PC	385.00	
31 REAR SLIDING DOOR REGULATOR GEAR - LH	197.90	1 PC	197.90	
32 REAR SLIDING DOOR REGULATOR GEAR MOTOR - LH	303.10	1 PC	303.10	
33 REAR SLIDING DOOR RUBBER - LH	85.50	1 PC	85.50	



YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031
 Email: yeeautopteltd@gmail.com
 Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd
 3 Anson Road
 #16-00 Springleaf Tower
 Singapore 079909

Estimate No: **ES2000096**
 Date: 22 Oct 2020
 Policy No:
 Veh Reg No: **SKU4335S**
 Make/Model: **HONDA ODYSSEY 2.4 EXV-S CVT SR NAVI RES**

ATTN: Motor Claim Department

Chassis No: **JHMRC1890FC202518**
 Engine No: **K24W71011220**
 Reg. Date: **27/07/2015**

Your Ref No: -
 Claim Type: Third Party
 Accident Date: 21/10/2020
 TP Veh Reg No: SKU4335S

Estimate Repair Cost to Vehicle No :SKU4335S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
34 REAR SLIDING DOOR SPEAKER	305.10	1 PC	305.10	X
35 REAR SLIDING DOOR STICKER	56.50	1 PC	56.50	—
36 REAR SLIDING DOOR WEATHERSTRIP - LH	179.50	1 PC	179.50	?
37 REAR SLIDING DOOR RUBBER SENSOR	550.00	1 PC	550.00	?
38 REAR SLIDING DOOR PROTECTOR - LH	485.10	1 PC	485.10	X
			13,162.40	13,162.40
Labour				
39 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,000.00	1 JOB	2,000.00	700
40 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,000.00	1 JOB	2,000.00	880
41 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	60
42 TO REMOVE/REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.	400.00	1 JOB	400.00	80
43 TO REMOVE/RENEW AIRCON CONDENSER & REFILL GAS	250.00	1 JOB	250.00	X
44 TO REMOVE/RENEW RADIATOR ASSY.	150.00	1 JOB	150.00	X
45 TO TOW VEHICLE TO WORKSHOP.	150.00	1 JOB	150.00	?
46 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	20
47 WHEEL ALIGNMENT	120.00	1 T	120.00	X
			5,370.00	5,370.00

200

Total SS 19,132.40

Add GST @ 7% 1,339.27

Total Amount Payable SS 20,471.67

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FOUR HUNDRED SEVENTY ONE AND CENTS SIXTY SEVEN ONLY

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

For Yee Auto Pte Ltd

AUTHORIZED SIGNATURE

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	21/10/2020 16:07
Date Of Accident	21/10/2020 13:30
Exact Location Of Accident	ANG MO KIO AVE 3 TOWARDS SERANGOON NORTH AVE 1
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SKU4335S
Insured/Policyholder	
Name Of Registered Owner	TAY HUI LING ADELINE
NRIC No	SXXXX471G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96206204
Alternative Phone No	OFFICE-NOPHONE

Vehicle Particulars

Manufacturer	HONDA
Model	ODYSSEY
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USED.
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE CAR

Insurance Company

Name of Insurance Company	FWD SINGAPORE PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	PNPV2020-00007553
Cover Note Number	27/07/2020 TO 26/07/2021

Driver

Name of Driver	TAY HUI LING ADELINE
NRIC No	SXXXX471G
Date Of Birth	05/12/1981
Occupation	INDOOR
Date Of Driving Pass	24/09/2009
Driving Experience	11 YEARS AND 0 MONTHS
Gender	FEMALE
Mobile Number	(LOCAL) +65-96206204
Fax Number	
Contact Number	OFFICE-NOPHONE
E-Mail Address	NOEMAIL

Address BLK 590A ANG MO KIO STREET 51
 #29-15
 Postcode 561590
 Was driver an employee of the Insured's Company NO
 If No, Relationship of the Driver with the Insured OWNER
 Vehicle Registration Number of Driver's Own Vehicle -
 -
 -
 Insurance Company of Driver's Own Vehicle -
 -
 -

General Information of the Accident

Type Of Accident COLLISION - MAJOR/MINOR RD
 Weather Conditions CLEAR
 Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
 Number of vehicles (including own vehicle) involved in the accident 2
 Was any body injured in the Accident? NO
 Was any injured conveyed to hospital by ambulance? NO
 Was any other material or property damaged? YES
 I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
 Number of Passengers (Including Driver) 5

Passenger 1 NAME: : SEE YONG PENG
 GENDER: : MALE

Passenger 2 NAME: : SEE WEI QIAN
 GENDER: : FEMALE

Passenger 3 NAME: : SEE WEN QING
 GENDER: : FEMALE

Passenger 4 NAME: : TOH EN YI
 GENDER: : FEMALE

Details of Police Action

Was the accident reported to the police? NO
 If Yes, Please state which Police Station
 Was notice of intended Prosecution given? NO
 If Yes, against whom?

Circumstances of Accident

REFER TO SKETCH PLAN.

Attachment(s)

Are accident photos available for attachment? YES
 Was there any video captured by Car Camera? YES
 Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1


Vehicle Registration Number GBJ6126E
 Vehicle Make/Model/Colour
 Details Of Properties

Ke

Sketch Plan Pg. 2

SKETCH PLAN

Date of Accident: 21/10/2020 Time: 1:30pm Location: Ang Mo Kio Ave 3 towards Serangoon North Ave 1
My Vehicle A: SKU4335S Vehicle B: GBJ6126E Vehicle C/Others:



DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 21/10/2020 at 1:30pm. I was travelling my Vehicle (A) SKU4335S along Ang Mo Kio Ave 3 towards Serangoon North Ave 1. As I go straight, suddenly, the Vehicle (B) GBJ6126E from left side cut into my lane and hit my vehicle left portion.

() Claim OD/TP at Ah Lim Motor Claim OD/TP at other workshop () Reporting Only

Remarks : Please forward a copy of my efile accident report to:

My workshop : Yee Auto Pte Ltd
 email address : yeeautopte ltd@gmail.com
 & myself : rdelinety@gmail.com
 email address : rdelinety@gmail.com

Note : Please take note that your insurer have 14 days timeframe for you to submit own damage claim under your own policy. Kindly check with your own insurer for more information.

DECLARATION

I/We declare the foregoing particulars are true in every respect.


 Policyholder's Signature
 Date & Time:


 Driver's Signature
 (If driver is not the policyholder)
 Date & Time:



 Reporting Centre Personnel's Signature
 Name:
 NRIC/FIN No.: 21/10/2020