



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
 Tel: 6457 5768 Fax: 6252 8459 Mobile: 9687 4031  
 Email: yeeautopteltd@gmail.com  
 Registration No.: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd  
 3 Anson Road  
 #16-00 Springleaf Tower  
 Singapore 079909

Estimate No: ES2000096  
 Date: 22 Oct 2020

ATTN: Motor Claim Department

*Not Noted*  
*L1 Sm @ 5100/r*  
*Recovery After Paint*

Policy No:  
 Veh Reg No: SKU4335S  
 Make/Model: HONDA ODYSSEY 2.4 EXV-S CVT SR NAVI RES  
 Chassis No: JHMRC1890FC202518  
 Engine No: K24W71011220  
 Reg. Date: 27/07/2015

Your Ref No: -  
 Claim Type: Third Party  
 Accident Date: 21/10/2020  
 TP Veh Reg No: SKU4335S

*6 days*

## Estimate Repair Cost to Vehicle No :SKU4335S

Description	U/Price	Quantity	List Price		Amount
			SS	SS	SS
<b>Net Price</b>					
1 REAR WHEEL RIM - LH	600.00	1 PC	Sm	600.00 X	600.00
<b>Spare Parts</b>					
2 FRONT DOOR - LH	1,135.90	1 PC	R	1,135.90 ✓	
3 FRONT DOOR CENTRE PILLAR - LH	642.10	1 PC	R	642.10 X	
4 FRONT DOOR CHANNEL - LH	92.40	1 PC	Sm	92.40 X	
5 FRONT DOOR GLASS OUTER MOULDING - LH	147.70	1 PC	Sm	147.70 X	
6 FRONT DOOR HINGE - LH (TOP)	188.60	1 PC	R	188.60 X	
7 FRONT DOOR HINGE - LH (LOWER)	188.60	1 PC	R	188.60 X	
8 FRONT DOOR LOCK - LH	272.80	1 PC	Del	272.80 ✓	
9 FRONT DOOR LOCKER PANEL STEP COVER - LH	198.50	1 PC	Sm	198.50 X	
10 FRONT DOOR OUTER HANDLE - LH	385.00	1 PC	Del	385.00 ✓	
11 FRONT DOOR PILLAR - LH	628.60	1 PC	R	628.60 X	
12 FRONT DOOR REGULATOR GEAR - LH	278.60	1 PC	R	278.60 ✓	
13 FRONT DOOR REGULATOR GEAR MOTOR - LH	334.90	1 PC	Sm	334.90 ✓	
14 FRONT DOOR STICKER - LH	56.50	1 PC	Sm	56.50 ✓	
15 FRONT DOOR TRIM BOARD - LH	698.00	1 PC	Sm	698.00 X	
16 FRONT DOOR WEATHERSTRIP - LH	179.50	1 PC	Sm	179.50 ✓	
17 FRONT DOOR OUTER HANDLE - LH (back)	195.50	1 PC	Del	195.50 ✓	
18 FRONT DOOR PROTECTOR - LH	485.10	1 PC	Sm	485.10 X	
19 REAR BUMPER	882.20	1 PC	R	882.20 X	
20 REAR BUMPER CLIPS	40.00	1 SET	Sm	40.00 X	
21 REAR BUMPER SIDE RETAINER - LH	65.20	1 PC	Sm	65.20 X	
22 REAR BUMPER SIDE RETAINER - RH	65.20	1 PC	Sm	65.20 X	
23 REAR SLIDING DOOR - LH	1,112.30	1 PC	R	1,112.30 ✓	
24 REAR SLIDING DOOR AUTOMATIC MOTOR - LH	755.20	1 PC	Sm	755.20 ✓	
25 REAR SLIDING DOOR GLASS OUTER MOULDING - LH	145.50	1 PC	Sm	145.50 X	
26 REAR SLIDING DOOR HINGE - LH (TOP)	186.40	1 PC	R	186.40 X	
27 REAR SLIDING DOOR INNER TRIM BOARD - LH (LOWER)	798.00	1 PC	Sm	798.00 X	
28 REAR SLIDING DOOR LOCKER PANEL STEP COVER - LH	225.50	1 PC	Sm	225.50 X	
29 REAR SLIDING DOOR HINGE - LH (CENTRE)	230.90	1 PC	Sm	230.90 X	
30 REAR SLIDING DOOR OUTER HANDLE - LH	385.00	1 PC	Sm	385.00 ✓	
31 REAR SLIDING DOOR REGULATOR GEAR - LH	197.90	1 PC	Sm	197.90 X	
32 REAR SLIDING DOOR REGULATOR GEAR MOTOR - LH	303.10	1 PC	Sm	303.10 X	
33 REAR SLIDING DOOR RUBBER - LH	85.50	1 PC	Sm	85.50 X	

*977.70*

*261.50*

*89.75*

*1080.80*

*255.60*



# YEE AUTO PTE LTD

160 Sin Ming Drive #02-17/#07-12 Sin Ming AutoCity Singapore 575722  
 Tel 6457 5768 Fax 6252 8459 Mobile 9687 4031  
 Email: yeeautopteltd@gmail.com  
 Registration No: 201719251W GST No: 201719251W

M/S : China Taiping Insurance (Singapore) Pte Ltd  
 3 Anson Road  
 #16-00 Springleaf Tower  
 Singapore 079909

Estimate No: ES2000096  
 Date: 22 Oct 2020  
 Policy No:  
 Veh Reg No: SKU4335S  
 Make/Model: HONDA ODYSSEY 2.4  
 EXV-S CVT SR NAVI  
 RES

ATTN: Motor Claim Department

Your Ref No: -  
 Claim Type: Third Party  
 Accident Date: 21/10/2020  
 TP Veh Reg No: SKU4335S

Chassis No: JHMRC1890FC202518  
 Engine No: K24W71011220  
 Reg. Date: 27/07/2015

### Estimate Repair Cost to Vehicle No :SKU4335S

Description	U/Price	Quantity	List Price	Amount
			SS	SS
34 REAR SLIDING DOOR SPEAKER	305.10	1 PC	305.10	X
35 REAR SLIDING DOOR STICKER	56.50	1 PC	56.50	
36 REAR SLIDING DOOR WEATHERSTRIP - LH	89.75 <i>89.75</i>	1 PC	179.50	<i>179.50</i>
37 REAR SLIDING DOOR RUBBER SENSOR	550.00	1 PC	550.00	<i>2</i>
38 REAR SLIDING DOOR PROTECTOR - LH	485.10	1 PC	485.10	X
			13,162.40	13,162.40
<b>Labour</b>				
39 TO DISMANTLE & REPLACE DAMAGED PARTS, PANEL BEAT WHERE NECESSARY.	2,000.00	1 JOB	2,000.00	<i>700</i>
40 TO PUTTY, APPLY PRIMER & SPRAY-PAINT ON THE AFFECTED PORTION.	2,000.00	1 JOB	2,000.00	<i>880</i>
41 TO APPLY RUST- PROOFING ON REPAIRED, REPLACED PANEL.	200.00	1 JOB	200.00	<i>60</i>
42 TO REMOVE/REFIT REAR CUSHION SEAT, SPEAKER BOARD, ROOF UPHOLSTERY TO FACILITATE REPAIRS.	400.00	1 JOB	400.00	<i>80</i>
43 TO REMOVE/RENEW AIRCON CONDENSER & REFILL GAS	250.00	1 JOB	250.00	X
44 TO REMOVE/RENEW RADIATOR ASSY.	150.00	1 JOB	150.00	X
45 TO TOW VEHICLE TO WORKSHOP.	150.00	1 JOB	150.00	X
46 TO CHECK WIRING FUNCTIONS.	100.00	1 JOB	100.00	<i>20</i>
47 WHEEL ALIGNMENT	120.00	1 T	120.00	X
			5,370.00	5,370.00

19,712.40 Total  
 Add GST @ 7% 1,339.27  
 Total Amount Payable S\$ 20,471.67

TOTAL: SINGAPORE DOLLAR TWENTY THOUSAND FOUR HUNDRED SEVENTY ONE AND CENTS SIXTY SEVEN ONLY

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
 Signature:  
 Date:

For Yee Auto Pte Ltd

AUTHORIZED SIGNATURE

## Yee Auto Pte Ltd

160 Sin Ming Dr #02-17 / #07-12 Sin Ming Autocity Singapore 575722  
 TEL: 6457 5768 FAX: 6252 8459 Email: yeeautopteLtd@gmail.com  
 GST:201719251W RCB NO:201719251W

**M/S :** China Taiping Insurance (Singapore) Pte Ltd  
 3 Anson Road  
 #16-00 Springleaf Tower  
 Singapore 079909

**ATTN:** Motor Claim Department


Your Ref No: -  
 Claim Type: Third Party  
 Accident Date: 21/10/2020  
 TP Veh Reg No: SKU4335S

**Estimate No:** ES2000096  
**Date:** 26 Oct 2020  
**Policy No:**  
**Veh Reg No:** SKU4335S  
**Make/Model:** HONDA ODYSSEY 2.4  
 EXV-S CVT SR NAVI  
 RES  
**Chassis No:** JHMRC1890FC202518  
**Engine No:** K24W71011220  
**Reg. Date:** 27/07/2015

### Estimate Repair Cost to Vehicle No :SKU4335S

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
Supplementary Parts to Repair				
<b>Net Price</b>				
1 FRONT DOOR SOUND PROOF INNER - LH	140.00	1 PC	140.00	120.50
2 FRONT DOOR SOUND PROOF OUTER - LH	140.00	1 PC	140.00	120.50
3 REAR SOUND PROOF SLIDING DOOR INNER - LH	150.00	1 PC	150.00	120.50
4 REAR SOUND PROOF SLIDING DOOR OUTER - LH	150.00	1 PC	150.00	120.50
			580.00	580.00
Total				S\$ 580.00
GST Amount				S\$ 40.60
Total Amount Payable				S\$ 620.60

For Yee Auto Pte Ltd

  
 \_\_\_\_\_  
 AUTHORIZED SIGNATURE