

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 28 Oct 2020

## Preliminary Advice

Insured Vehicle No : SKH6144G  
TP Vehicle No : SKW5935T  
Make : MITSUBISHI LANCER  
Date of Inspection : 23/10/2020  
Inspection At : Alfred Auto Services & Supplies (HQ)  
Blk 5035, Ang Mo Kio Ave 3, #01-351, Ang Mo Kio Industrial Park 2  
Singapore 569538

Accident Date : 25/09/2020  
Assignment Date : 22/10/2020  
Est. Duration of Repair : 2

### Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	5,311.00
Revised Amount	:S\$	600.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	600.00

Lump Sum Repair :S\$

### **Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

### Remarks

- The vehicle is economical for repair
  - The vehicle is not economical for repair
  - Part-by-Part repair
  - Lump Sum repair
- The above survey was conducted on a 'without prejudice' basis.