

Denise Tay (LKKAuto)

From: Simon Ho (LKKAuto)
Sent: Wednesday, 28 October 2020 10:50 AM
To: Denise Tay (LKKAuto)
Subject: Re: AUDIT CHECK

Follow Up Flag: Follow up
Flag Status: Flagged

Hi Denise,

Audit check done for SLB5441A, found photos for damaged parts LH rear rim & tyre, RH rear door trim panel are needed.

Best Regards,

Simon Ho

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: simonho@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



Save the Earth. Print only when necessary.

From: Denise Tay (LKKAuto) <denisetay@lkkauto.com>
Sent: Wednesday, 28 October 2020 8:19 AM
To: Simon Ho (LKKAuto) <SimonHo@lkkauto.com>
Subject: AUDIT CHECK

Hi Simon,

SLB 5441A photo in merimen

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6741-3062 | email: sur@lkkauto.com | fax: 6271-8802

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)