

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
 TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
 GST:201001158E RCB NO:201001158E

M/S: MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP/MSIG/AMK

Claim Type: Third Party

Accident Date: 23/10/2020

TP Veh Reg No: SLQ7615Z

Estimate No: ES2090859/AMK

Date: 27 Oct 2020

Policy No: DMPCSNW00096212000

Veh Reg No: SMD2261A

Make/Model: HONDA JAZZ 1.3 CVT A

Chassis No: JHMGK3850JX226639

Engine No: L13B11031016

Reg. Date: 08/08/2018

Estimate Repair Cost to Vehicle No :SMD2261A

Description	U/Price	Quantity	List Price	Amount
64 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	SS 60.00 ✓	SS
65 REMOVE & REFIX REAR BUMPER & ATTACHMENTS, TAILLAMP; TO CUT, WELD & RENEW REAR END PANEL; KNOCKING & REPAIR REAR LH FENDER & REALIGN THE SAME	600.00	1 LA	600.00 ? ✓	400
66 PUTTY & RESPRAY REAR BUMPER & REVERSE SENSORS, REAR END PANEL, REAR LH FENDER & ALL AFFECTED AREAS	600.00	1 LA	600.00	550
67 RUSTPROOFING	150.00	1 LA	150.00	120
			4,260.00	3760
				4,260.00
			Total	SS 16,943.20
			Add GST @ 7%	1,186.02
			Total Amount Payable	SS 18,129.22

* SURVEY VEHICLE AT ANG MO KIO WORKSHOP

For Cheng Hoe Motor Pte Ltd

Dorlyn

AUTHORISED SIGNATURE

PART: 11218.96

SW: 190

L: 3760

15168.96

PIP: 15168.96

PLS CHECK & CONFIRM