

Our Job Ref No 305428825Date : 24.10.20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr STEVEVehicle Reg No. SHA1695M CTPL19.10.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- SLD9665J

2. The finalized amount shall be:

(a) Spare Parts after List discount

(b) Labour Charges

Total for Part-By-Part Repair Cost

(c.) Lumpsum Repair (if applicable)

Total for Lumpsum repair cost after Less:

20%\$1,200.00**Final Lumpsum Repair cost**\$1,200.003. Estimated normal period for repairs: 2 working days.4. **We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : LIM KWOK ENGTel : 62148316Fax : 65468156Signature : Name : SteveDate : 26/10/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6. Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305428825
 REGN NO : SHA1695M
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 16.06.2016
 DATE/TIME IN : 19.10.2020 13:00
 ACCIDENT DATE : 19.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001 04-01-0103-0579-G	I40VC COVER ASSY-RR BUMPE	1 L	1,106.00	20.00	884.80	✓	00
0002 04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	✓	1,128 -20%
0003 04-01-0103-0738-G	I40VC COVER-RR BUMPER LWR	1 L	228.00	20.00	182.40	X	902.40
0004 09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	135.70	10.00	122.13	?	
0005 04-01-0103-0585-G	I40VC LAMP ASSY-RR COMB O ^{ch}	1 L	697.80	20.00	558.24	X (Not confirmed)	water marked
SUB-TOTAL : 1,765.17							

JOB NATURE

0000 20-05	REAR BUMPER ADVERTISMENT LOGO		50.00	✓	50.00	590
0001 L	PANEL BEATING	350.00	280			1,492.40 -20%
0002 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200			1,193.92
0003 17-01	CHECK ALL LIGHTING	50.00	30			
0004 20-22	REMOVE/REFIX REVERSE SENSOR	120.00	30			
SUB-TOTAL : 820.00						

Steve (CLKK) WK PL

19/10/20, 4.10pm

L/S \$1,200/-

By AL dy
2 dy