

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

Date: 21.10.2020

Time: 11:07:36

Page: 1

IS

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

NTUC - LKS
 LKK - Steve

JOB NO : 305429068
 REGN NO : SHD3379Y
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : I-40
 DATE OF REGN : 08.09.2016
 DATE/TIME IN : 21.10.2020 09:30
 ACCIDENT DATE : 14.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

QTY	IND	UNIT-PRICE	DISC%	AMOUNT
0001	04-01-0103-0579-U	REAR BUMPER	1	1,106.00 20.00 884.80 / DD
0002	04-01-0103-0738-G	REAR BUMPER UNDER COVER	1	228.00 20.00 182.40 X NM
0003	04-01-0101-0111-G	REAR BUMPER CLIPS	10 L	22.00 20.00 17.60 / MC
0004	09-01-9999-0068-A	REVERSE SENSOR	1	135.70 10.00 122.13 ? X NM

SUB-TOTAL : 1,206.93

JOB NATURE

0000 PB	PANEL BEATING	300.00	280
0001 SP	SPRAYPAINT CHARGE	250.00	200
0002 L	R/I REVERSE SENSOR	120.00	30

SUB-TOTAL : 670.00

TOTAL : 1,876.93

MVA NAME & SIGNATURE

DATE :

SURVEYOR NAME & SIGNATURE

DATE :

AUTHORISED : YES / NO

Lmfs

Steven (LKK) in M

21/10/20, 2-30 pm

L/S

My AL sy

2 dys

1412.40

LIS - 1129.92
= 1150

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To do a final survey after the repair
- Parts must be replaced with original or of equivalent quality
- Third party survey is done on a "no fault" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: