

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE

DATE: 20.10.2020

3P INSURANCE: NTUC

MODEL: HYUNDAI IONIQ (G3)

SURVEYOR: LKK

VEH NO.: SHA6607K

MVA: LOKE WY

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Bumper / BR			\$459.40
	Rear Bumper Reinforcement / BR			\$294.80
	Rear Bumper Reinforcement Bracket LH RH (RH) / BT	21	\$138.10	\$276.20
	Rear Bumper Centre Moulding Assy / BR			\$451.25
	Rear Bumper Lower Centre Moulding Assy / BR			\$155.00
	Rear Bumper Stay ? X			\$138.10
	Rear Bumper Side Bracket LH RH (RH) / BR	21		\$111.60
	Rear Bumper Cover Clips / MC	10		\$22.00
	Rear Bumper Under Centre Cover X			\$225.00
	Rear Bumper Side Under LH RH X	2	\$108.00	\$216.00
	Rear Bumper Hook X			\$5.40
	Rear Bumper Reflector Lamp (LRH) X			\$31.90
	Rear Bumper Fog Lamp / CUT			\$201.50
	Rear Bumper Towing Cover X			\$98.80
	Boot Lid / DD			\$2,480.40
	Boot Lid Rubber ? X			\$127.40
	Boot Lid Hinge LH RH X	2	\$31.30	\$62.60
	Boot Lid Lock Upper ? X			\$224.00
	Boot Lid Lock Lower X			\$51.30
	Emblem - Hybrid / MC			\$24.30
	Emblem - Ioniq / MC			\$31.30
	Boot Lid 'H' Emblem / CUT			\$28.00
	Rear Spoiler ? X			\$665.40
	Unit Aesy SMARTK CRU (Rader Sensor) ? / BR			\$2,910.90
	ASSY BSD- Blind Spot Radar ? / BT			\$1,625.00
	Wiring Harness BWS Ext ? X			\$988.90
	Tail Lamp RH / CUT			\$870.40
	Boot Lid Glass Lower / MC			\$384.90
	Boot Lid Lamp LH RH (RH) / CUT	21	\$794.40	\$1,588.80
	Boot Lid Trimboard ? / CRU			\$159.70
	Licence Lamp / MIS			\$60.40
	Licence Lamp Cover ? X			\$35.10
	Boot Lid Absorber ? X			\$65.65
	Boot Lid Trimboard Clips ? / MC	10		\$11.00
	Boot Lid Moulding ? X			\$85.00
	Boot Lid Garnish ? X			\$36.10
	Boot Lid Lower Garnish ? X			\$25.40
	Rear Panel / DD			\$532.00
	Rear Panel Garnish ? / CRU			\$155.00

PART NO.	DESCRIPTION	QTY	LIST PRICE	REMARKS
	Rear Panel Lower Panel ✓ <i>W</i>	2	\$39.40	\$78.80
	Exhaust Silencer RH X			\$943.50
	Exhaust Pipe Centre X			\$573.60
	SPARE PARTS SUB TOTAL			\$17,511.80
	LESS 20%			\$3,502.36
	DISCOUNTED SPARE PARTS TOTAL			\$14,009.44
	Rear Bumper Reverse Sensor ✓ <i>OR</i>		-10%	\$162.00 Nett
	Rear Bumper Rubber Mat ✓ <i>MC</i>			\$50.00 Nett
	Boot Lid Comfort Logo & Tel No. Sticker ✓ <i>MC</i>			\$30.00 Nett
	Boot Lid Comfort Logo Sticker ✓ <i>MC</i>			\$8.60 Nett
	Boot Lid Comfort Cablink Tel No. Sticker ✓ <i>MC</i>			\$9.00 Nett
	Rear No. Plate with Trim Cover ✓ <i>OR</i>			\$55.00 Nett
	Rear Bumper Reverse Light X			\$257.10 Nett
	NETT TOTAL			\$571.70
	DISCOUNTED SPARE PARTS & NETT TOTAL			\$14,581.14
	Panel Beating			\$1,700.00 <i>960</i>
	Spray Painting			\$1,000.00 <i>800</i>
	Remove/Refix Reverse Sensor			\$120.00 <i>30</i>
	Remove/ Refix Exhaust Silencer			\$120.00 X
	Check Wiring			\$120.00 <i>30</i>
	Tuff Kote			\$180.00 <i>30</i>
	LABOUR TOTAL			\$3,240.00
	ESTIMATE TOTAL			\$17,821.14

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

Steve (LKK)
W PR
20/10/20, 3.00pm
P/P
R BL SL
4 days

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: