



CYCLE &amp; CARRIAGE

CYCLE & CARRIAGE KIA PTE LTD  
PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240



## ESTIMATE

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address                                                                                                                                | Owner Name & Vehicle Info                                                                                                                                                                                                                                                |
|-------------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AIG Asia Pacific Insurance Pte.<br>Ltd.<br>MOTOR CLAIM DEPARTMENT<br>78 SHENTON WAY #08-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000 | Cust No/Name LCV10795/CHONG WEN HAO<br>Reg No/Reg Date SKT1394X / 06/08/201<br>Date In/Mileage 23/10/2020/ 0<br>Chassis No KNAD6811VL6319126<br>Engine No G3LCKP067522<br>Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF<br>Colour/Trim ABP AURORA BLACK / WK SATURN BLACK |

| Account No                                                                                                                                      | Terms  | Date/Time Printed | CSE | Operator          | WIP No |            |       |              |
|-------------------------------------------------------------------------------------------------------------------------------------------------|--------|-------------------|-----|-------------------|--------|------------|-------|--------------|
| LAX00000                                                                                                                                        | Credit | 23/10/2020/ 15:11 | QUK | 282 / Kevin Leong | 23156  |            |       |              |
| Description of Goods / Services                                                                                                                 |        |                   |     |                   | Qty    | Unit Price | Disc% | Amount       |
| E PNT88000                                                                                                                                      |        |                   |     |                   |        |            |       | 1200 3200.00 |
| TO REPLACE FRT BUMPER, BONNET, SUPPORT, FRT RH FENDER,<br>FRT RH WHEEL HOUSING & AFFECTED AREA @ 400 X 3 =<br>TO REPAIR ON FRT RH BODY CHASSIS? |        |                   |     |                   |        |            |       |              |
| E PNT98000                                                                                                                                      |        |                   |     |                   |        |            |       | 1400 2100.00 |
| PAINT WORK ON FRT BUMPER, BONNET, FRT RH WHEEL HOUSING, FRT RH-BODY CHASSIS & BOTH FRT FENDER @ 350 X 4                                         |        |                   |     |                   |        |            |       |              |
| E PNT88000                                                                                                                                      |        |                   |     |                   |        |            |       | ? 120.00     |
| TO REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR                                                                                   |        |                   |     |                   |        |            |       | ? 80.00      |
| M SUNDRY                                                                                                                                        |        |                   |     |                   |        |            |       | ? 400.00     |
| TO TOP UP AIRCON GAS                                                                                                                            |        |                   |     |                   |        |            |       | X 80.00      |
| A 11900199                                                                                                                                      |        |                   |     |                   |        |            |       | Yo 160.00    |
| TO REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR                                                                                                |        |                   |     |                   |        |            |       | 30.00        |
| M SUNDRY                                                                                                                                        |        |                   |     |                   |        |            |       | 120.00       |
| TO APPLY SEALANT ON AFFECTED AREA                                                                                                               |        |                   |     |                   |        |            |       | 50.00        |
| M SUNDRY                                                                                                                                        |        |                   |     |                   |        |            |       | 20 50.00     |
| PERFORM RUST PREVENTION                                                                                                                         |        |                   |     |                   |        |            |       |              |
| A 54900099                                                                                                                                      |        |                   |     |                   |        |            |       |              |
| CHECK WIRING & CHASSIS ELECTRICAL SYSTEM                                                                                                        |        |                   |     |                   |        |            |       |              |
| A 10028901                                                                                                                                      |        |                   |     |                   |        |            |       |              |
| TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST<br>USING HI-SCAN PRO TEST                                                                  |        |                   |     |                   |        |            |       |              |
| M SUNDRY                                                                                                                                        |        |                   |     |                   |        |            |       |              |
| TO SUPPLY FRONT NUMBER PLATE WITH FRAME                                                                                                         |        |                   |     |                   |        |            |       |              |
| M SUNDRY                                                                                                                                        |        |                   |     |                   |        |            |       |              |
| SUNDRIES                                                                                                                                        |        |                   |     |                   |        |            |       |              |
| M LAMP ASSY-HEAD, LH                                                                                                                            |        |                   |     |                   | 1.00   | 1845.00    | 20.00 | 1476.00      |
| M LAMP ASSY-HEAD, RH                                                                                                                            |        |                   |     |                   | 1.00   | 1845.00    | 20.00 | 1476.00      |
| M RESERVOIR & PUMP ASSY-WASHER                                                                                                                  |        |                   |     |                   | 1.00   | 152.00     | 20.00 | 121.60       |
| M PANEL ASSY-HOOD                                                                                                                               |        |                   |     |                   | 1.00   | 904.00     | 20.00 | 723.20       |
| M HINGE ASSY-HOOD, RH                                                                                                                           |        |                   |     |                   | 1.00   | 43.00      | 20.00 | 34.40        |
| M HINGE ASSY-HOOD, LH                                                                                                                           |        |                   |     |                   | 1.00   | 43.00      | 20.00 | 34.40        |
| M PANEL-FENDER, RH                                                                                                                              |        |                   |     |                   | 1.00   | 401.00     | 20.00 | 320.80       |

Confirm &amp; accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

Page 1 of 2

GIA / PR Seen: \_\_\_\_\_

Est. Repairs: \_\_\_\_\_

days

Res.: Yes Or No

23/10/2020

Estimate held at

CYCLE &amp; CARRIAGE (PST)





CYCLE &amp; CARRIAGE

# CYCLE & CARRIAGE KIA PTE LTD PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65651240

**ESTIMATE**

GST Reg No : MR-8500111-X

Co Reg No : 199405410K

| Invoice Name & Address                                                                                                                             | Owner Name & Vehicle Info                                                                                                                                                                                                                                                |
|----------------------------------------------------------------------------------------------------------------------------------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|
| AIG Asia Pacific Insurance Pte. Ltd.<br>MOTOR CLAIM DEPARTMENT<br>7B SHENTON WAY #08-16<br>AIG BUILDING<br>SINGAPORE 079120<br>Contact No 64191000 | Cust No/Name LCV10795/CHONG WEN HAO<br>Reg No/Reg Date SKT1394X / 06/08/201<br>Date In/Mileage 23/10/2020/ 0<br>Chassis No KNAD6811VL6319126<br>Engine No G3LCKP067522<br>Make/Model KIA/STONIC 1.0 A SX BJ3 W SUNROOF<br>Colour/Trim ABP AURORA BLACK / WK SATURN BLACK |

| Account No                             | Terms  | Date/Time Printed | CSE        | Operator          | WIP No |
|----------------------------------------|--------|-------------------|------------|-------------------|--------|
| LAX00000                               | Credit | 23/10/2020/ 15:11 | QUK        | 282 / Kevin Leong | 23156  |
| Description of Goods / Services        |        | Qty               | Unit Price | Disc%             | Amount |
| M INSULATOR-FENDER RH ?                |        | 1.00              | 27.00      | 20.00             | 21.60  |
| M BEAM COMPLETE-FR BUMPER              |        | 1.00              | 544.00     | 20.00             | 435.20 |
| M CARRIER ASSY-FRONT END MODULE ?      |        | 1.00              | 556.00     | 20.00             | 444.80 |
| M BRACKET ASSY-CARRIER MTG, RH ?       |        | 1.00              | 27.00      | 20.00             | 21.60  |
| M EXTN-FR SIDE MEMBER OTR FR, RH ?     |        | 1.00              | 24.00      | 20.00             | 19.20  |
| M REINF-FENDER APRON UPR, RH ?         |        | 1.00              | 62.00      | 20.00             | 49.60  |
| M PANEL ASSY-FNDR APRON, RH ?          |        | 1.00              | 263.00     | 20.00             | 210.40 |
| M INSULATOR-DASH PANEL ?               |        | 1.00              | 114.00     | 20.00             | 91.20  |
| M PAD-HOOD INSULATING ?                |        | 1.00              | 119.00     | 20.00             | 95.20  |
| M LATCH ASSY-HOOD ?                    |        | 1.00              | 101.00     | 20.00             | 80.80  |
| M GUARD ASSY-FRONT WHEEL, RH ?         |        | 1.00              | 56.00      | 20.00             | 44.80  |
| M ORNAMENT-KIA NO.115 ?                |        | 1.00              | 32.00      | 20.00             | 25.60  |
| M COVER-FR BUMPER UPR ?                |        | 1.00              | 476.00     | 20.00             | 380.80 |
| M SKID PLATE-FR BUMPER ?               |        | 1.00              | 55.00      | 20.00             | 44.00  |
| M LIP ASSY-FRONT BUMPER ?              |        | 1.00              | 32.00      | 20.00             | 25.60  |
| M GRILLE ASSY-RADIATOR ?               |        | 1.00              | 324.00     | 20.00             | 259.20 |
| M COVER-RADIATOR GRILLE UPR ?          |        | 1.00              | 46.00      | 20.00             | 36.80  |
| M MOULDING-FRONT BUMPER A/INTAKE ?     |        | 1.00              | 61.00      | 20.00             | 48.80  |
| M STRIP-FR BUMPER ?                    |        | 1.00              | 27.00      | 20.00             | 21.60  |
| M CAP-FRONT HOOK ?                     |        | 1.00              | 5.00       | 20.00             | 4.00   |
| M COVER-FR BUMPER, LWR ?               |        | 1.00              | 367.00     | 20.00             | 293.60 |
| M GRILLE-FRONT BUMPER ?                |        | 1.00              | 96.00      | 20.00             | 76.80  |
| M ABSORBER-FRONT BUMPER ENERGY ?       |        | 1.00              | 98.00      | 20.00             | 78.40  |
| M AIR DUCT-FR BUMPER, RH ?             |        | 1.00              | 38.00      | 20.00             | 30.40  |
| M COVER-FR BUMPER FOG LAMP, RH ?       |        | 1.00              | 64.00      | 20.00             | 51.20  |
| M LAMP ASSY-FRONT FOG, RH ?            |        | 1.00              | 234.00     | 20.00             | 187.20 |
| M BRACKET-FR BUMPER SIDE, LH ?         |        | 1.00              | 13.00      | 20.00             | 10.40  |
| M BRACKET-FR BUMPER SIDE, RH ?         |        | 1.00              | 13.00      | 20.00             | 10.40  |
| M STIFFNER-FR BPR LWR ?                |        | 1.00              | 123.00     | 20.00             | 98.40  |
| M GARNISH ASSY-FNDR SIDE, RH ?         |        | 1.00              | 45.00      | 20.00             | 36.00  |
| SURVEYOR NAME: <u>RASUL - Hooodary</u> |        |                   |            |                   |        |
| SURVEYOR SIGNATURE: <u>[Signature]</u> |        |                   |            |                   |        |
| DATE: <u>26/10/2020 @ 1015</u>         |        |                   |            |                   |        |
| REMARKS: <u>2 days</u>                 |        |                   |            |                   |        |
| EXCESS: <u>THA / REPAIR</u>            |        |                   |            |                   |        |
| Repay before part                      |        |                   |            |                   |        |
| 7% GST on                              |        |                   |            |                   |        |
| Total Payable                          |        |                   |            |                   |        |

LKK Auto Consultants hence notify the Repairer of the following:

- To survey before repair painting
- To display damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on "V" basis
- No illegal or illegal parts
- Supplemental parts are subject to approval
- Is subject to final approval

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing the rubber seal or other repair requiring the removal of the windscreen.

GIA / PK

Est. Details

days

Res.: Yes or No

Page 2 of 2