



CYCLE & CARRIAGE

Exceptional Journeys

INSURANCE CO. : **AIG**

Supplementary Parts For Registration No.:

SKT 1394 X

Materials


	<u>Cost (\$)</u>
1 Clip-mounting (x3) nec ✓	9.00
2 Cover assy-Cowl Top cra ✓	166.00
3 Clips (x10) nec ✓	20.00
4 Guard assy-front wheel, LH cra ✓	56.00
5 Moulding-windshield glass nec ✓	52.00
6 Pad-windshield glass (x12) nec ✓	24.00
7 Stopper-RR window glass (x2) nec ✓	8.00
8 Retainer (x4) nec ✓	4.00
9 Coolant (4L) nec ✓	26.00
Total	365.00
Less 20% discount	73.00
Total after discount	292.00

Labour

	<u>Cost (\$)</u>
1 Replace front end carrier, RH front fender upper apron, repair LH front fender and all other affected areas	1,400.00 ✓
2 Remove & reinstall front windscreen glass to facilitate repair, and conduct water leak test	240.00 ✓
3 Supply front windscreen glass sealant	80.00 ✓
4 Respray on RH front fender upper apron	350.00 ✓
Total Labour	2,070.00
Taxable amount	2,362.00
7% GST	165.34
Grand total	\$ 2,527.34

Thank You.

Yours faithfully,


LOI AI TING
Senior Officer - Admin
KIA SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240