



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 19/7014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHNG SAY TIONG Reg No/Reg Date SMH448X / 09/01/201 Date In/Mileage 21/10/2020/ 0 Chassis No MMBSTA13AJH004442 Engine No 3A92UHK1692 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No		
KAX00008	Credit	22/10/2020/ 10:38	QUK	282 / Kevin Leong	58728		
Description of Goods / Services				Qty	Unit Price	Disc%	Amount
E PNT88000	✓	✓	✓	✓	✓	2250.3150.00	
REPLACE FRT BUMPER, BONNET, SUPPORT, BOTH FRT FENDER & AFFECTED AREA							
REPAIR ON FRT RH BODY CHASSIS ✓?							2100.
E PNT98000	✓	✓	✓	✓	✓	2450.00	
PAINT WORK FRT BUMPER, BONNET, SUPPORT, FRT RH BODY CHASSIS, BODY KIT & BOTH FRT FENDER ✓							
E PNT88000	✓	✓	✓	✓	✓	120.00	
TO REMOVE & INSTALL RADIATOR, CONDENSER FOR FACILITATE REPAIR							
A 11900199	nn	✗	pl	?		450.00	
TO REMOVE & INSTALL ENGINE FOR FACILITATE REPAIR							
A 55900099	✓	✓	✓	✓	✓	80.00	
TO TOP UP AIRCON GAS							
M SUNDRY	✓	✓	✓	✓	✓	120.00	
PERFORM RUST PREVENTION							
A 54900099	✓	✓	✓	✓	✓	30.00	
CHECK WIRING & CHASSIS ELECTRICAL SYSTEM							
A 10028901	✓	✓	✓	✓	✓	120.00	
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST							
M SUNDRY	✓	mis	✓			50.00	
TO SUPPLY FRONT NUMBER PLATE WITH FRAME							
M SUNDRY	✓	20.	✓			50.00	
SUNDRIES							
M HEADLAMP ASSY,LH			1.00	660.00	23.00	can 508.20	
M HEADLAMP ASSY,RH			1.00	660.00	23.00	can 508.20	
M LAMP ASSY,FOG,FR LH			1.00	303.00	23.00	nn ? 233.31	
M HORN			1.00	79.00	23.00	nn ? 60.83	
M TANK,WINDSHIELD WASHER			1.00	74.00	23.00	? 56.98	
M MOTOR,WINDSHIELD WASHER			1.00	30.00	23.00	? 23.10	
M CONDENSER ASSY,A/C REFRIGE			1.00	758.00	23.00	bt 583.66	
M PIPE,A/C CONDENSER OUTLET			1.00	305.00	23.00	? 234.85	
M FACE,FR BUMPER			1.00	703.00	23.00	de 541.31	
M COVER,HEADLAMP SUPT PANEL			1.00	62.00	23.00	can 47.74	

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
 any additional parts or labour which may be required after repair work has commenced.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 1977014696

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name /CHNG SAY TIONG Reg No/Reg Date SMH448X / 09/01/201 Date In/Mileage 21/10/2020/ 0 Chassis No MMBSTA13AJH004442 Engine No 3A92UHK1692 Make/Model MIT/18MY ATTRAGE 1.2 CVT Colour/Trim P01 RED METALLIC / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/10/2020/ 10:38	QUK	282 / Kevin Leong	58728

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
M GRILLE,FR UNDER	1.00	165.00	23.00	127.05
M AIR DAM,SIDE,FR RH	1.00	18.00	23.00	13.86
M AIR DAM,SIDE,FR LH	1.00	18.00	23.00	13.86
M GARNISH,FR BUMPER,LH	1.00	127.00	23.00	97.79
M GARNISH,FR BUMPER,RH	1.00	127.00	23.00	97.79
M BRACKET,FR BUMPER,RH	1.00	13.00	23.00	10.01
M BRACKET,FR BUMPER,LH	1.00	13.00	23.00	10.01
M GRILLE,RADIATOR	1.00	554.00	23.00	426.58
M HOOD	1.00	734.00	23.00	565.18
M INSULATOR,HOOD	1.00	177.00	23.00	136.29
M HINGE,HOOD,LH	1.00	56.00	23.00	43.12
M HINGE,HOOD,RH	1.00	56.00	23.00	43.12
M LATCH,HOOD	1.00	69.00	23.00	53.13
M FENDER,FR LH	1.00	497.00	23.00	382.69
M FENDER,FR RH	1.00	497.00	23.00	382.69
M PANEL,HEADLAMP SUPPORT,UPR	1.00	65.00	23.00	50.05
M PANEL ASSY,FR END	1.00	1055.00	23.00	812.35
M COVER,ENG ROOM UNDER,FR	1.00	99.00	23.00	76.23
M SHIELD,FR WHEELHOUSE,RH	1.00	98.00	23.00	75.46
M RADIATOR ASSY	1.00	967.00	23.00	744.59
M PANEL,AIR GUIDE	1.00	112.00	23.00	86.24
M SHROUD,COOLING FAN	1.00	130.00	23.00	100.10
M MOTOR,COOLING FAN	1.00	479.00	23.00	368.83
M FAN,COOLING,LH	1.00	77.00	23.00	59.29
M TANK ASSY,RADIATOR COND	1.00	42.00	23.00	32.34
M ATTRAGE BODYKITS	1.00	1643.00	00.00	1643.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tan Jhi 97495744SURVEYOR SIGNATURE: [Signature]DATE: 22/10/2020 5:15pm

REMARKS: Not Authorise, Resurvey before paint
EX: to be advise, tan jhi 97495744
of days

Confirm & accepted by

Nett 15,869.83
 7% GST on 15869.83 1110.89
Total Payable 16,980.72

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash or by cheque. You must also agree to pay full amount for renewal of the windscreen in case of damage. The rubber seal or other repair materials are not included.