

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 23 / 10 / 2020

ESTIMATE COSTS OF REPAIR

Ms Koh Mui Gek, Susan

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SGB 5182 G - Toyota Altis 1.6

Accident date : 22 / 10 / 2020

*Not Authorized
L/Lip &
Penny After Paint
6 days*

Quantity	Descriptions	Amount (S\$)
----------	--------------	----------------

1	1 pc	rear windscreen glass molding	\$	80.00	✓
2	1 pc	boot lid	\$	595.58	X
3	1 pc	boot lid 'Toyota' logo	\$	52.50	X
4	1 pc	boot lid 'COROLLA' emblem	\$	42.35	X
5	1 pc	boot lid 'ALTIS' emblem	\$	44.17	X
6	1 pc	boot lid '1.6' emblem	\$	32.81	X
7	1 pc	boot lid "VVT-I" emblem	\$	32.81	X
8	1 pc	rear weather strip	\$	175.35	50% ✓
9	1 pc	o/s tail lamp	\$	360.98	✓
10	1 pc	o/s tail lamp lower panel	\$	76.86	✓
11	1 pc	rear bumper	\$	459.75	✓
12	2 pcs	rear bumper side retainer 1 @ 66.76	\$	133.52	✓
13	2 pcs	rear bumper bracket 1 @ 82.81	\$	165.62	X
14	2 pcs	rear bumper stopper 1 @ 29.60	\$	59.20	X
15	11 pcs	rear bumper clip 1 @ 3.50	\$	38.50	✓
16	1 pc	rear bumper lower lip	\$	985.50	✓
17	1 pc	rear end panel	\$	552.30	✓
18	1 pc	rear end panel inner garnish	\$	185.29	X
19	1 pc	rear exhaust box	\$	787.12	X
20	1 pc	o/s rear shock absorber	\$	114.88	X
21	1 pc	o/s rear hup bearing	\$	462.00	X
22	1 pc	rear axle beam	\$	1,488.71	X
23	1 pc	o/s rear fender	\$	1,125.80	✓
24	1 pc	o/s rear fender inner garnish	\$	168.20	X
25	1 pc	o/s rear fender outer garnish	\$	57.61	✓
26	1 pc	o/s rear door	\$	1,052.10	X
27	1 pc	o/s rear door protector	\$	85.90	X
		Balance C/FD	\$	9,415.41	

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Balance B/FD (SGB 5182 G)

\$ 9,415.41

28 1 pc rear floor panel

\$ 12 702.90 X

\$ 10,118.31

Less 25 %

\$ 2,529.58

\$ 7,588.73

29 1 pc rear windscreen glass inner seal

\$ 60.00 sn 3012

30 1 pc rear windscreen glass inner gum

\$ 60.00 sn 4052

31 1 set rear bumper reverse sensor

\$ 350.00 sn 20012

32 1 pc rear panel seal

\$ 250.00 sn 3052

33 1 pc rear no plate

\$ 100.00 sn X

\$ 8,408.73

Labour charges

\$ 1,800.00 1100

To putty and spray painting

\$ 1,500.00 800

To check wiring

\$ 120.00 20

To re-seal anti rust

\$ 180.00 60

Remove and refix rear reverse sensor

\$ 100.00 50

Remove and refix rear exhaust box

\$ 120.00 60

Remove and refix rear windscreen glass

\$ 220.00 120

Remove and refix rear cushion seat,carpet,garnish & etc.

\$ 350.00 120

\$ 12,798.73

Plus 7% GST

\$ 895.91

Sub_Total

\$ 13,694.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: