

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

Date : 23 / 10 / 2020

ESTIMATE COSTS OF REPAIR

Ms Koh Mui Gek, Susan

C/o 160 Sin Ming Drive

05-09 Sin Ming Auto City

Singapore 575722

Dear Sir / Madam ,

Vehicle no. : SGB 5182 G - Toyota Altis 1.6

Accident date : 22 / 10 / 2020

*Not Authorized
U/Sup & 1600k Max
Penny After Pain
5 days*

Quantity	Descriptions	Amount (S\$)
1	1 pc rear windscreen glass molding	\$ 80.00 ✓
2	1 pc boot lid	\$ 595.58 X
3	1 pc boot lid 'Toyota' logo	\$ 52.50 X
4	1 pc boot lid 'COROLLA' emblem	\$ 42.35 X
5	1 pc boot lid 'ALTIS' emblem	\$ 44.17 X
6	1 pc boot lid '1.6' emblem	\$ 32.81 X
7	1 pc boot lid 'VVT-I' emblem	\$ 32.81 X
8	1 pc rear weather strip	\$ 175.35 ✓
9	1 pc o/s tail lamp	\$ 360.98 ✓
10	1 pc o/s tail lamp lower panel	\$ 76.86 ✓
11	1 pc rear bumper	\$ 459.75 ✓
12	2 pcs rear bumper side retainer 1 @ 66.76	\$ 133.52 ✓
13	2 pcs rear bumper bracket 1 @ 82.81	\$ 165.62 X
14	2 pcs rear bumper stopper 1 @ 29.60	\$ 59.20 X
15	11 pcs rear bumper clip 1 @ 3.50	\$ 38.50 ✓
16	1 pc rear bumper lower lip	\$ 985.50 ✓
17	1 pc rear end panel	\$ 552.30 ✓
18	1 pc rear end panel inner garnish	\$ 185.29 X
19	1 pc rear exhaust box	\$ 787.12 X
20	1 pc o/s rear shock absorber	\$ 114.88 X
21	1 pc o/s rear hup bearing	\$ 462.00 X
22	1 pc rear axle beam	\$ 1,488.71 X
23	1 pc o/s rear fender	\$ 1,125.80 ✓
24	1 pc o/s rear fender inner garnish	\$ 168.20 X
25	1 pc o/s rear fender outer garnish	\$ 57.61 ✓
26	1 pc o/s rear door	\$ 1,052.10 X
27	1 pc o/s rear door protector	\$ 85.90 X
	Balance C/D	\$ 9,415.41

H C AUTO PTE LTD

160 Sin Ming Drive #05-09 Sin Ming Auto City Singapore 575722

Tel : 6457 0678 Fax : 6457 8287

Co. and GST Reg. No. : 200820153N

		Balance B/FD (SGB 5182 G)	\$ 9,415.41
28	1 pc	rear floor panel	\$ R 702.90 X
		Less 25 %	\$ 10,118.31
			\$ 2,529.58
			\$ 7,588.73
29	1 pc	rear windscreen glass inner seal	\$ M 60.00 sn 301N
30	1 pc	rear windscreen glass inner gum	\$ M 60.00 sn 405N
31	1 set	rear bumper reverse sensor	\$ M 350.00 sn 2001N
32	1 pc	rear panel seal	\$ M 250.00 sn 305N
33	1 pc	rear no plate	\$ M 100.00 sn X
			\$ 8,408.73
		Labour charges	\$ 1,800.00 1100/
		To putty and spray painting	\$ 1,500.00 800/
		To check wiring	\$ 120.00 20/
		To re-seal anti rust	\$ 180.00 60/
		Remove and refix rear reverse sensor	\$ 100.00 50/
		Remove and refix rear exhaust box	\$ 120.00 60/
		Remove and refix rear windscreen glass	\$ 220.00 120/
		Remove and refix rear cushion seat,carpet,garnish & etc.	\$ 350.00 120/
		Plus 7% GST	\$ 12,798.73
		Sub_Total	\$ 895.91
			\$ 13,694.64

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer:
Signature:
Date: