

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

(SUPPLEMENTARY)

INSURER: Lonpac Insurance Bhd (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (Own Damage)	Ref. No:	20/LP/OD-410 (10)
Policy No:	Z20VC05005789	Date of Loss:	11/10/2020
Vehicle Reg. No.:	YQ342C	Driveable?	
Driver Age/Info:	28 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	YES	Third Party Involved?	YES
Insured/Claimant:	BSN TECH ENGINEERING PTE LTD		
Driver:	NATARAJAN PALANIRAJ		
Make/Model:	mitsubishi canter, 3.0 D FEA01BR2SDEB (CBU) (M)	Vehicle Reg. Date:	19/03/2019
Vehicle Colour:	White		
Engine No:	4P10D61955	Chassis No:	FEB21EA30013
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	14		
Present Location:	SME MOTOR PTE LTD (KAKI BUKIT)		

COST OF CLAIMS

	Amount
Parts	7,917.75
Miscellaneous Items	1,200.00
Labour	250.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	9,367.75
+ GST 7.00% (S\$)	655.74
Nett Amount (S\$)	10,023.49
+ Previous Estimates (S\$)	52,148.64
Claim Total (S\$)	62,172.13

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS

Reference

Part Source: (Last Synchronised: 25 Nov 2020)
 Parts: N/A MITSUBISHI CANTER 3.0 D FEA01BR2SDEB (CBU) (M) (Model not available in database)
 Labour: Repairer's (Price-denominated Standard List)
 Print Code: SME Motor Pte Ltd/YQ342C/25/11/2020 10:45
 Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
 Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT RH DRIVER SEAT / BT/CR4	0.00	0.00	*2,200.00 F ✓
2	1		*RH DOOR PILLAR INNER TRIM FRT / BR	0.00	0.00	*230.00 F ✓
3	1		*RH DOOR PILLAR INNER TRIM REAR / BR	0.00	0.00	*295.00 F ✓
4	1		*CABIN REAR TRIM / BR	0.00	0.00	*350.00 F ✓
5	1		*CARBON CANNISTER / BT	0.00	0.00	*380.00 F ✓
6	1		*CABIN INSULATOR LOWER / TN	0.00	0.00	*290.00 F ✓
7	2		*FUEL INJECTOR / BR	0.00	0.00	*360.00 F ✓
8	1		*EXHAUST MANIFOLD / BR	0.00	0.00	*750.00 F ✓
9	1		*ENGINE TOP COVER / BR	0.00	0.00	*320.00 F ✓
10	2		*ENGINE MOUNTING / TN	0.00	0.00	*240.00 F ✓
11	1		*GEARBOX MOUNTING / TN	0.00	0.00	*50.00 F ✓
12	1		*RADIATOR / Twisted	0.00	0.00	*850.00 F ✓
13	1		*RADIATOR COWLING / BR	0.00	0.00	*150.00 F ✓
14	1		*REAR CABIN CROSSMEMBER / BR (Washed)	0.00	0.00	*420.00 F ✓

F=Franchise part.

Sub Total (\$\$) 6,885.00 6885
 + Margin on L,N Items 15.00% (\$\$) 1,032.75
 Total Parts (\$\$) 7,917.75 *15%

SME Motor Pte Ltd/YQ342C/25/11/2020 10:45. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS

7917.75

L/S - 6334.20

Estimates on Miscellaneous Items

No Qty Particulars

Amount

Miscellaneous Items

1	1	REAR TAIL BOARD WOODEN BOARD AND LOWER WOODEN HOLDER ASSY	BT (metal)	1,200.00
---	---	---	------------	----------

Sub Total (S\$) 1,200.00

Estimates on Labour

No Particulars

Lab.Type

Amount

Labour Items

1	REPLACE ENGINE MOUNTINGS, FUEL INJECTORS AND EXHAUST MANIFOLD	New	100	250.00
---	---	-----	-----	--------

Gross Labour Cost (S\$) 250.00

SME Motor Pte Ltd/YQ342C/25/11/2020 10:45. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >