

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD202T

AAD2010-081

*Not Notarised**11/10/20*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

Date of Registration :

21 OCT 2020

SHD202T

VF1ABL15AUC282365

RENAULT

LATITUDE

19/10/2020

TOKIO

02/10/2015

	PART
1	1 BUMPER COVER REAR
2	1 BUMPER LOWER REAR
3	1 BUMPER BRACKET CTR REAR
4	1 BUMPER BRACKET SIDE RH REAR
5	1 BUMPER RETAINER RH REAR
7	1 BUMPER BRACKET SIDE LH REAR
8	1 BUMPER RETAINER LH REAR
10	1 BUMPER BEAM REAR
11	1 BUMPER BEAM BRACKET LH REAR
12	1 BUMPER BEAM BRACKET RH REAR
13	1 BUMPER REFLECTOR RH
14	1 OUTER PANEL REAR (End Panel)
15	1 OUTER PANEL REAR (End Panel)TRIM
16	1 BOOT REAR
17	1 BOOT BADGE 'RENAULT'
18	1 BOOT BADGE
19	1 TAILLAMP RH

	LIST	
\$	Bu	561.70 ✓
\$	Adl/ha	411.90 ✓
\$	Sm	98.10 X
\$	Sm	82.10 X
\$	Sm	59.80 X
\$	Sm	80.80 X
\$	Sm	54.20 X
\$	Bu	547.80 ✓
\$	Na	114.50
\$	Na	114.50
\$	Sm	16.60
\$	Na	745.80
\$	Sm	404.56
\$	Na	1,677.20
\$	na	82.40
\$	na	95.80
\$	Sm	401.40
\$		5,549.16
10% \$		554.92
\$		4,994.24

Special Net

1	1SET PARKING AID
2	1SET REAR BUMPER CLIP
3	1SET BUMPER BRACKET CTR CLIP
4	1SET BUMPER BRACKET SIDE CLIP RH RR
5	1SET BUMPER RETAINER RH CLIP RR
6	1SET BUMPER BRACKET SIDE CLIP LH RR

\$	Sm	700.00 X
\$	Na	66.00 ✓
\$	na	33.00 X
\$	na	10.00 X
\$	na	20.00 X
\$	na	10.00 X

Trans-cab Auto Services Pte Ltd

AAD2010-081

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD202T

7 1SET BUMPER RETAINER CLIP LH RR	\$	na	20.00	X
8 1SET BUMPER LOWER REAR RIVET	\$	na	22.00	X
9 1SET BUMPER LOWER REAR CLIP	\$	na	66.00	✓
10 1 REAR NUMBER PLATE WITH HOLDER	\$	Ph	120.00	X
14 1 REAR BOOT STICKER 'Trans-cab'	\$	na	80.00	X
15 1 REAR BOOT STICKER '6555-3333'	\$	na	80.00	X
TOTAL	\$		428.00	
TOTAL PARTS	\$		5,422.24	

LABOUR

Putty And Spray Painting Of The Affected Portion.	\$		3,000.00	220/
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$		3,000.00	200/
To Rust-Proofing Of The Affected Areas.	\$	na	170.00	X
To reinstall rear bumper parking sensor.	\$		170.00	60/
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	na	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	✓	170.00	X
To check steering geometry and computer wheel alignment	\$	✓	220.00	X
To Check Electrical Lighting Concerned.	\$	✓	170.00	X
TOTAL	\$		7,070.00	

Over All Total	\$	17,486.49
-----------------------	-----------	------------------

AAD2010-081

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD202T

(LUMP SUM)
Repair Days

18 DAYS
2 day

For Official Use

Prepared By : _____
(Accident Dept)

Verify By : _____
(Accident Workshop)

Checked By : _____
(Finance Dept)

LKK A to Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____