

Surveyor : TAUFIKH LKK
 Claim : AIG OD
 DOA : 21.10.2020
 Emailed : 23.11.2020, 10.30am
 Date Survey : 22.10.2020

VEHICLE NO : SGT 1686 B
 MODEL : MIT ATTRAGE 1.2
 WIP : 58759

Material	:	\$	<u>5,092.60</u>
Labour	:	\$	<u>6,760.00</u>
Sub-Total	:	\$	<u>11,852.60</u>
	:		<u>-</u>
Less Excess	:	\$	<u>-</u>
Total	:	\$	<u>11,852.60</u>
GST 7%	:	\$	<u>829.68</u>
Grand Total	:	\$	<u>12,682.28</u>
Finalise By/Date	:	<u>LOI / 23/11/2020</u>	

☒ REVERT BACK WITHIN 7 DAYS,
 OTHERWISE WILL PROCEED WITH INVOICING

☐ SURVEYOR'S REPORT REQUIRED

☐ REPAIR TOOK 0 WORKING DAYS + 0 Days (0) Weekends
 + 0 Days (0) Public Holiday
 TOTAL DAYS REPAIR TOOK = 0

☐ TP claim _____

☐ Claim GIA / LTA fee _____

☐ Claim Loss of ☐ Use / ☐ Rental

☐ Claim Medical Fee / Others _____

☐ Third Party Report - _____

PRO-FORMA INVOICE

Co Reg No : 197701469G

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 26/10/2020	<table> <tr> <td>Cust No/Name</td><td>KCV11880/AMMAR ABDUL HADI BIN YUSOP</td></tr> <tr> <td>Reg No/Reg Date</td><td>SGT1686B / 16/08/2019</td></tr> <tr> <td>Date In/Mileage</td><td>26/10/2020/ 11666</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AKH002289 /DC17P(F)</td></tr> <tr> <td>Engine No</td><td>3A92UHT9449</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>W05 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV11880/AMMAR ABDUL HADI BIN YUSOP	Reg No/Reg Date	SGT1686B / 16/08/2019	Date In/Mileage	26/10/2020/ 11666	Chassis/Package	MMBSTA13AKH002289 /DC17P(F)	Engine No	3A92UHT9449	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	W05 WHITE PEARL / BK BLACK
Cust No/Name	KCV11880/AMMAR ABDUL HADI BIN YUSOP														
Reg No/Reg Date	SGT1686B / 16/08/2019														
Date In/Mileage	26/10/2020/ 11666														
Chassis/Package	MMBSTA13AKH002289 /DC17P(F)														
Engine No	3A92UHT9449														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	W05 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	20/11/2020/ 14:15	BLK	260 / AiTing	58759			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE DAMAGED PARTS, REPLACE REAR BUMPER, BOOT, RH REAR FENDER, REAR END PANEL, RH REAR TAIL LAMP PANEL, BODY KIT, REPAIR LH REAR FENDER, AND ALL OTHER AFFECTED AREAS, ADJUST AND ALIGN BODY GAPS ALIGNMENT TO THE SAME								✓ 2700.00
E PNT98000 RESPRAY ON REAR BUMPER, BOOT, BODY KIT, REAR END PANEL, RH REAR TAIL LAMP PANEL, FLOOR PANEL, BOTH REAR FENDER, AND ALL OTHER AFFECTED AREAS TO THE SAME								✓ 2800.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST TO FACILITATE REPAIR								✓ 100.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPONENTS TO FACILITATE REPAIR								✓ 120.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR, AND CONDUCT WATER LEAK TEST								✓ 240.00
M SUNDRY APPLY REAR WINDSCREEN GLASS SEALANT								✓ 80.00
E PNT88000 REMOVE & INSTALL REAR SEAT COMPARTMENTS TO FACILITATE REPAIR								✓ 120.00
E PNT88000 TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL								✓ 100.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								✓ 80.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS								✓ 80.00
M SUNDRY SUPPLY C & C EMBLEM								✓ 40.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								✓ 30.00
A 10028901 CONDUCT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST AND CLEAR TROUBLE CODE								✓ 120.00
M SUNDRY								✓ 20.00

PRO-FORMA INVOICE

Co Reg No : 1977014696

THIS IS NOT AN OFFICIAL TAX INVOICE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info														
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892 26/10/2020	<table> <tr> <td>Cust No/Name</td><td>KCV11880/AMMAR ABDUL HADI BIN YUSOP</td></tr> <tr> <td>Reg No/Reg Date</td><td>SGT1686B / 16/08/2019</td></tr> <tr> <td>Date In/Mileage</td><td>26/10/2020/ 11666</td></tr> <tr> <td>Chassis/Package</td><td>MMBSTA13AKH002289 /DC17P(F)</td></tr> <tr> <td>Engine No</td><td>3A92UHT9449</td></tr> <tr> <td>Make/Model</td><td>MIT/19MY ATTRAGE 1.2 CVT</td></tr> <tr> <td>Colour/Trim</td><td>W05 WHITE PEARL / BK BLACK</td></tr> </table>	Cust No/Name	KCV11880/AMMAR ABDUL HADI BIN YUSOP	Reg No/Reg Date	SGT1686B / 16/08/2019	Date In/Mileage	26/10/2020/ 11666	Chassis/Package	MMBSTA13AKH002289 /DC17P(F)	Engine No	3A92UHT9449	Make/Model	MIT/19MY ATTRAGE 1.2 CVT	Colour/Trim	W05 WHITE PEARL / BK BLACK
Cust No/Name	KCV11880/AMMAR ABDUL HADI BIN YUSOP														
Reg No/Reg Date	SGT1686B / 16/08/2019														
Date In/Mileage	26/10/2020/ 11666														
Chassis/Package	MMBSTA13AKH002289 /DC17P(F)														
Engine No	3A92UHT9449														
Make/Model	MIT/19MY ATTRAGE 1.2 CVT														
Colour/Trim	W05 WHITE PEARL / BK BLACK														

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	20/11/2020/ 14:15	BLK	260 / AiTing	58759

Description of Goods / Services	Qty	Unit Price	Disc%	Amount
SUNDRIES				
S SPECIALISTJOB				✓ 50.00
SUPPLY & REPLACE REAR NUMBER PLATE WITH FRAME				
S SPECIALISTJOB				✓ 80.00
APPLICATION TO BREAK REAR OPC PLATE AND RESEAL AT VICOM				
X LAMP ASSY,COMB,RR RH	1.00	✓ 335.00	23.00	257.95
X BRACKET,RR BUMPER,RH	1.00	✓ 28.00	23.00	21.56
X FACE,RR BUMPER	1.00	✓ 748.00	23.00	575.96
X PANEL,QTR,OTR RH	1.00	✓ 763.00	23.00	587.51
X PANEL,RR COMB LAMP HSG,RH	1.00	✓ 60.00	23.00	46.20
X PANEL,RR END	1.00	✓ 425.00	23.00	327.25
X STOPPER,WINDSHIELD GLASS	2.00	✓ 3.00	23.00	4.62
X SPACER,RR WINDOW	3.00	✓ 9.00	23.00	20.79
X WEATHERSTRIP,TRUNK LID	1.00	✓ 157.00	23.00	120.89
X PANEL,TRUNK LID	1.00	✓ 791.00	23.00	609.07
X LATCH,TRUNK LID	1.00	✓ 218.00	23.00	167.86
X GARNISH,RR END PANEL	1.00	✓ 336.00	23.00	258.72
X MARK,THREE-DIA	1.00	✓ 69.00	23.00	53.13
X MARK,ATTRAGE	1.00	✓ 21.00	23.00	16.17
X BOARD,TRUNK ROOM FLOOR	1.00	✓ 195.00	23.00	150.15
X CARPET,TRUNK ROOM	1.00	✓ 170.00	23.00	130.90
X BODY KIT, ATTRAGE	1.00	✓ 1643.00	00.00	1643.00
X BUZZER,KEYLESS OPERATIO,RR	1.00	91.00	23.00	cra 70.07
X COVER,RR VENTILATOR	1.00	40.00	23.00	cra ✓ 30.80
Z TEXT				
AIG OD CLAIM.				
DOA : 21.10.20				
SURVEYOR : TAUFIKH LKK 22.10.20				
POLICY NO : 1900149406				
Guarantee Your Warranty, Maintain with Cycle & Carriage!				

Parts	5,092.60	Nett	11,852.60
Labour	6,330.00	7% GST on 11852.60	829.68
Standard Menu	0.00		
Specialist Job	130.00	Total Payable	12,682.28
Diagnostics Job	0.00		
Sundry/Others	300.00		
Total(w/o GST)	11,852.60		

INSURANCE CO.: **AIG**

Supplementary Parts For Registration No.: **SGT 1686 B**


<u>Materials</u>		<u>Cost (\$)</u>
1	Buzzer, keyless operatio, RR	91.00
2	Cover, RR ventilator	40.00

Total		131.00
Less 23% discount		30.13
Total after discount		100.87
7% GST		7.06

Grand total		<u>\$ 107.93</u>

Thank You.

Yours faithfully



LOI AI TING
SENIOR OFFICER - ADMIN
MITSUBISHI SERVICE CENTRE
DID : 6568 4556 / 6568 4501
FAX : 6567 5258 / 6565 1240

WIP: 50151 (ADDITIONAL PARTS)

CAR NO: 5471686B

S/NO	PARTS NAME	? / SUPP	CSA SIGN	PHOTO TAKEN	REMARKS
1	Panel, RR Comb Lamp HSG. RH bf ✓	? / SUPP	2 pages		
2	Latch Trunk Lid bf ✓	? / SUPP			
3	Buzzer CA ✓	? / SUPP			
4	Cover RR Ventilator CA	? / SUPP		22/10/2022	
5		? / SUPP			
6		? / SUPP			
7		? / SUPP			
8		? / SUPP			
9		? / SUPP			
10		? / SUPP			
11		? / SUPP			
12		? / SUPP			
13		? / SUPP			
14		? / SUPP			
15		? / SUPP			
16		? / SUPP			
17		? / SUPP			
18		? / SUPP			
19		? / SUPP			
20		? / SUPP			

MODEL: Affrage
SURVEYOR: Muk-Tan Fik

	DATE	TAKEN BY
PHOTO BEFORE PAINT		
PHOTO AFTER PAINT		
PHOTO OF MOUNT TO CELLETE BENCH		
REMOVE AND INSTALL ENGINE		
REMOVE AND INSTALL DASHBAORD		
REMOVE & INSTALL FUEL TANK		
PHOTO UNDERCARRIAGE PARTS		

2011 16000 ID

After Repair to use

PIOT-3x NOT unit to

Base Is found

to Job Done

All DTCs

Setting	
Item	Information
M.U.T.-3 Version	SEW20011-00
V.C.I. Version	B177
Vehicle Information	A13A 2019MY

2020.11.09

All DTCs

2020.11.09

	System Name	SCC or DVC or Diagnostic database ID	Diagnostic trouble code(s)	Name		Malfunction Condition
	MPI/GDI/DIESEL	KOSS_99880010		No DTCs		
	AT/CVT/A-MT/TC-SST	KOSS_99880010		No DTCs		
	4WS/Electric Power Steering	KOSS_99880010		No DTCs		
	ABS/ASC/ASTC/WSS	KOSS_99880010		No DTCs		
	SRS-AIR BAG	KOSS_99880010		No DTCs		
	Air Conditioner	KOSS_99880010		No DTCs		
	ETACS	KOSS_99880010		No DTCs		
	Meter	KOSS_99880010		No DTCs		
	Steering Angle Sensor	KOSS_99880010		Non-target System		
	KOS/OSS/IMMO/Keyless (with KOS)	KOSS_99880010		No DTCs		