

CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

ESTIMATE

Co Reg No : 197701469G

GST Reg No : MR-8500111-X


Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11880/AMMAR ABDUL HADI BIN YUSOP Reg No/Reg Date SGT1686B / 16/08/201 Date In/Mileage 22/10/2020/ 0 Chassis No MMBSTA13AKH002289 Engine No 3A92UHT9449 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No			
KAX00008	Credit	22/10/2020/ 15:36	QUK	282 / Kevin Leong	58759			
Description of Goods / Services					Qty	Unit Price	Disc%	Amount
E PNT88000 REPLACE ON REAR BUMPER, BOOT, REAR RH FENDER, END PANEL, REAR RH TAIL LAMP PANEL, FLOOR PANEL & BODY KIT REPAIR ON REAR LH FENDER								2700.4050.00
E PNT98000 PAINT WORK ON REAR BUMPER, BOOT, BODY KIT, END PANEL, REAR RH TAIL LAMP PANEL, FLOOR PANEL & BOTH REAR FENDER								2800.00
E PNT88000 REMOVE & INSTALL REAR PARKING ASSIST								100.120.00
E PNT88000 REMOVE & INSTALL REAR BOOT COMPONENTS FOR FACILITATE REPAIR								120.00
E PNT88000 REMOVE & INSTALL REAR WINDSCREEN GLASS TO FACILITATE REPAIR, AND CONDUCT WATER LEAK TEST								240.00
M SUNDRY TO APPLY REAR WINDSCREEN SEALANT								80.00
E PNT88000 REMOVE & INSTALL REAR SEAT COMPARTMENT TO FACILITATE REPAIR								120.00
E PNT88000 TRANSFER REAR BOOT ATTACHMENTS TO NEW PANEL								100.120.00
M SUNDRY PERFORM RUST PREVENTION ON AFFECTED AREAS								80.160.00
M SUNDRY APPLY BODY SEALANT ON AFFECTED AREAS								80.120.00
M SUNDRY SUPPLY C & C EMBLEM								40.00
M SUNDRY TO SUPPLY & REPLACE REAR NUMBER PLATE WITH FRAME								50.00
M SUNDRY APPLICATION TO BREAK FRONT OPC PLATE AND RESEAL								80.00
A 54900099 CHECK WIRING & CHASSIS ELECTRICAL SYSTEM								30.00
A 10028901								120.00

Confirm & accepted by

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
after work has started and needed for repairs or replacement. However, should this occur, we would advise you to pay for the
deposit of 50% of the above estimate is payable before commencement of work. You must also agree to the above terms and conditions.



CYCLE & CARRIAGE

CYCLE & CARRIAGE AUTOMOTIVE PTE LIMITED

PANDAN GARDENS CUSTOMER SERVICE CENTRE

209 Pandan Gardens Singapore 609339 Tel: 65684555 Fax: 65691056

MITSUBISHI
MOTORS

Co Reg No : 197701469G

ESTIMATE

GST Reg No : MR-8500111-X

Invoice Name & Address	Owner Name & Vehicle Info
AIG Asia Pacific Insurance Pte. Ltd. MOTOR CLAIM DEPT 78 SHENTON WAY #08-16 AIG BUILDING SINGAPORE 079120 Contact No 6419 1892	Cust No/Name KCV11880/AMMAR ABDUL HADI BIN YUSOP Reg No/Reg Date SGT1686B / 16/08/201 Date In/Mileage 22/10/2020/ 0 Chassis No MMBSTA13AKH002289 Engine No 3A92UHT9449 Make/Model MIT/19MY ATTRAGE 1.2 CVT Colour/Trim W05 WHITE PEARL / BK BLACK

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
KAX00008	Credit	22/10/2020/ 15:36	QUK	282 / Kevin Leong	58759
Description of Goods / Services		Qty	Unit Price	Disc%	Amount
TO CARRY OUT DIAGNOSTIC CHECK USING HI-SCAN PRO TEST USING HI-SCAN PRO TEST					
M SUNDRY					20. 50.00
SUNDRIES					
M SUNDRY					Xnn? 80.00
TO APPLY ANTI-CORROSION					
M LAMP ASSY, COMB, RR RH		1.00	335.00	23.00	257.95
M LAMP ASSY, COMB, RR LH		1.00	335.00	23.00	Xnn? 257.95
M LAMP ASSY, LICENSE PLATE		2.00	51.00	23.00	X 78.54
M BRACKET, RR BUMPER, LH		1.00	28.00	23.00	Xnn? 21.56
M BRACKET, RR BUMPER, RH		1.00	28.00	23.00	de 21.56
M FACE, RR BUMPER		1.00	748.00	23.00	de 575.96
M PANEL, QTR, QTR RH		1.00	763.00	23.00	bu 587.51
M PANEL, RR COMB LAMP HSG, RH		1.00	60.00	23.00	cr 46.20
M FLOOR, RR		1.00	956.00	23.00	Xnn? 736.12
M PANEL, RR END		1.00	425.00	23.00	bt 327.25
M GLASS, RR WINDOW		1.00	544.00	23.00	Xnn? 418.88
M STOPPER, WINDSHIELD GLASS		2.00	3.00	23.00	ner 4.62
M SPACER, RR WINDOW		3.00	9.00	23.00	ner 20.79
M WEATHERSTRIP, TRUNK LID		1.00	157.00	23.00	ret 120.89
M PANEL, TRUNK LID		1.00	791.00	23.00	bt 609.07
M HINGE, TRUNK LID, LH		1.00	203.00	23.00	Xnn? 156.31
M HINGE, TRUNK LID, RH		1.00	203.00	23.00	Xnn? 156.31
M STRIKER, TRUNK LID LATCH		1.00	20.00	23.00	Xnn? 15.40
M LATCH, TRUNK LID		1.00	218.00	23.00	de 167.86
M SHIELD, RR WHEELHOUSE, RH		1.00	40.00	23.00	de 30.80
M GARNISH, RR END PANEL		1.00	336.00	23.00	de 258.72
M MARK, THREE-DIA		1.00	69.00	23.00	ner 53.13
M MARK, ATTRAGE		1.00	21.00	23.00	ner 16.17
M TRIM, RR END		1.00	66.00	23.00	Xnn? 50.82
M BOARD, TRUNK ROOM FLOOR		1.00	195.00	23.00	an 150.15
M CARPET, TRUNK ROOM		1.00	170.00	23.00	de 130.90
M ATTRAGE BODYKITS		1.00	1643.00	20.00	an 1314.40

Estimate

- LKK Auto Consultants hence notify the Repairer of the following:
- To resurvey before/after spray painting
 - To display damaged part(s) during resurvey
 - Parts prices are subject to confirmation
 - Third party survey is on a "Without Prejudice" basis
 - No illegal modification(s) is allowed
 - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

SURVEYOR NAME: Tan JiahSURVEYOR SIGNATURE: [Signature]DATE: 22/10/2020

Confirm & accepted by

REMARKS: Not Advise, Resurvey before paintEx: to be advise. 12 daystanjiah@lkk.com

Nett

14965.82

Total Payable

14,965.82

1047.61

16,013.43

Authorized signatory and company stamp

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required. Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include any additional parts or labour which may be required after repair work has started.