

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: China Taiping Insurance (Singapore) Pte. Ltd.  
3 Anson Road  
#16-00 Springleaf Tower  
Singapore 079909From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Pauline Tham

Date: 02 Nov 2020

**Preliminary Advice**

Insured Vehicle No	: GBB5327R		
TP Vehicle No	: SMG106M	Accident Date	: 21/10/2020
Make	: TOYOTA ADVAN	Assignment Date	: 22/10/2020
Date of Inspection	: 22/10/2020	Est. Duration of Repair	: 7
Inspection At	: TEAM AUTOPRO PTE LTD (SIN MING) 385 SIN MING DRIVE, #01-02 VICOM INSPECTION CENTRE SINGAPORE 575718		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	17,835.02
Revised Amount	:S\$	10,628.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	10,628.24
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

**Remarks**

- ( ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( ) Other comments :