



VEHICLE INSPECTION ESTIMATE

Address : 1 Kaki Bukit Avenue 6 #02-22/20 Autobay S(417883)

REG NO : 201828067M

Insurance Company: SOMPO INSURANCE SINGAPORE PTE LTD
(MOTOR CLAIMS DEPARTMENT)

Address: NO 50, RAFFLES PLACE, #05-01/06
SINGAPORE LAND TOWER, S(048623)

Telephone: 64616555 Fax: 62257947

Email motorsurvey@sompo.com.sg

Xiao Chen.

Make/ Model : HYUNDAI ACCENT

Date: 22.10.2020

Chassis No : KMHCU41BTKU444993

Vehicle No: SME5402K

Date/Time of Accide 21.10.2020/ 1710

DATE OF REG: 04.10.2018

Materials Cost/ Spare Parts Cost

TO BE COMPLETED BY SERVICE ADVISOR

ITEMS	PARTS DESCRIPTION	QTY	LIST PRICE \$		FINAL PRICE \$
1	REAR END PANEL <i>Dented</i>	1	\$ 608.70		\$ 608.70
2	REAR END PANEL TOP GARNISH <i>End</i>	1	\$ 192.50		\$ 192.50
3	SPARE TYRE FLOOR PANEL <i>Regis</i>	1	\$ 625.30		\$ 625.30
4	BOOTLID <i>Buckled.</i>	1	\$ 1,198.60		\$ 1,198.60
5	BOOTLID INNER TRIM <i>Not in</i>	1	\$ 285.10		\$ 285.10
6	BOOTLID HINGE <i>Not in</i>	2	\$ 145.80		\$ 291.60
7	BOOTLID OUTER STOPPER <i>Green</i>	2	\$ 40.50		\$ 81.00
8	BOOTLID INNER STOPPER	2	\$ 38.50		\$ 77.00
9	BOOTLID INNER TRIM <i>Not in</i>	1	\$ 105.60		\$ 105.60
10	BOOTLID LOGO <i>Not in</i>	1	\$ 85.60		\$ 85.60
11	BOOTLID "ACCENT" EMBLEM <i>Not in</i>	1	\$ 79.50		\$ 79.50
12	BOOTLID WEATHERSTRIP <i>Not in</i>	1	\$ 192.60		\$ 192.60
13	BOOTLID INNER LOCK <i>Damaged</i>	1	\$ 185.90		\$ 185.90
14	BOOTLID OUTER GARNISH <i>Not in</i>	1	\$ 236.70		\$ 236.70
15	BOOTLID NUMBER PLATE LAMP <i>Not in</i>	2	\$ 80.90		\$ 161.80
16	REAR BUMPER <i>Dented</i>	1	\$ 679.80		\$ 483 679.80
17	REAR BUMPER REFLECTORS <i>LH cracked</i>	2	\$ 154.60		\$ 309.20
18	REAR BUMPER SIDE RETAINERS <i>Not in</i>	2	\$ 75.90		\$ 151.80
19	REAR BUMPER REINFORCEMENT <i>Cracked</i>	1	\$ 698.90		\$ 390.80 698.90
20	REAR REINFORCEMENT BRACKETS <i>LH cracked</i>	2	\$ 69.70		\$ 139.40
21	REAR SILENCER BOX <i>Not in</i>	1	\$ 580.90		\$ 580.90
22	REAR FENDER INNER COWLING <i>Not in</i>	1	\$ 168.50		\$ 168.50
23	TAILAMP <i>LH cracked</i>	2	\$ 495.20		\$ 990.40
24	TAILAMP INNER SEALER <i>Not in</i>	2	\$ 38.50		\$ 77.00
Total List Price Cost					\$ 8,203.40

PARTS DISCOUNT 20% \$ 6,562.72

4288.50

3430.80

SPECIAL NETT	PARTS DESCRIPTION	QTY	PRICE \$		FINAL PRICE \$
1	REAR BUMPER CLIPS <i>Neu</i>	1 SET	\$ 30.00		\$ 30.00 ✓
2	REAR NUMBER PLATE WITH CASING <i>Neu</i>	1 SET	\$ 50.00		\$ 50.00 +
3	BOOTLID INNER TRIM CLIPS <i>Neu</i>	1 SET	\$ 30.00		\$ 30.00 +
4	END PANEL TOP GARNISH CLIPS <i>Neu</i>	1 SET	\$ 30.00		\$ 30.00 10
5	REVERSE SENSORS <i>Damaged</i>	1 SET	\$ 250.00		\$ 250.00 200
6	REAR BUMPER TOP GARNISH "VERNA" <i>Neu</i>	1 SET	\$ 280.00		\$ 280.00 180
7	END PANEL TOP GARNISH CLIPS <i>Repaired</i>	1 SET	\$ 30.00		\$ 30.00 +
8	END PANEL SEALANTS <i>Neu</i>	2	\$ 80.00		\$ 80.00 60
9	TAILAMPS CLIPS <i>Neu</i>	2 SET	\$ 30.00		\$ 60.00 20
Total Special Nett Items					\$ 840.00

500

Labour Works/ Panel Beating Related Works	
Job Scope	Quotation
TO RENEW DAMAGED PARTS, REPLACE, BEAT, WELD, REALIGN AND ALIGNE ALL PARTS	\$ 1,600.00
Spray Painting	
Job Scope	Quotation
TO RESPRAY AFFECTED AREAS	\$ 1,600.00
Others Cost (Accident Repair Related Expenses)	
Job Scope	Quotation
TO TUFFCOAT AFFECTED AREA	\$ 200.00 60
TO REMOVE/ REFIT INTERIOR UPHOLSTERY	\$ 150.00 60
LABOUR TO APPLY SEALANT TO THE AFFECTED AREAS	\$ 150.00 60
TO REMOVE/ REFIT WIRING CHECKS ON TAILAMPS	\$ 120.00 30
TO REMOVE/ REPLACE REVERSE SENSORS AND DISTANCE SETTLING	\$ 150.00 50
TO REMOVE AND REPLACE/REFIT BOOTLID MECHANISM	\$ 150.00 60
Total Others Cost	\$ 920.00
GRAND TOTAL	\$ 11,522.72

1920

Adrian Lj
1/s 23/10/20
06 hrs

CAS GARAGE PTE LTD

Person Incharge: Allan
Direct Contact: +65 8782 7171
Email: allan@casgarage.sg

total: 5850.80

1/s 4.6k