

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: ERGO Insurance Pte. Ltd.
5 Temasek Boulevard
#04-01 Suntec Tower Five
Singapore 038985

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn:

Date: 31 Oct 2020

Preliminary Advice

Insured Vehicle No	: YM7197E		
TP Vehicle No	: GBD7131P	Accident Date	: 19/10/2020
Make	: HONDA ACCORD	Assignment Date	: 26/10/2020
Date of Inspection	: 29/10/2020	Est. Duration of Repair	: 2
Inspection At	: GOLDBELL ENGINEERING PTE LTD (PIONEER) BLK 3 PIONEER ROAD NORTH, #01-24 SINGAPORE 628457		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages front O/S portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	1,784.76
Revised Amount	:S\$	1,025.2
Check Items (Estimated)	:S\$	0.00
Total	:S\$	1,025.92
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : SURVEY ON WP