

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI20011561/UYF3Q2

Date: 10/11/2020

REFERENCE

Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. Policy No: DMCVSNA00021272001

Claimant Vehicle No : FBK324J Insured Vehicle No : YQ751E

Date of Loss: 24/09/2020 Nature of Claim: TP Claim No: SNM20D203932/C02/LEWLC

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **FBK324J**

Make & Model: YAMAHA FZ16ST, 153cc (M) Engine No: 45SB023710

Reg. Date: 06/02/2015 (Man. Year: 2013) Chassis No: ME145S0B1E2023850

Colour: Multi-colour Odometer: 0 km

Engine Capacity: 153 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 100-80-17 Rear Tyre Size: 140-60-17

Front Left Side: Timsun 6 mm Rear Left Side: Timsun 6 mm

Front Right Side: 0 mm Rear Right Side: 0 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,816.00	1,965.60	1,850.40	48.49
Miscellaneous Items	0.00	0.00	0.00	
Labour	350.00	290.00	60.00	17.14
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	4,166.00	2,255.60	1,910.40	45.86
Approved Total (Overridden) (S\$)		1,800.00		
Nett Amount (S\$)	4,166.00	1,800.00	2,366.00	56.79

INSPECTION

Date of Assignment: 22/10/2020

Date Inspected: 22/10/2020 Inspected At: F T Fasttrack (HQ)
25 KAKI BUKIT ROAD 4 #01-77
SYNERGY @ KB
Singapore 417800

Estimated Period of Repair: 4.0 days

Adjuster: MARCUS CHUA

Manager: YVONNE WONG YIN CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 10 Nov 2020)	
Parts:	N/A	YAMAHA FZ16ST 153cc (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for FBK324J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*HEADLAMP ASSY	Scratched	315.00 FL	*315.00 FL
2	1		*FRONT COWLING	Cut	255.00 FL	*255.00 FL
3	1		*FRONT FAIRING (LH)	No such part	135.00 FL	*- FL
4	1		*FRONT SIGNAL LAMP (RH) & (LH)	O/s Cut	70.00 FL	*35.00 FL
5	1		*MIRROR (RH) & (LH)	O/s Cut	80.00 FL	*40.00 FL
6	1		*HANDLE BAR	Bent	90.00 FL	*90.00 FL
7	1		*METER ASSY	Not Necessary	268.00 FL	*- FL
8	1		*METER PANEL (RH)	Cracked	42.00 FL	*42.00 FL
9	1		*BRAKE LEVER	Scratched	25.00 FL	*25.00 FL
10	1		*FRONT FORK (LH) & (RH)	O/s Bent	1,040.00 FL	*520.00 FL
11	1		*COWLING OUTER (RH) & (LH)	O/s Cut	150.00 FL	*75.00 FL
12	1		*COWLING INNER (RH) & (LH)	O/s Cut	190.00 FL	*95.00 FL
13	1		*TANK COVER (RH)	Cut	42.00 FL	*42.00 FL
14	1		*THROTTLE GRIP	Torn	22.00 FL	*22.00 FL
15	1		*HANDLE GRIP	Torn	40.00 FL	*40.00 FL
16	1		*BRAKE PEDAL	Bent	65.00 FL	*65.00 FL
17	1		*FRONT WHEEL RIM	Repair	633.00 FL	*- FL
18	1		*FRONT BRAKE DISC	Not Necessary	185.00 FL	*- FL
19	1		*FRONT WHEEL SHAFT	Cut	38.00 FL	*38.00 FL
20	1		*EXHAUST PROTECTOR-A	Cut	133.00 FL	*133.00 FL
21	1		*EXHAUST PROTECTOR-B	Cut	102.00 FL	*102.00 FL
22	1		*TOP BOX	Cut	250.00 FL	*180.00 FL
23	1		*BASE BOX	Bent	70.00 FL	*70.00 FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$\$)	4,240.00	2,184.00
- List Item Discount on L Items 10.00/10.00% (\$\$)	424.00	218.40
Total Parts (\$\$)	3,816.00	1,965.60

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	TRANSPORT FEE	New	50.00	40.00
2	LABOUR CHARGE	New	300.00	250.00
Gross Labour Cost (\$)			350.00	290.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >