

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0782/2020/NS
DATE : 19-Oct-20
WIP : 53283

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Hi Adrian,

3 days - ok - Jy - 03 May 21

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME : MR WANG JUNG MING
ADDRESS : BLK 59 TELOK BLANGAH HEIGHTS
#02-21
SINGAPORE 100059
TELEPHONE : HP +65 80300650
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1800024244-02
VEHICLE NO : SLX 1792 Y
MODEL CODE : AUDI A7 SB 2.0 TFSI 4GF08
MODEL YEAR : 19/03/2018
ENGINE NO : CYP 079823
CHASSIS NO : WAUZZZ4G7JN026931
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 14-Oct-20
PLACE OF ACCIDENT : NEX SHOPPING CENTRE CARPARK

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLX 1792 Y

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE AND REINSTALL REAR PARKING AID AND REAR LID KICK SENSOR. CHECK FUNCTION AND RENEW ACCORDING TO DAMAGE.	S/N \$	360.00	\$ 360.00
2	TO DISMANTLE AND REINSTALL REAR BUMPER. TO REPAIR RHS REAR FENDER. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	1,600.00	\$ 500.00
3	TO RESPRAY REAR BUMPER AND RHS REAR FENDER.	\$	2,200.00	\$ 1,100.00
4	TO RENEW RHS REAR RIM AND TYRE. TO CARRY OUT PRE AND POST WHEEL ALIGNMENT.	S/N \$	520.00	\$ 280.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$ 192.00
TOTAL LABOUR CHARGES		:	\$ 4,872.00	\$ 2,432.00



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLX 1792 Y

S/N	PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
			S/NETT	REMARKS
1	REAR ALUMINIUM RIM - RH	\$	1,267.00	\$ 1,013.60
2	REAR RADIAL TYRE - RH	\$	1,252.00	
3	REAR BUMPER GUIDE SECTION - RH OUTER	\$	53.00	
4	SUNDRIES	\$	300.00	
TOTAL SPARE PARTS		:	\$ 2,872.00	\$ 1,013.60
TOTAL LABOUR CHARGES		:	\$ 4,872.00	\$ 2,432.00
GRAND TOTAL		:	\$ 7,744.00	\$ 3,445.60

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED

SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT