

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE	:	ACCIDENT REPAIRS
WORKSHOP	:	UBI ROAD 1
CONTACT NO	:	6366 2323
FAX NO	:	6841 1183
REFERENCE	:	PA/OD/0770/2020/NS
DATE	:	14-Oct-20
WIP	:	53035

VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY.

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

ATTN: MR. ADRIAN LING - MOTOR CLAIMS DEPT

TEL: 6841 0055 - FAX: 6256 4315

OWNER'S NAME	:	MR SINGHANIA MANAV
ADDRESS	:	19 KOVAN ROAD #10-10 SINGAPORE 548191
TELEPHONE	:	HP +65 97114721
TYPE OF CLAIM	:	OWN DAMAGE CLAIM
POLICY NO	:	2070114801
VEHICLE NO	:	SMU 8190 S
MODEL CODE	:	AUDI Q3 1.4 1.4 TFSI S TRONIC
MODEL YEAR	:	21/8/2020
ENGINE NO	:	CZD 895168
CHASSIS NO	:	WAUZZZF33L1111236
MILEAGE	:	-
DATE IN	:	-
ESTIMATED BY	:	JOHNNY BOO / ALLAN WU
ACCIDENT DATE	:	10-Oct-20
PLACE OF ACCIDENT	:	NEAR BOTANICAL GARDEN



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMU 8190 S

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND REINSTALL FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$ 280.00 ✓	
2	TO REMOVE AND TRANSFER LHS HEADLIGHT CONTROL UNIT AND POWER MODULE.	S/N \$ 400.00 250	
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANISE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 1,500.00 500	
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER. ✓	\$ 1,650.00 550	
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00 ✓	
TOTAL LABOUR CHARGES		: <u>\$ 4,022.00</u>	

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMU 8190 S

S/N PARTS DESCRIPTION	QTY	DAMAGED PARTS & PRICES	
		S/NETT	REMARKS
1 FRONT BUMPER <i>red</i>		\$ 2,045.00	✓
2 FRONT BUMPER CLOSING ELEMENT - LH		\$ 58.00	+
3 FRONT BUMPER GRILLE - LH		\$ 109.00	+
4 FRONT BUMPER CLOSING ELEMENT		\$ 188.00	+
5 FRONT SPOILER <i>lt</i>		\$ 379.00	✓
6 FRONT BUMPER AIR GUIDE GRILLE - LH		\$ 151.00	+
7 FRONT BUMPER GUIDE SECTION - LH		\$ 38.00	+
8 FRONT FENDER - LH		\$ 1,271.00	+
9 FRONT FENDER ATTACHMENT PARTS		\$ 62.00	+
10 FRONT FENDER BRACE - LH		\$ 87.00	+
11 FRONT FENDER BRACKET - LH		\$ 31.00	+
12 FRONT WHEEL HOUSING LINER - LH		\$ 237.00	+
13 WHEEL HOUSING LINER ATTACHMENT PARTS <i>new</i>		\$ 100.00	+
14 HEADLIGHT MOUNTING - LH <i>new</i>		\$ 117.00	+
15 LED HEADLIGHT - LH <i>lt</i>		\$ 5,526.00	✓
16 LIFT CYLINDER - LH <i>new</i>		\$ 208.00	+
17 FRONT WHEEL COVER - LH / RH <i>new</i>	2	\$ 530.00	✓
18 SUNDRIES		\$ 250.00	?
TOTAL SPARE PARTS	:	\$ 11,387.00	
TOTAL LABOUR CHARGES	:	\$ 4,022.00	
GRAND TOTAL	:	\$ 15,409.00	

ALL CHARGES ARE INCLUSIVE OF GST

LEGEND:

REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.



PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME : Adnan L
SURVEYED DATE : 22/10/20.
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS : Not Authorised, 03 Days.

PLEASE NOTE : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LAOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT