

(08/11/13) wef.

ASS. RES. BY: Marcus

REF:

CS/ TP2001568/UVF3

ASSIGNMENT

From:

Date:

Estimated Cost:

OD (TP/WS/TP RES/OD RES/EVA/INV/MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent?: Yes or No

GIA / PR Seen:

Consistent?: Yes or No

Est. Repairs:

days

Res.: Yes or No

Lump Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

FW3618G

Yr Regn:

3, 03

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Yamaha RXZ

c.c

133

Colour

yellow

A/C: Insured / Std / NI / NA

Sp. Reading

37484

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

PM4SPV10000002822

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: M / S / Rim / STD A/Rim or

Tyre Size:

F:

2.75-18

R:

90-90-18 mic

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

metzeler

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

mm

L/Bal.

mm

D.O.A.

27/9/20

D.O.I.

22/10/20

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Body

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Car until 4-3-2023 N/A #403

N/A #3500

claims Malaysia motorcycle

6/11/20 continued N/S #900 with MR 700 (Red 2781.60, 76%)

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2) 6/11/20-typist

Days Of Repair: 4

Resurvey No. of Trip: 1

Survey Fee:

Transportation:

) _ S + RS. _ \$

) Photos

) Others

TOTAL

Report Format : TP

Lump Sum / H.B. (\$) 900

Add Fee: ☐ : Site Insp (\$)

☐ : Interview (\$)

☐ : Tech. Invs (\$)

☐ : Weekend (\$)

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Wong Chen Poh

Accident Date : 27-Sep-20

Vehicle No : FW3618G

Vehicle Model : Yamaha RXZ

Estimated Repair Costs

Qty	Description	Amount S(\$)
	List Items	
1	Front fender	\$ 67 65.00 ✓
2	Fork inner tubes	\$ 82 210.00 X
2	Fork outer tubes	\$ 82 220.00 X
1	Fork under bracket	\$ 17 145.00 X
1	Front bracket disc	\$ 11 135.00 X
1	Front sport rim	\$ 11 280.00 X
1	Front rim shaft	\$ 11 38.00 X
1	Top cowling	\$ CM 85.00 ✓
1	Windshield	\$ CM 32.00 ✓
1	Lampstay	\$ 11 50.00 X
1	Headlamp	\$ 82 70.00 X
2	Side mirrors	35 N/S \$ 52 70.00 100
2	Handle-bar	68 N/S \$ 52 136.00 100
1	Hand grip (1 set)	18 N/S \$ 35 35.00 ✓
2	Handle bar ends	\$ 36 36.00 100
1	Clutch lever	\$ CM 25.00 ✓
1	Meter assy	\$ 11 480.00 X
1	Front footrest - L/H	\$ 32 32.00 ✓
1	Front footrest bracket - L/H	\$ 55 55.00 ✓
2	Rear footrest	\$ 56 56.00 ✓
1	Rear centre cowling	\$ 11 35.00 X
1	Main stand	\$ 11 70.00 X
1	Side stand	\$ 11 58.00 X
2	Side boards	\$ 2 96.00 X
		\$ 2,514.00
		\$ 251.40
		\$ 2,262.60

Less 10%

not Authorised

1/5 @ 900
H/S

P. 506
102
455.40

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Owner : Wong Chen Poh

Accident Date : 27-Sep-20

Vehicle No : FW3618G

Vehicle Model : Yamaha RXZ

Estimated Repair Costs

<u>Special Net Items</u>		
1	Number plate (1 set)	28.00 10
2	Fork oils	\$ 11 30.00 X
2	Fork oil seals	\$ 11 56.00 X
1	Steering cone (1 set)	\$ 11 75.00 X
1	Rear box	\$ 11 150.00
1	Rear box bracket	\$ 11 90.00 X
1	Front tyre	\$ 11 100.00 X
		\$ 529.00

<u>S/No.</u>	<u>Labour</u>	
1	To provide towing service	\$ 80.00 35
2	To ckeck wiring and reset headlamp focusing	\$ 11 80.00 X
3	To repair body frame	\$ 350.00 200
4	To provide labour	\$ 380.00 300
		\$ 890.00

Grand Total

\$ 3,681.60

Singapore Dollars: Three Thousand Six Hundred Eighty-One and Cents: Sixty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: