

Boxfresh Pte Ltd

7030 Ang Mo Kio Ave 5 #06-49

Northstar @AMK Singapore 569880

Tel : 64585441 Fax : 64553470

Vehicle No : SBS3501C

Accident date : 20/10/2020

Model No : VOLVO

Registered owner : Go Ahead Singapore Pte Ltd

B9TL-9.4 D AUTO TURBO ABS (A)

Date of Estimates : 28/10/20

Ref : BF-IC-1021

Replacement charges

Total Charges.

NS #3 Panel P/N: A12-02149. <i>bt</i> ✓	S\$ 790.37
NS#4 Panel P/N: A12-01973 <i>X suc</i>	<i>X</i> S\$875.10 ✓
Mid body Pillar P/N : G01-00097 <i>bt</i> ✓	S\$1571.43
Mid body Pillar P/N : 01G-00163 <i>bt</i> ✓	S\$972.48
ADH SIKA 265 600ml S (7 pcs) P/N : ADA-00094 <i>nee</i> ✓	S\$436.4
SIKA 552 White 600mlo Sausage (10 pcs) P/N : ADA00135 <i>nee</i> ✓	S\$629.85
Pillar Trim infill P/N : AUE00086 <i>bt</i> ✓	S\$139.41
Huck Magna Monobot (150pcs) P/N : FND-00030 <i>nee</i> ✓	S\$154.28
Alloy Capping for LD P/N : M0102506 <i>nee</i> ✓	S\$32.67
Entrance door pillar capping P/N: M08-01027 <i>bt</i> ✓	S\$90
Vertical Window Capping RAL 7035 (2 pcs) P/N : PCD01022 <i>nee</i> ✓	S\$ 275.03
Plastic capping P/N : PLA00025 <i>nee</i> ✓	S\$22.70
Cladding Capping Endcap LHS P/N : PMF01195 (2pcs) <i>X suc</i>	S\$ 36.96
Pillar Repair Kit (for 01G00163) P/N : PRK-00125 <i>nee</i> ✓	S\$722.74
Pillar Repair kit (for G01-00097) P/N : PRK-00126 <i>nee</i> ✓	S\$791.68

6629.04

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg



Replacement part total

: S\$7541.1

Spray Work and Labour (Estimated 2 days)

- Respray replacement new parts
- Respray of damaged parts made good

Labor charges (Estimated 10 days X 2 workers)

- Stripping of all damaged parts
- Re-fit of all replaced parts
- Dismantle of glass panel for repair
- Re-install of all new parts replaced.
- Install new door and AL window capping
- Install new body panels
- Re-fit lower sideglasses
- Repairing of damaged pillars

~~S\$1280~~ 400

3400

~~S\$6000~~ 3000

6629.04

3400.00

10,029.04

Total charges

S\$14821.1

GST

S\$1037.47

Total Bill

S\$ 15858.58

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: _____
Date: _____

Rasm
Hp 90010068

7 days

P/P

26/10/2020 @ 1510 hrs

Resurvey before paint

BOXFRESH PTE LTD

WORKSHOP: 154 GUL CIRCLE SINGAPORE 629611

OFFICE: 7030 ANG MO KIO AVE 5 #06-49 NORTHSTAR SINGAPORE 569880

T: +65 64585441 • F: +65 64553470 • E: business@boxfresh.com.sg • W: www.boxfresh.com.sg