

# Enquire if Your Vehicle is Under Recall

## Vehicle Recall Details

\* ONLY INFORMATION ON VEHICLE RECALLS SUBMITTED FROM 9 APRIL 2007 IS AVAILABLE

Owner ID Type  
**Government**

Owner ID  
**014A**

Vehicle No.  
**QX84E**

Make/Model  
**HONDA/ ODYSSEY 2.4A**

Engine No.:  
**K24A63002168**

Chassis No.:  
**JHMRB18406C202168**

## Recall Details

**Recall No.: R2016070264**



Manufacturer Recall Date:  
**09 Jun 2016**

Estimated Completion Year of Recall:  
**2021**

Brief Description (As Provided by Motor Dealer):

According to the equipment defect notifications filed by Takata, the propellant wafers in some of the subject inflators may degrade over time, which could lead to over-aggressive combustion in the event the airbag is activated. In the event of an inflator rupture, metal fragments could pass through the airbag cushion material possible causing serious injury or fatality to vehicle occupants.

Date Rectified:

**30 Dec 2016**

Hotline Information:

**KAH MOTOR CO SDN BHD at 68413838**

For more details, contact KAH MOTOR COMPANY SDN. BERHAD.

## Recall No.: R2007040003



Manufacturer Recall Date:

**13 Mar 2007**

Estimated Completion Year of Recall:

**2017**

Brief Description (As Provided by Motor Dealer):

**Due to lack of tightening force of Power Steering Pump's bolt, the bolt gets excessive stress and breaks if this is repeatedly used. However in worst case the belt may come off causing steering heavy.**

Date Rectified:

**18 Jun 2007**

Hotline Information:

**KAH MOTOR CO SDN BHD at 68413838**

For more details, contact KAH MOTOR COMPANY SDN. BERHAD.

Save as PDF

OK →

Print