


MBM WHEELPOWER PTE LTD



Your Ref: SLZ211D

Our Ref: GBJ9986U

To: AIG

CC

Fax

Not Notified
Resurvey B4paint
3 days

Date: 16/11/2020
From: Danny
Fax: 64525333
Contact: 93288668
Make / Model: SSANGYONG ACTYON
Chassis No.: KPADA1EESJP3295839
Engine No.: 672960226158228
Year of Make: 2018
Accident Date: 22 October 2020

ESTIMATE FOR VEHICLE NO. : GBJ9986U

DESCRIPTION

REAR BUMPER
REAR BUMPER LOWER COVER
REAR BUMPER CENTER CARRIER
REAR BUMPER LH REFLECTOR
REAR BUMPER CLIPS
REAR BUMPER LH SIDE RETAINER
REAR BUMPER RH SIDE RETAINER
TAIL LAMP LH

QTY		List Price	
1	\$	<i>RM</i> 1,280.00	✓
1	\$	<i>NIP</i> 420.00	X
1	\$	490.00	✓
1	\$	<i>CM</i> 72.00	✓
10	\$	<i>MC</i> 60.00	✓
1	\$	<i>DI</i> 166.00	✓
1	\$	<i>IN</i> 166.00	X
1	\$	<i>CM</i> 691.20	✓
Total:		\$ 3,345.20	
LESS 10%		\$ (334.52)	
Parts Total:		\$ 3,010.68	

SPECIAL NETT

BODY SEALANT

1 \$ *nn* 80.00 X

LABOUR

TO REMOVE, REFIT & REPAIR AFFECTED DAMAGED PARTS INCLUDING TO KNOCK-OUT, WELD & STRAIGHTEN ON THE AFFECTED PARTS.
TO APPLY ANTI RUST COATING
TO REMOVE, REFIT & UPHOLSTERY TO FACILITATE REPAIRS
TO REMOVE & REPLACE BUMPER SENSORS
TO CHECK & RECONNECT ALL NECESSARY WIRING
TO SPRAY PAINT ON THE AFFECTED AREAS

	\$	<i>400</i> 800.00	
	\$	<i>nn</i> 150.00	X
	\$	<i>nn</i> 150.00	X
	\$	60.00	<i>50</i>
	\$	80.00	<i>20</i>
	\$	600.00	<i>400</i>
Total:		\$ 4,930.68	
7% GST:		\$ 345.15	
Grand Total:		\$ 5,275.83	

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Mbm wheelpower pte ltd
160 SIN MING DRIVE
#06-02
SIN MING AUTOCITY
t 62628888 f 64525333