

AIG INSURANCE

Vehicle number	SLA8305X
Make / Model	VOLKSWAGEN GOLF
Chassis number	WVWZZZAUZGW040293
Accident date	22/10/20
Reference	2010-29

Qty Particulars Unit Price - SGD \$

PARTS REPLACEMENT - LIST ITEMS		
1	REAR BUMPER	1267.86 de
1	REAR BUMPER RETAINER LH	57.78 net
1	REAR BUMPER REFLECTOR LH	99.26 X
1	TAILLAMP LH	414.70 ?
1	REAR FENDER LH	1877.78 bu
1	REAR FENDER INNER SHIELD LH	257.52 ?
1	REAR LH LOWER ARM	442.90 ?
1	REAR LH UPPER ARM	442.24 X
1	REAR LH KNUCKLE ARM	918.90 ?
1	REAR LH KNUCKLE ARM BEARING	575.70 ?
1	REAR LH SHOCK ABSORBER	422.62 ?
1	REAR LH TRAILING ARM	538.26 X
1	REAR LH CONTROL ARM	324.22 X
1	REAR LH DOOR PANEL	2187.30 Kyo
1	REAR LH DOOR WEATHERSTRIP	147.02 X
		9974.06
Less 10%		997.41
		8976.65
PARTS REPLACEMENT - SPECIAL NETT ITEMS		
1	RIM	1000.00 600.00 cut
1	RIM LOGO	120.00 X
1	TYRE	600.00 X
1 BOT	BRAKE FUILD	60.00 X
1 SET	REAR BUMPER CLIP	30.00 net
1 SET	REAR FENDER INNER SHIELD CLIP	30.00 X
1 SET	REAR REVERSE SENSOR	400.00 X
Subtotal		2240.00
LABOUR AND MISCELLANEOUS CHARGES		
Balance B/F		11216.65
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00 30.
2	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	150.00 80
3	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	200.00 100? plus
4	REMOVE, REPLACE AND REFIT REVERSE SENSOR	200.00 30.
5	PANEL BEATING ON AFFECTED AREAS	1000.00 600
6	SPRAY PAINTING ON AFFECTED AREAS	1000.00 600
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00 30
Subtotal		2760.00
Grand total		13976.65

Taufik 97493449
 WP 26/10/200 1700
 5 days
 1/2 running after repair
 Taufik 11/11/200