

AIG INSURANCE

Vehicle number	SLA8305X
Make / Model	VOLKSWAGEN GOLF
Chassis number	WVWZZZAUZGW040293
Accident date	22/10/20
Reference	2010-29

Qty	Particulars	Unit Price - SGD \$	
<u>PARTS REPLACEMENT - LIST ITEMS</u>			
1	REAR BUMPER	1267.86	de ✓ 1012
1	REAR BUMPER RETAINER LH	57.78	net ✓
1	REAR BUMPER REFLECTOR LH	99.26	x nn ✓
1	TAILLAMP LH	414.70	x nn ✓ 248
1	REAR FENDER LH	1877.78	buc ✓ 1429
1	REAR FENDER INNER SHIELD LH	257.52	? de ✓ 214.60
1	REAR LH LOWER ARM	442.90	? bt ✓ 350
1	REAR LH UPPER ARM	442.24	x nn ✓
1	REAR LH KNUCKLE ARM	918.90	? bt ✓ 750
1	REAR LH KNUCKLE ARM BEARING	575.70	? bt ✓ 400.10
1	REAR LH SHOCK ABSORBER	422.62	? bt ✓ 263.30
1	REAR LH TRAILING ARM	538.26	x nn ✓
1	REAR LH CONTROL ARM	324.22	x nn ✓
1	REAR LH DOOR PANEL	2187.30	Rp ✓
1	REAR LH DOOR WEATHERSTRIP	147.02	x nn ✓
		9974.06	4724.78
Less 10%		997.41	4252.50
		8976.65	
<u>PARTS REPLACEMENT - SPECIAL NETT ITEMS</u>			
1	RIM	1000.00	600. ✓
1	RIM LOGO	120.00	x nn ✓
1	TYRE	600.00	x nn ✓
1 BOT	BRAKE FUILO	60.00	x nn ✓
1 SET	REAR BUMPER CLIP	30.00	net ✓
1 SET	REAR FENDER INNER SHIELD CLIP	30.00	x nn ✓
1 SET	REAR REVERSE SENSOR	400.00	x nn ✓ 630
Subtotal		2240.00	
<u>LABOUR AND MISCELLANEOUS CHARGES</u>			
Balance B/F		11216.65	
1	CHECK WIRING AND LIGHTNING SYSTEM	60.00	30. ✓
2	COMPUTERISED AND CHECK REAR WHEEL ALIGNMENT	150.00	80 ✓
3	REMOVE AND REPLACE REAR UNDERCARRIAGE PARTS	200.00	100 ✓ 1000
4	REMOVE, REPLACE AND REFIT REVERSE SENSOR	200.00	30. ✓
5	PANEL BEATING ON AFFECTED AREAS	1000.00	600 ✓
6	SPRAY PAINTING ON AFFECTED AREAS	1000.00	600 ✓
7	APPLY ANTI RUST ON AFFECTED AREAS	150.00	30 ✓ 1470
Subtotal		2760.00	6352.30
Grand total		13976.65	4551.00

Taukh 9744549
 WP 26/10/200 1700
 5 days
 1/5 Repair After repair
 1/5 Repair After repair