

ASS. REC. BY: Sun Pin

REF:

CC4/LPC20011583/Qea3

~~CC4/LPC20011583/Qea3~~

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

☒	☒
N/S	O/S
☐	☐

Bal. or Market Value: _____

IDAC Accident Report: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: 10 days Res.: Yes or NoLum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: PC 841 J Yr Regn: 16/11/2011Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Scania K184X2 c.c. 8867Colour: Multicolour A/C: Insured / Std / NI / NA

Sp. Reading: _____ T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: Ys 2K4X20001874302Gen. Cond: Good / Fail / Poor / BurntSteering: In order / 8 Jammed / Leaked / Burnt or _____Brake: In order / 8 Jammed / Leaked / Burnt or _____Modi: Nil / S/Rim / STD A/Rim or _____Tyre Size: F: 295/80 R22.5R: 295/80 R22.5BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front

R/Bal. 6 mmL/Bal. 6 mmD.O.A. 11/10/2020

Survey held at

Des. of Damages: Frnt / Rear / O/S / N/S / U/C / Rooftop or

Rear

R/Bal. 6 mmL/Bal. 6 mmD.O.I. 26/10/2020SC Auto

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

MV: ~~410,000~~ 42,000PR: 3,398NV: ~~106,602~~ 38,602

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Rep. Format: _____

Lump Sum / L.B.I. (\$) _____

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee: ☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

S + RS. \$ _____

Photos

Others

TOTAL

LKK Auto Consultants hereby certify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

YS2K 4X 2000187

Co. Reg. No. 199800107D

M/S TECH MARINE OFFSHORE (S) PTE LTD
Acknowledged by Repairer
Signature: 13 Tuas South Street 3
Singapore 638019

Insured TECH MARINE OFFSHORE (S) PTE LTD
Policy GA413021

Damaged Vehicle No: PC841J

ESTIMATE Bill

GST Reg. No: 19-9800107D
Date: 20/10/2020
Our Case Ref. SC20/10/119/4TM-TP
Accident Date 11/10/2020

S/no	Description	QTY	Price	Disc	Amount
Replaced Parts					
1	LHS SIDE VIEW MIRROR / CRU.	1	PC \$1,980.00		\$1,980.00 1780
2	FRONT WINDSCREEN / BR	1	PC \$4,370.30		\$4,370.30 /
3	RUBBER GLASS / NEC	1	PC \$262.30		\$262.30 /
4	SEALANT / NEC	28	PC \$49.00		\$1,372.00 784
5	FRONT WIPER SET / CRU	1	PC \$1,980.00		\$1,980.00 1,584
6	FRONT CAP (1/2 SECTION) / BR	1	PC \$2,400.00		\$2,400.00 1,450
7	FRONT CAP STRUCTURE (1/2 SECTION) / BT	1	PC \$2,500.00		\$2,500.00 1,850
8	FRONT SALOON / CRU	1	PC \$1,200.00		\$1,200.00 1,050
9	FRONT SALOON EXTENSION / BT	1	PC \$1,400.00		\$1,400.00 1,050
10	FRONT SALOON STRUCTURE FRAME / BT	1	PC \$1,500.00		\$1,500.00 1,380
11	FRONT BUMPER / CRU.	1	PC \$1,800.00		\$1,800.00 /
12	FRONT BUMPER STRUCTURE / BT	1	PC \$1,920.00		\$1,920.00 1,480
13	LHS FOG LAMP COVER / CRU.	1	PC \$136.00		\$136.00 /
14	RHS FOG LAMP COVER / CRA	1	PC \$136.00		\$136.00 /
15	FOG LAMP LH / CRU	1	PC \$160.00		\$320.00 160
16	LHS HEADLAMP / CRU	1	PC \$1,196.00		\$1,196.00 /
17	FRONT NUMBER PLATE / PD	1	PC \$50.00		\$50.00 /
18	EMBLE 'SCANIA' / NEC	1	PC \$108.00		\$108.00 /
19	ARTWORK / NEC	1	PC \$800.00		\$800.00 500
20	FRONT PASSENGER DOOR ASSEMBLY / CRU	1	PC \$3,150.00		\$3,150.00 2,450
21	FRONT DOOR ARM ASSEMBLY / BT	1	PC \$550.00		\$550.00 /
22	RUBBER DOOR GASKET / NEC	2	PC \$140.00		\$280.00 /



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S TECH MARINE OFFSHORE (S) PTE LTD

13 Tuas South Street 3
Singapore 638019

Insured TECH MARINE OFFSHORE (S) PTE LTD

Policy GA413021

Damaged Vehicle No: PC841J

ESTIMATE Bill

GST Reg. No: 19-9800107D

Date: 20/10/2020

Our Case Ref. SC20/10/119/4TM-TP

Accident Date 11/10/2020

S/no	Description	QTY	Price	Disc	Amount
23	FRONT PASSENGER DOOR ALUMINIUM PROFILE / NT	1 PC	\$240.00		\$240.00
24	FRONT PASSENGER GLASS DOOR / BK	1 PC	\$448.00		\$448.00
25	STAIRS ASSEMBLY ? / CRU	1 PC	\$2,800.00		\$2,800.00 2,580
26	STAIRS HANDLE BAR / BT	1 PC	\$280.00		\$280.00
27	STANCHION POLE ? / BT	1 PC	\$580.00		\$580.00
28	FRONT DOOR TOP GLASS / BK	1 PC	\$325.00		\$325.00
29	SIDE DECORATION PANEL / SCR.	1 PC	\$300.00		\$300.00
30	FRONT LHS MUDGUARD PANEL X R	1 PC	\$1,056.00		\$1,056.00 X
31	RHS STABILIZER BAR ? / BT	1 PC	\$127.00		\$127.00
32	RHS TORSION BAR ? / BT	1 PC	\$395.00		\$395.00
33	FRONT RHS MUDGUARD ? / CRU	1 PC	\$520.00		\$520.00
					31,201.60
Labour Charges					* Labour to be confirm
1	LABOUR FOR SPRAY PAINTING	1	\$3,500.00	-	\$3,500.00 2,000
2	LABOUR FOR WIRING	1	\$1,280.00	-	\$1,280.00 200
3	LABOUR FOR GLASS 4 glass	1	\$1,550.00	-	\$1,550.00 /
4	LABOUR FOR UNDERCARRIAGE & MECHANICAL	1	\$2,560.00	-	\$2,560.00 1,280
5	LABOUR FOR UPHOLSTERY & MATERIAL	1	\$1,920.00	-	\$1,920.00 1,280
6	LABOUR FOR FRONT & RHS PORTION 4	1	\$7,680.00	-	\$7,680.00 2,560
\$640 - days					6400
Repair day - 10					3,560
After pain pho					8,810
Sun Pin (24k)					
26/10/2020					
TP with projuder.					
8661 2627					
Sunpin @14K auto.com					
Sub Total					\$54,971.60

Authorised Signature

TP with projuder.

8661 2627

Sunpin @14K auto.com



SC AUTO INDUSTRIES (S) PTE LTD

51 Senoko Road, Singapore 758133
T 65 6758 2222 F 65 6257 6931
E sales@scauto.com.sg
scauto.com.sg

Co. Reg. No. 199800107D

M/S	TECH MARINE OFFSHORE (S) PTE LTD
	13 Tuas South Street 3 Singapore 638019
Insured	TECH MARINE OFFSHORE (S) PTE LTD
Policy	GA413021

SUPPLEMENTARY Bill

GST Reg. No: 19-9800107D
Date: 20/10/2020
Our Case Ref. SC20/10/119/4TM-TP
Accident Date 11/10/2020

Damaged Vehicle No: PC841J

S/no	Description	QTY	Price	Disc	Amount
<u>Replaced Parts</u>					
1	UNDER CARRIAGE ENGINE COVER X SVC	1	PC \$1,750.00	-	\$1,750.00
2	UNDER CARRIAGE ENGINE COVER RHS ? / CRU	1	PC \$875.00	-	\$875.00
3	SILENCER / CRU	1	PC \$22,248.00	-	\$22,248.00
4	INTERIOR FRONT PANEL / CRU	1	PC \$800.00	-	\$800.00
5	FRONT LHS BUMPER BRACKET / BO	1	PC \$125.00	-	\$125.00
6	PASSENGER DOOR STRUCTURE / BO	1	PC \$1,250.00	-	\$1,250.00
					6,730
					- 10%
					6,057.00
					4,200
					31,201.50
					6,057.00
					8,870
					46,128.50
					20%
					36,902.88
					37,800
					\$36,900
					10 days
Sub Total					\$27,048.00

Authorised Signature