

趙源摩哆 Chew Goon Motor

Blk 10, Ang Mo Kio Industrial Park 2A, Avenue 5
#01-15, 16, 17 & #03-05, AMK Autopoint Singapore 568047
Tel: 6484 1626 (24Hrs) Fax: 6484 0465
Business Reg. No: 221880/00C GST Reg. No: MX-0486007-A0

To: China Taiping Insurance (S) Pte Ltd

Accident Date : 20.10.2020

Not Notionia
61 Reg 82900p
Resurvey After Pain

2day Third Party
Policy No: _____
Date: 22.10.2020

Specialised in Car Painting, Welding,
Panel-Beating and Insurance Claim.

ESTIMATE

承接汽车烧焊喷漆及
代理各种车辆赔偿

数量 Quantity	货名 DESCRIPTION	单价 Unit Price	银 Amount 额 \$ cts.
	Estimate Cost of Repair to "Honda Shuttle" Reg. No. SLK8075G Claiming Against Your Insured Veh. No. SMM9494B		
1pc	Front Bumper <i>1020.20</i>	5.50	<i>Bu</i> 1,152.00 <i>✓</i>
12pcs	Front Bumper Clips		<i>na</i> 66.00 <i>✓</i>
1pc	Front Bumper Corner Retainer LH		<i>DIT</i> 21.00 <i>✓</i>
1pc	Front Bumper Reinforcement		<i>R</i> 297.50 <i>✓</i>
1pc	Front Bumper Fog Lamp LH		<i>mycat</i> 347.00 <i>✓</i>
1pc	Front Bumper Fog Lamp Chrome Garnish		<i>na</i> 95.20 <i>✓</i>
1pc	Front Bumper Center Air Grille Side Cover LH (Top)		<i>na</i> 33.20 <i>✓</i>
1pc	Front Bumper Center Air Grille Side Cover LH (Bottom)		<i>na</i> 95.20 <i>✓</i>
1pc	Air Cleaner Resonator		<i>na</i> 89.50 <i>✓</i>
1pc	Air Cleaner Resonator Hose		<i>na</i> 50.10 <i>✓</i>
1pc	Headlamp LH (LED)		<i>cut</i> 2,250.40 <i>✓</i>
1pc	Headlamp Lower Ext Arm <i>62.10</i>		<i>cut</i> 146.00 <i>✓</i>
	Less 20%		4,643.10 928.62 3,714.48
	Front Bumper Inner Electromagnetic Parking Sensor		<i>NSD</i> 450.00 <i>SN X</i>
	Front Number Plate Writers (Chrome) <i>Chun Type</i>		<i>na</i> 120.00 <i>SN 35na</i>
	Headlamp Lower Garnish		<i>na</i> 120.00 <i>SN 205na</i>
	To Conduct Front Electrical Check, Focus Headlamp		30.00 <i>201</i>
	To Conduct Computerize Wheel Alignment Test		<i>na</i> 80.00 <i>X</i>
	Labour Charge - Panel Beating, Repairing Of Bumper Beam, Lower Panel And Part Replacement		300.00 <i>2001</i>
	To Respray Affected Areas		280.00 <i>2001</i>
	Total :		<u>5,094.48</u>