

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SMR3540P (Insd veh)	Model:	TOYOTA HARRIER 2.0
	SMR4371D (TP veh)		PREMIUM (A)
Date of Accident:	24/10/2020		

Global Sum Settlement	:	☒ Yes	☐ No
Repair Estimate	:	\$	22,532.21
Final Repair Cost	:	\$	13,500.00
Loss of Use	:	\$	days at \$0.00 per day
Rental (if any)	:	\$	9 days
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum (Global Sum)	:	\$	13,500.00
Is Third Party Workshop GIA Registered? ☐ YES ☒ NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability ____ 100 ____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): ____ 0 ____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	Ryder Auto Pte Ltd	: \$	13,500.00
2)		: \$	
3)		: \$	

JOANNE LEE KHANG MIN

13 Apr
2021

LKK Auto Consultants Pte Ltd

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report;
Medical Report/ Bill (if any))