

JWG INTERNATIONAL PTE. LTD.

10, ANG MO KIO IND PARK 2A, #03-08 AMK AUTOPOINT, SINGAPORE 568047

H/P: 8299 6103 | FAX: 6909 9592

E-Mail: jwg.claims@yahoo.com

To: INDIA INTERNATIONAL INSURANCE PTE LTD

Att: Motor Claims Dept

ACCIDENT INVOLVING SHD2229D [YOUR INSURED] & SLZ3940M [OUR CLIENT]
ON 26/10/2020.

ESTIMATED REPAIR COSTS FOR SLZ3940M

<u>QTY</u>	<u>PARTS</u>	<u>AMOUNT</u>	
1PC	TAILGATE <i>Devent</i>	\$ 1,659.20	✓
1PC	TAILGATE INNER TRIM BOARD <i>HL</i>	\$ 525.50	X
1SET	TAILGATE INNER TRIM BOARD CLIPS <i>HL</i>	\$ 20.00	X
1PC	TAILGATE CENTER MOULDING <i>HL</i>	\$ 495.79	X
1SET	TAILGATE CENTER MOULDING CLIPS <i>HL</i>	\$ 20.00	X
1PC	TAILGATE TOYOTA LOGO <i>HL</i>	\$ 72.50	✓
1PC	TAILGATE PRIUS PLUS EMBLEM <i>HL</i>	\$ 65.90	✓
1PC	TAILGATE HYBRID SYNERGY EMBLEM <i>HL</i>	\$ 79.62	✓
1PC	TAILGATE SWITCH <i>HL</i>	\$ 352.90	X
1PC	TAILGATE LOCK <i>Devent</i>	\$ 461.60	✓
1PC	TAILGATE WEATHER STRIP <i>HL</i>	\$ 399.82	✓
2PCS	TAIL LAMP LH / RH @ \$601.90 EACH <i>monetary crack</i>	\$ 1,203.80	✓
2PCS	TAIL LAMP PANEL LH / RH @ \$339.80 EACH <i>HL</i>	\$ 679.60	X
2PCS	TAIL LAMP LOWER BRACKET LH / RH @ \$209.40 EACH <i>HL</i>	\$ 418.80	X
1PC	REAR BUMPER <i>distorted</i>	\$ 1,030.59	✓
1SET	REAR BUMPER CLIPS <i>HL</i>	\$ 20.00	✓
2PCS	REAR BUMPER SIDE RETAINER L+R @ \$144.42 EACH <i>SVC</i>	\$ 288.84	X
2PCS	REAR BUMPER REFLECTOR LH / RH @ \$109.33 EACH <i>HL</i>	\$ 218.66	X
1PC	REAR END PANEL <i>Devent</i>	\$ 880.80	✓
1PC	REAR END PANEL TOP GARNISH <i>distorted monetary</i>	\$ 332.40	✓
1SET	REAR END PANEL TOP GARNISH CLIPS <i>HL</i>	\$ 20.00	✓
1PC	SPARE WHEEL PANEL <i>Devent</i>	\$ 1,219.48	✓
2PCS	SPARE WHEEL QUARTER PANEL LH / RH @ \$698.74 EACH <i>HL</i>	\$ 1,397.48	X
1PC	SPARE WHEEL PANEL TOP BOARD <i>HL</i>	\$ 412.99	X
2PCS	REAR FENDER LH / RH @ \$ 1,847.86 EACH <i>HL</i>	\$ 3,695.72	X
2PCS	REAR FENDER INNER TRIM LH / RH @ \$882.42 EACH <i>o/s crack H/S</i>	\$ 1,764.84	✓
1PCS	REAR TOOL BOX <i>monetary distorted</i>	\$601.39	✓
		PARTS SUM: \$ 17,736.83	
		PARTS LESS 25%: \$ 4,434.21	
		PARTS TOTAL: <u>\$ 13,302.62</u>	

LABOUR & SPECIAL NETT ITEMS

*	TO SUPPLY REAR NUMBER PLATE HW	\$ 80.00 X
*	TO SUPPLY REVERSE SENSOR D-W	\$ 400.00 220/-
*	TO SUPPLY TAIL LAMP SEALANT HW	\$ 60.00 X
*	TO SUPPLY REAR END PANEL SEALANT Hec	\$ 80.00 40/-
*	TO SUPPLY 1 PC REVERSE CAMERA HW	\$ 500.00 X
*	TO SUPPLY REAR FENDER SEALANT HW	\$ 80.00 X
*	TO SUPPLY REAR FENDER INNER TRIM CLIPS Hec	\$ 50.00 20/-
*	TO REMOVE ALL INTERIOR UPHOLSTERLY ITEMS TO FACILITATE REPAIRS	\$ 300.00 80/-
*	TO REMOVE & PANEL BEAT ALL DAMAGED ABOVE PARTS & PANELS	\$ 2,000.00 900/-
*	TO RESPRAY NEW PAINTWORK FOR ALL DAMAGED AREAS	\$ 2,000.00 700/-
*	TO TUFF COAT DAMAGED AREAS	\$ 300.00 40/-
*	TO RNR REAR BOOT MECHANISM TO ASSIST WORK LOAD	\$ 200.00 60/-
*	TO RNR EXHAUST SYSTEM AND ATTACHMENT PARTS	\$ 250.00 HW
*	TO RNR TAILGATE WINDSCREEN TO ASSIST WORK LOAD	\$ 300.00 120/-
*	TO RNR REAR FENDER QUARTER GLASS TO FACILITATE REPAIRS	\$ 400.00 HW
	TO RNR REVERSE SENSOR & REVERSE CAMERA	\$ 300.00 30/-
*	TO CHECK & RE-FIX ALL ELECTRICAL WIRINGS	\$ 200.00 30/-
*	TO COMPUTERIZE DIAGNOSE FAULT CODES & CONTROL UNITS. RESET ALL MEMORIES TO FACTORY DEFAULT SETTINGS	\$ 300.00 HW

LABOUR & S/N TOTAL: \$ 6,550.00

GRAND TOTAL ESTIMATED REPAIR COSTS (NON-INCLUSIVE OF 7% GST): \$ 19,852.62

27/10/2020 @ 0915hrs
Nat Antun
L/Sun
Ryan 5 dgs.
LKK Auto

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Check Part prices.