

Adjuster Letter/DV not verified.
This claim is to be authorized on the insurer's behalf.
Submissions will not be allowed until the Letter of Offer/DV is VERIFIED.
Click on 'View Letter/DV' to verify the offer.

You cannot authorize this offer because
Adjuster Letter/DV not verified.
File to be authorized by your superior.

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AIG20011608/QBA3Q2
Date: 17/03/2021

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.	Policy No: 2070116730	
Claimant Vehicle No: SLU1781U	Insured Vehicle No: SMU3215M	
Date of Loss: 21/10/2020	Nature of Claim: TP	Claim No: 9844258977SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLU1781U		
Make & Model: TOYOTA C-HR HYBRID, 1.8 S CVT (A)	Engine No: 2ZR8196899	
Reg. Date: 24/11/2017 (Man. Year: 2017)	Chassis No: ZYX102076011	
Colour: White	Odometer: 207223 km	
Engine Capacity: 1797 cc		
Market Value/New Car Price: N/A		
Sum Insured (S\$): Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable): Yes	Footbrake (Serviceable): Yes
Handbrake (Serviceable): Yes	Engine Modification: No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 215/60 R17	Rear Tyre Size: 215/60 R17	
Front Left Side: Dunlop 6 mm	Rear Left Side: Dunlop 6 mm	
Front Right Side: Dunlop 6 mm	Rear Right Side: Dunlop 6 mm	

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,127.91	5,007.51	8,120.40	61.86
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,370.00	1,620.00	1,750.00	51.93
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,497.91	6,627.51	9,870.40	59.83
Approved Total (Overridden) (S\$)		5,300.00		
(S\$)	16,497.91	5,300.00	11,197.91	67.87
+ GST 7.00/7.00% (S\$)	1,154.85	371.00	783.85	67.87
Nett Amount (S\$)	17,652.76	5,671.00	11,981.76	67.87
+ Loss of Use (7.0 x S\$80.00/day) (S\$)		560.00		
+ Doc/Search Fee (S\$)		7.45		
Nett Liability (S\$)		6,238.45		
Global Sum Settlement (S\$)		6,000.00		

INSPECTION

Date of Assignment: 23/10/2020		
Date Inspected: 26/10/2020	Inspected At:	My Car Consultant Pte Ltd (HQ) 60 Jalan Lam Huat,, Carros Centre #05-67/68 Singapore 737869

3/17/2021

Merimen e-Claims

Estimated Period of Repair: 5.0 days

Adjuster: OI SUN PIN

Manager: CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*REAR BUMPER PLATE TOP APRON	Cracked	708.00 FL	*708.00 FL	
2	1		*REAR BUMPER	Crumpled	681.90 FL	*681.90 FL	
3	1		*REAR BUMPER CTR COVER	Serviceable	195.10 FL	*- FL	
4	1		*REAR BUMPER SIDE RETAINER LH	Serviceable	212.00 FL	*- FL	
5	1		*REAR BUMPER SIDE RETAINER RH	Broken	212.00 FL	*98.00 FL	
6	1		*REAR BUMPER REINF	Bent	681.10 FL	*398.00 FL	
7	1		*REAR BUMPER TOWING COVER	Missing	151.10 FL	*68.50 FL	
8	1		*REAR BUMPER LOWER	Scratched	681.10 FL	*580.00 FL	
9	1		*REAR BUMPER REFLECTOR RH	Cracked	85.00 FL	*85.00 FL	
10	1		*REAR BUMPER REFLECTOR GAR RH	Cracked	105.00 FL	*105.00 FL	
11	1		*REAR BOOTLID	Crumpled	1,120.85 FL	*1,120.85 FL	
12	1		*REAR BOOTLID EMBLEM	Necessary	112.00 FL	*81.10 FL	
13	1		*REAR BOOTLID CHR LOGO	Necessary	112.00 FL	*81.10 FL	
14	1		*REAR BOOTLID ENERGY LOGO	Necessary	81.10 FL	*81.10 FL	
15	1		*REAR BOOTLID LOCK	Jammed	581.90 FL	*364.00 FL	
16	1		*REAR BOOTLID WEATHERSTRIPE	Cut	477.10 FL	*340.00 FL	
17	1		*REAR BOOTLID INNERTRIM BOARD	Crumpled	780.00 FL	*480.00 FL	
18	1		*REAR END PANEL	Repair	880.00 FL	*- FL	
19	1		*REAR END PANEL TOP GAR	Serviceable	474.45 FL	*- FL	
20	1		*REAR SPARE TYRE PANEL	Serviceable	1,100.00 FL	*- FL	
21	1		*REAR SPARE TYRE BOARD	Serviceable	890.00 FL	*- FL	
22	1		*REAR FENDER INNER TRIM RH	Serviceable	655.00 FL	*- FL	
23	1		*REAR FENDER PROTECTOR RH	Serviceable	378.10 FL	*- FL	
24	1		*REAR REVERSE SENSOR LH INNER }	Shorted	363.83 FS	*200.00 FS	
25	1		*REAR REVERSE SENSOR RH INNER }	Shorted	363.83 FS	*- FS	
26	1		*REAR EXHAUST HEAT SHIELD	Serviceable	256.20 FL	*- FL	
27	1		*REAR EXHAUST MUFFLER	Serviceable	1,200.10 FL	*- FL	
28	1		*REAR WINDSCREEN MOULDING	Necessary	192.80 FL	*192.80 FL	
29	1		*REAR NUMBER PLATE	Scratched	80.00 FS	*30.00 FS	
30	1		*SET REAR BUMPER CLIP	Necessary	100.00 FS	*30.00 FS	
31	1		*SET REAR BOOTLID INNERTRIM CLIP	Necessary	100.00 FS	*20.00 FS	
32	1		*SET REAR END PANEL TOP GAR CLIP	Not Necessary	100.00 FS	*- FS	
33	1		*SET REAR FENDER INNER TRIM RH CLIP	Serviceable	100.00 FS	*- FS	
34	1		*REAR FENDER PROTECTOR CLIP SET RH	Serviceable	100.00 FS	*- FS	
35	1		*REAR FENDER PROTECTOR CLIP SET LH	Serviceable	100.00 FS	*- FS	
36	1		*REAR WINDSCREEN SEALANT	Necessary	150.00 FS	*30.00 FS	
37	1		*REAR END PANEL SEALANT	Serviceable	120.00 FS	*- FS	
38	1		*REAR SPARE TYRE PANEL SEALANT	Serviceable	150.00 FS	*- FS	
39	1		*REAR FENDER PROTECTOR LH	Serviceable	378.10 FL	*- FL	
40	1		*TAILAMP RH	Cracked	798.00 FL	*566.00 FL	
41	1		*TAILGATE LAMP RH	Serviceable	454.00 FL	*- FL	
42	1		*TAILAMP LOWER BRACKET RH	Broken	112.00 FL	*112.00 FL	
43	1		*KEYLESS SENSOR	Cracked	321.00 FL	*120.00 FL	
F=Franchise part. S=SpcNett. L=ListItemDisc.							
					Sub Total (\$\$)	16,894.66	6,573.35
					- List Item Discount on L Items 25.00/25.00% (\$\$)	3,766.75	1,565.84
					Total Parts (\$\$)	13,127.91	5,007.51

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items
There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	CHECK WIRING	New	80.00	30.00
2	R+R REVERSE SENSOR	New	120.00	30.00
3	R+R RR WINDSCREEN	New	150.00	120.00
4	R+R EXHAUST	New	250.00	0.00
5	RESET & DIAGNOSE FAULT CODE	New	250.00	0.00
6	ANTI RUST COAT	New	120.00	40.00
7	PANEL BEAT	New	1,200.00	700.00
8	SPRAY	New	1,200.00	700.00
Gross Labour Cost (S\$)			3,370.00	1,620.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >