

POLYMATH GARAGE PTE LTD

10 KAKI BUKIT ROAD 2 #01-21 FIRST EAST CENTRE
SINGAPORE 417868
97253727

TO	: INDIA INTERNATIONAL	DATE	: 26/10/2020
ATTENTION	: MOTOR INSURANCE CLAIM	JOB TYPE	: T/P CLAIM
ESTIMATE REPORT	:		
VEHICLE DETAILS			
VEHICLE NO	: SJQ1050R		
VEHICLE MODEL	: HONDA AIRWAVE		
CHASSIS NO	: GJ11302813		
ACCIDENT DETAILS	DATE	:	
	TIME	:	
THIRD PARTY REQUESTOR / CONTACT	:	NIGEL / 97253727	

CLAIM DETAILS: PARTS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER <i>Neu</i>	1	\$ 981.50	\$ 981.50
2	FRONT BUMPER SIDE HOLDER LH <i>Neu</i>	1	\$ 38.50	\$ 38.50
3	HEADLAMP LH <i>3 Ave</i>	1	\$ 868.50	\$ 868.50
4	FRONT LH FENDER <i>3 Ave</i>	1	\$ 661.20	\$ 661.20
5	FRONT LH FENDER GLASS C/W MOULDING <i>cut</i>	1	\$ 325.00	\$ 325.00
6	FRONT LH DOOR <i>Dented</i>	1	\$ 1,045.60	\$ 1,045.60
7	FRONT LH DOOR LOCK <i>Neu</i>	1	\$ 314.60	\$ 314.60
8	FRONT LH DOOR WEATHERSTRIPE <i>Neu</i>	1	\$ 156.70	\$ 156.70
9	FRONT LH DOOR WING MIRROR <i>Damaged</i>	1	\$ 589.60	\$ 589.60
10	FRONT LH DOOR OUTER HANDLE <i>Repair</i>	1	\$ 109.50	\$ 109.50
11	REAR LH DOOR <i>Dented</i>	1	\$ 987.40	\$ 987.40
12	REAR LH DOOR LOCK <i>Neu</i>	1	\$ 314.60	\$ 314.60
13	REAR LH DOOR WEATHERSTRIPE <i>Neu</i>	1	\$ 168.20	\$ 168.20
14	REAR LH DOOR OUTER HANDLE <i>Repair</i>	1	\$ 115.20	\$ 115.20

TOTAL PRICE: \$ 6,676.10

LESS 20% \$ 542.78

SUB TOTAL PRICE: \$ 6,133.32

2947.60
2358.08

SPECIAL NETT ITEMS

	ITEMS	QTY	UNIT PRICE	TOTAL
1	FRONT BUMPER CLIPS <i>Neu</i>	1 SET	\$ 30.00	\$ 30.00
2	FRONT LH FENDER GLASS SEALANT <i>over</i>	1	\$ 30.00	\$ 30.00
3	FRONT LH DOOR BLACK TAPE <i>3 Neu</i>	1	\$ 60.00	\$ 60.00
4	REAR LH DOOR BLACK TAPE <i>3 Neu</i>	1	\$ 60.00	\$ 60.00

150

TOTAL : \$ 120.00

LABOUR

	JOB	PRICE	ADJUSTED COST	APPROVED
1	PANEL BEATING, REMOVE AND REFIT PARTS	\$ 1,000.00	500	
2	SPRAY PAINTING TO AFFECTED AREA	\$ 1,000.00	500	
3	WIRING CHECK	\$ 50.00	30	
4	TUFF COAT	\$ 150.00	50	
5	TO TRANSFER FRONT DOOR FITTINGS	\$ 150.00	80	
6	TO TRANSFER REAR DOOR FITTINGS	\$ 150.00	80	
7	TO REMOVE FENDER GLASS	\$ 100.00	50	

TOTAL: \$ 2,600.00

1290

ESTIMATE REPORT

TOTAL PARTS COST: \$ 6,253.32

TOTAL LABOUR COST: \$ 2,600.00

TOTAL REPAIR COST: \$ 8,853.32

APPROVED DETAILS

SURVEYOR:

CONTACT:

PART BY PART / LUMP SUM:

NO. OF DAYS:

FAX:

total: 3798.00

L/S: 3K

04 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: