

Our Job Ref No 305429979Date : 02.11.20ComfortDelGro Engineering Pte Ltd
59 Loyang Drive Singapore 508969
Fax: 6546 8156**FINALIZATION FORM**To : LKK

Fax :

Attn : Mr STEVEVehicle Reg No. SHC2461D CTPL21.10.20

The survey and estimates of the repairs of the above-mentioned vehicle are as follows:-

1. The repair job shall bill to: NTUC --- FBG677L
2. The finalized amount shall be:
- | | |
|---|--------------------------|
| (a) Spare Parts after List discount | <u>\$902.02</u> |
| (b) Labour Charges | <u>\$550.00</u> |
| Total for Part-By-Part Repair Cost | <u>\$1,452.02</u> |
| (c.) Lumpsum Repair (if applicable) | |
| Total for Lumpsum repair cost after Less: | <u>20%</u> |
| Final Lumpsum Repair cost | |

3. Estimated normal period for repairs:
- 2
- working days.

- 4.
- We shall treat the above amount as Correct and Confirmed if there is no reply from you within 7 working days**

5. Thank you for your assistance.

We confirm the estimates and
finalized amountSignature : Name : LIM KWOK ENGTel : 62148316Fax : 65468156Signature : Name : SteveDate : 3/11/20**For Official Use Only**

Item	Amount	Document Attached Yes or No	Confirm By (Signature)	Remarks
1. Rental Rate P/Day		YES		
2. Loss of Income Paid		NO		
3. Survey Fees				
4. LTA Search Fee	\$7.49 / \$2.00			
5. Medical Fees (on behalf of driver, if applicable)				
6 Overrun				

Remarks:

COMPANY : THIRD PARTY'S CLAIMS (CAS)
 CUSTOMER: 7010045
 ADDRESS : COMFORT TRANSPORTATION PTE LTD
 383 SIN MING DRIVE
 SINGAPORE SINGAPORE 575717
 65508755

JOB NO : 305429979
 REGN NO : SHC2461D
 MILEAGE : 0000000000
 MAKE : HYUNDAI
 MODEL : IONIQ(G2)
 DATE OF REGN : 11.12.2018
 DATE/TIME IN : 26.10.2020 11:05
 ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1 L	459.40	20.00	367.52	X R ✓ part-taken
0002	04-01-0101-0111-G	HYUNDAI BUMPER COVER CLIP	10 L	22.00	20.00	17.60	X
0003	04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1 L	451.25	20.00	361.00	/ CR4
0004	09-01-9999-0068-A	HYUNDAI REVERSE SENSOR AS	1 N	180.00	10.00	162.00	X
0005	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1 L	155.00	20.00	124.00	x ✓ part-taken.
0006	FNPS	NO PLATE(S) WITH TRIM COV	1 N	55.00	10.00	49.50	/ DR

SUB-TOTAL : 1,081.62

JOB NATURE

0000 L	PANEL BEATING	350.00	320
0001 23-502	SPRAYPAINT ON AFFECTED AREA	250.00	200
0002 20-22	REMOVE/REFIX REVERSE SENSOR	80.00	30

SUB-TOTAL : 680.00

Steve CLKK) in the
 26/10/20, 3.40 pm
 2 days
 P/P
 Ry Bel my

COMPANY : THIRD PARTY'S CLAIMS (CAS)
CUSTOMER: 7010045
ADDRESS : COMFORT TRANSPORTATION PTE LTD
383 SIN MING DRIVE
SINGAPORE SINGAPORE 575717
65508755

JOB NO : 305429979
REGN NO : SHC2461D
MILEAGE : 0000000000
MAKE : HYUNDAI
MODEL : IONIQ(G2)
DATE OF REGN : 11.12.2018
DATE/TIME IN : 26.10.2020 11:05
ACCIDENT DATE : 21.10.2020

JOB / PARTS DESCRIPTION

QTY IND UNIT-PRICE DISC% AMOUNT

PART REQUISITION

0001	04-01-0104-2282-G	IONIQVC COVER-RR BUMPER#	1	L	459.40	20.00	367.52
0002	04-01-0104-2533-G	IONIQV2-4 MOULDING ASSY-R	1	L	451.25	20.00	361.00
0003	04-01-0104-2545-G	IONIQVC MOULDING-REAR BUM	1	L	155.00	20.00	124.00
0004	FNPS	NO PLATE(S)	1	N	55.00	10.00	49.50

SUB-TOTAL : 902.02

JOB NATURE

0000	L	PANEL BEATING	320.00
0001	23-502	SPRAYPAINT ON AFFECTED AREA	200.00
0002	20-22	REMOVE/REFIX REVERSE SENSOR	30.00

SUB-TOTAL : 550.00

TOTAL : 1,452.02

AUTHORISED : YES / NO

MVA NAME & SIGNATURE
DATE :

SURVEYOR NAME & SIGNATURE
DATE :