

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/III20011620/GBA3Q2
Date: 30/07/2021**REFERENCE**

Handling Insurer:	India International Insurance Pte Ltd	Policy No:	MCOM0015
Claimant Vehicle No :	SMF7111G	Insured Vehicle No :	SH7311P
Date of Loss:	22/10/2020	Nature of Claim:	TP
		Claim No:	MCT20100364

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SMF7111G	Engine No:	LEB5916948
Make & Model:	HONDA VEZEL, 1.5 HYBRID (A)	Chassis No:	RU31216938
Reg. Date:	20/01/2017 (Man. Year: 2016)	Odometer:	191742 km
Colour:	Black		
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	235/40Z R19	Rear Tyre Size:	235/40Z R19
Front Left Side:	Tourador 6 mm	Rear Left Side:	Tourador 6 mm
Front Right Side:	Tourador 6 mm	Rear Right Side:	Tourador 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,314.48	1,496.48	1,818.00	54.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,560.00	1,000.00	2,560.00	71.91
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,874.48	2,496.48	4,378.00	63.68
Approved Total (Overridden) (S\$)		2,000.00		

Nett Amount (S\$)	6,874.48	2,000.00	4,874.48	70.91
+ Loss of Use (5.0 x S\$60.00/day) (S\$)		300.00		
(S\$)		2,300.00		
Liabe Amount (50.00%) (S\$)		1,150.00		

INSPECTION

Date of Assignment: 26/10/2020

Date Inspected: 10/12/2020

Inspected At:

SEM AUTO CARE PTE LTD
 8 KAKI BUKIT ROAD 4, #03-45, PREMIER @ KAKI BUKIT
 Singapore 415875

Estimated Period of Repair: 4.0 days

Adjuster: XING GUO QIANG**Manager:** CHUA ZHEN LI

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 01 Jul 2021)
Parts:	M1-SUV	HONDA VEZEL 1.5 HYBRID (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SMF7111G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*DOOR FRONT LH	Buckled	930.60 FL	*930.60 FL
2	1		*DOOR REAR LH	Buckled	900.00 FL	*900.00 FL
3	2		*DOOR LOCK LH FR & RR	Not Necessary	520.00 FL	*- FL
4	2		*DOOR RUBBER LH FR & RR	Not Necessary	120.00 FL	*- FL
5	2		*DOOR RUBBER LH FR & RR	Not Necessary	80.00 FL	*- FL
6	2		*DOOR RUBBER BELOW LH FR & RR	Not Necessary	80.00 FL	*- FL
7	1		*DOOR STICKER LH	Not Necessary	30.00 FL	*- FL
8	2		*DOOR WEATHERSTRIP LH FR & RR	Not Necessary	320.00 FL	*- FL
9	2		*DOOR MOULDING LH FR & RR	Not Necessary	60.00 FL	*- FL
10	2		*DOOR TAPE LH FR & RR	Necessary	40.00 FL	*40.00 FL
11	1		*SOUND PROOF DOOR LH FR & RR	Not Necessary	850.00 FS	*- FS
					Sub Total (\$\$)	3,930.60
					- List Item Discount on L Items 20.00/20.00% (\$\$)	616.12
					Total Parts (\$\$)	3,314.48

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR CHARGE TO REPAIR & REBUILD INCLUDING CUT & WELD WHERE NECESSARY REMOVE & REPLACE REAR DAMAGE PARTS AS LISTED ABOVE	New	1,000.00	400.00
2	TO SPRAY PAINT ON REAR PORTION AFFECTED AREAS	New	800.00	500.00
3	MATT BLACK STICKER	New	800.00	0.00
4	TO REMOVE AND REINSTALL LEFT FR & RR DOOR GLASS TO FACILITATE REPAIR }	New	360.00	100.00
5	SOUND PROOF DOORS LH FR & RR }	New	600.00	0.00
Gross Labour Cost (\$)			3,560.00	1,000.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >