

ESTIMATE

Invoice Name & Address	Owner Name & Vehicle Info
INDIA INTERNATIONAL INSURANCE SINGA 64 CECIL STREET #04-05 IOU BUILDING SINGAPORE 049711	Cust No/Name /Mr Loh Soo Moi @loh Soon Hing J Reg No/Reg Date SGM2931Z*1F / 15/01/2016 Date In/Mileage 24/10/2020/ 143590 Chassis No JMFXTGA2WFZC08803 Engine No 4B11QT3042 Make/Model MIT/ASX 2.0 CVT 2WD (N04) Colour/Trim W01 / BK
Contact No	

Account No	Terms	Date/Time Printed	CSE	Operator	WIP No
F0000036	Credit	26/10/2020/ 13:34	DS	218 / Mars Ler	55371
Description of Goods / Services	Qty	Unit Price	Disc%	Amount	
S MIPNT88088 DIAGNOSTIC / SCANNING				250.00	
S MIPNT88088 TO CHECK LIGHTING AND WIRING SYSTEM ON FRONT ACCIDENT AFFECTED AREAS				100.00	
S MIPNT88088 TO REPLACE FRONT BUMPER, REINFORCEMENT, ETC -TO REPAIR HOOD STRAIGHTEN, REFORM, ALIGN ON FRONT ACCIDENT AFFECTED AREAS	1520			1800.00	
S MIPNT98088 SPRAY PAINTING ON FRONT ACCIDENT AFFECTED AREAS				1680.00	
M JJ6400G901 FACE, FR BUMPER	1.00	1036.00	0.00	1036.00	
M JJ6402A275 GARNISH, FR BUMPER	1.00	841.00	0.00	841.00	
M JJMR473000 RIVET, FR BUMPER	4.00	4.00	0.00	16.00	
P JJMR288150 CLIP, FR BUMPER	4.00	3.00	0.00	12.00	
M JJMU000319 CLIP, FR BUMPER	5.00	4.00	0.00	20.00	
M JJ6402A288 GRILLE, RADIATOR	1.00	265.00	0.00	265.00	
P JJ7415A603 MARK, THREE-DIA	1.00	69.00	0.00	69.00	
P JJ6400C966 REINFORCEMENT, FR BUM	1.00	53.00	0.00	53.00	
M JJ6400H876 REINFORCEMENT, FR BUM	1.00	415.00	0.00	415.00	
M JJ6400C878 CORE, FR BUMPER	1.00	10.00	0.00	10.00	
M JJ5220K207 LH MOULDING, FR WHEEL	1.00	132.00	0.00	132.00	
M JJ5220K208 RH MOULDING, FR WHEEL	1.00	131.00	0.00	131.00	
M JJ8301C874 RH HEADLAMP ASSY	1.00	816.00	0.00	816.00	
Z NOTES ACCIDENT ON 23/10/2020 ALONG BLK 153 BUKIT BATOK ST. 11 OPEN CARPARK OWNER CLAIMING THIRD PARTY REQUIRED REPLACEMENT CAR TP # YP445U TP INS : I.I.I.				2188	
				3708	

LKK Auto Consultants hence notify
 the Repaired of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company

Guo Qianf.
8288082
28/10/2020

Parts	3,816.00
Labour	0.00
Standard Menu	0.00
Specialist Job	3,830.00
Others (Lub, etc)	0.00
Sundry	0.00
Total (w/o GST)	7,646.00

Validity of this estimate is 14 days from date of quote. This is a computer generated document, no signature is required.
 Estimated costs quoted are excluding GST. We would mention that the above estimate is based on our initial inspection and does not include
 any additional parts or labour which may be required after repair work has commenced. Occasionally worn or damaged parts are discovered
 after work has started and needed for repairs or replacement. However, should this occur, we would advise you. Please be informed that a
 deposit of 50% of the above estimate is payable before commencement of the work. Payment for this may be made in cash, credit card or
 cheque. You must also agree to pay full amount for renewal of the windscreen in the event of inadvertent breakage in the course of renewing
 the rubber seal or other repair requiring the removal of the windscreen.