

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG20011630/EEA3Q2
Date: 23/09/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	1800097991-02
Claimant Vehicle No :	SHA4368M	Insured Vehicle No :	SMD2020D
Date of Loss:	21/10/2020	Nature of Claim:	TP
		Claim No:	9722796268SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA4368M		
Make & Model:	HYUNDAI AE IONIQ HEV DCT, 1.6 (A)	Engine No:	G4LEJU188234
Reg. Date:	27/02/2019 (Man. Year: 2018)	Chassis No:	KMHC851CVKU140644
Colour:	Blue	Odometer:	234850 km
Engine Capacity:	1580 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Bridgestone 5 mm	Rear Left Side:	Bridgestone 5 mm
Front Right Side:	Bridgestone 5 mm	Rear Right Side:	Bridgestone 5 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	377.12	377.12	0.00	0.00
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,010.00	780.00	230.00	22.77
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	1,387.12	1,157.12	230.00	16.58
+ GST 7.00/7.00% (S\$)	97.10	81.00	16.10	16.58

Nett Amount (S\$)	1,484.22	1,238.12	246.10	16.58
<hr/>				
+ Loss of Use (2.0 x S\$50.00/day) (S\$)		100.00		
+ Car Rental (2.0 x S\$125.19/day) (S\$)		250.38		
+ Doc/Search Fee (S\$)		2.00		
<hr/>				
Nett Liability (S\$)		1,590.50		
<hr/>				
Global Sum Settlement (S\$)		1,590.00		
<hr/>				

INSPECTION

Date of Assignment: 26/10/2020

Date Inspected: 26/10/2020

Estimated Period of Repair: 2.0 days

Inspected At:

ComfortDelGro Engineering Pte Ltd (Loyang)
59 Loyang Drive
Singapore 508969

Adjuster: CHEN TSUE YEE**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*IONIQV4 CAP ASSY -WHEEL HU	Broken	346.40 FL	*346.40 FL
2	1		*REAR FENDER ADVERTISEMENT LOGO RH	Necessary	100.00 FS	*100.00 FS
F=Franchise part. S=SpcNett. L=ListItemDisc.						
Sub Total (S\$)					446.40	446.40
- List Item Discount on L Items 20.00/20.00% (S\$)					69.28	69.28
Total Parts (S\$)					377.12	377.12

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING (REAR BUMPER & FENDER R)	New	480.00	320.00
2	SPRAYPAINT ON AFFECTED AREA	New	450.00	400.00
3	ADJUST REAR WHEEL ALIGNMENT	New	80.00	60.00
Gross Labour Cost (\$\$)			1,010.00	780.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >