



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SFB 325G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT BUMPER	DEFORMED	1,259.93	1,259.93
1	FRONT BUMPER LOWER GRILLE	CRACKED	393.23	393.23
2	FRONT BUMPER SIDE RETAINER	NECESSARY	160.50	160.50
1	FRONT BUMPER REINFORCEMENT	BENT	609.90	609.90
1	FRONT BUMPER UNDERCOVER	TORN	256.60	256.60
2	FOGLAMP COWLING	CRACKED	173.34	173.34
2	FOGLAMP COVER	N/S CUT	706.20	353.10
2	FOGLAMP	NOT NECESSARY	465.45	-
1	FRONT GRILLE	CRACKED	365.94	365.94
1	FRONT LOGO	NECESSARY	208.65	208.65
2	HEADLAMP PANEL	CRACKED	642.00	642.00
2	HEADLAMP	CRACKED	1,588.95	1,588.95
1	FRONT FENDER (LH)	BUCKLED	569.78	569.78
1	AIR CON CONDENSER	BENT	802.50	802.50
1	INTERCOOLER	DENTED	834.15	834.15
1	HORN	NOT NECESSARY	85.60	-
2	RADIATOR COWLING	NOT NECESSARY	108.20	-
1	RADIATOR	BENT	513.60	513.60
	LESS 10% DISCOUNT		-974.45	-873.22
			8,770.07	7,858.95
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	BENT	30.00	30.00
1	FRONT NUMBER PLATE CASING (SN)	CRACKED	30.00	30.00
1	RADIATOR COOLANT (SN)	NECESSARY	80.00	40.00
			140.00	100.00
<u>LABOUR</u>				
	TO CHECK FRONT ELECTRICAL WIRING SYSTEM AND FOCUS HEADLAMP.		120.00	30.00
	TO REMOVE & REINSTALL A/C CONDENSER,RADIATOR & INTERCOOLER AND REFILL A/C GAS.		250.00	180.00
	LABOUR TO REMOVE,CUT,CHANGE & PANEL BEATING.		1,500.00	800.00

Report Ref No. CS/FCI20011646/Asf3e2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO PUTTY AND RESPRAY AFFECTED AREAS.		1,200.00	700.00
			3,070.00	1,710.00
GRAND TOTAL			11,980.07	9,668.95
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,700.00

Report Ref No. CS/FCI20011646/Asf3e2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.